TECHNICAL MEMORANDUM



TO:

Michael Kuntz, Washington State Department of Ecology

FROM:

Piper Roelen, P.E., and Martin Valeri

DATE:

July 15, 2013

RE:

MONTHLY REMEDIATION PROGRESS REPORT – JUNE 2013 FORMER HEAVENS SUPPLY COMPANY SITE (VCP #NW1698)

TORMER HEAVENS SUPPLY COMPANY SITE (VCP #N W 109)

7009 GREENWOOD AVENUE NORTH

SEATTLE, WASHINGTON

Per the reporting and data submission requirements outlined in the Final Cleanup Action Plan (Landau Associates 2012) as approved by the Washington State Department of Ecology (Ecology; 2012), this technical memorandum summarizes the status and progress of the electrical resistance heating (ERH) and soil vapor extraction (SVE) remedial action at the Former Heavens Supply Company site (Site) located at 7009 Greenwood Avenue North in Seattle, Washington (Figure 1). A Site map is provided as Figure 2. This progress report covers the June 2013 reporting period.

SUMMARY OF WORK COMPLETED DURING REPORTING PERIOD (JUNE 2013)

- The ERH/SVE system operated nearly continuously from June 1 through June 26, 2013. The system was shut down briefly on June 18 to allow for changeout of the vapor-phase granular-activated carbon (VGAC) and liquid-phase GAC (LGAC). The system was shut down again on June 26 in preparation for interim cleanup drilling and soil sampling (results to be reported in July status report).
- While in operation, TRS collected daily system operation data (e.g., energy application, subsurface temperatures, and vapor system flow rates) and optimized system performance during active operations.
- Landau Associates collected vapor samples and monitored contaminant concentrations in vapor with a photoionization detector (PID) from various sampling points in the vapor recovery (VR) lines and from the influent, mid-point, and effluent of the vapor-phase granular-activated carbon (VGAC) system in conformance with the requirements of the Puget Sound Clean Air Agency (PSCAA) air permit.
- Landau Associates conducted weekly performance monitoring of indoor air and soil vapor, with samples collected as follows:
 - Indoor air samples from the neighboring residences during the weeks of June 3, June 10, June 17, and June 24.
 - Soil vapor samples from perimeter soil vapor monitoring wells (wells VMW-1 through VMW-4, SMW-2 through SMW-4, and VP-1) during the weeks of June 3, June 10, and June 24. Sampling was not performed on June 18 due to conflict with TRS' VGAC changeout activities.

- Landau Associates also collected weekly vacuum measurements from each of the vapor monitoring points to monitor the vacuum influence of the SVE and VR systems.
- Landau Associates also conducted quarterly performance monitoring for groundwater, with samples collected as follows:
 - Groundwater samples from deep monitoring wells (diffusion bags placed June 5 and collected June 18; wells MW-2 through MW-5).
 - No groundwater samples were collected from shallow (perched groundwater) monitoring wells SMW-2 through SMW-4 as these wells were all dry.

SUMMARY OF REMEDIATION PROGRESS AND PERFORMANCE MONITORING DATA (JUNE 2013)

- As of July 1, 1,642,045 kilowatt-hours (kWh) of energy (approximately 54 percent of the design total energy delivery) has been applied to the subsurface by the ERH system, resulting in an average 79.9 degree Celsius (°C) rise in subsurface temperature from the start of power application through July 1. Temperatures increased from an average of 90.4°C on May 27 to an average of 96.3°C on July 1. Greater detail on energy delivery, subsurface temperature profiles, and vapor system flow rate data for the reporting period are included in TRS's Electrical Resistance Heating Weekly Status Reports for this reporting period (Attachment 1).
- Monitoring results for indoor air sampling indicate that concentrations of the Site contaminants of concern [specifically tetrachloroethene (PCE), trichloroethene (TCE), and vinyl chloride (VC)] in the indoor air spaces of neighboring residences were below the Site-specific cleanup levels during this reporting period. Table 1 summarizes cumulative laboratory analytical results for indoor air. Laboratory analytical reports for indoor air sampling are provided in Attachment 2.
- Monitoring results for soil vapor sampling, from vapor monitoring wells around the perimeter of the Site, indicate that concentrations of volatile organic compounds (VOCs) PCE and TCE varied. Table 2 summarizes cumulative laboratory analytical results for soil vapor. Figures 3a and 3b present soil vapor VOC concentrations over time at each monitoring location. Laboratory analytical reports for soil vapor sampling are provided in Attachment 3. Results for samples from most of the vapor monitoring wells appear to be relatively stable or consistent; however, concentrations in samples collected from SMW-2 appear to be generally increasing. This increase may be related to the operation of the new vapor recovery points operating to the west of the well (i.e., vapor being pulled from the active heating area toward SMW-2. Results from VMW-3 and VMW-4 have been somewhat sporadic but may be exhibiting an overall increase. These wells are located adjacent to known areas of soil contamination in the public rights-of-way that are not within the zone of influence of either the active heating area or vapor recovery system. These increased concentrations may be related to seasonal fluctuations and increases in ambient air temperatures¹ in these contaminated areas (Figure 3c illustrates this apparent correlation).
- Monitoring of vapors from various sampling points in the ERH/SVE system VR lines (including influent concentrations to the VGAC system) through PID measurements and laboratory analysis indicates that VOC concentrations peaked slightly in early April and have steadily declined since that time, even though active heating has continued to increase soil temperatures across the Site. Tables 4 and 5 summarize cumulative laboratory analytical results for vapor samples from the northern SVE trench, and the VGAC influent, mid-point, and effluent, respectively. Laboratory analytical reports for system vapor sampling are

-

Ambient air temperatures used for comparison from local Phinney Ridge weather station: http://www.wunderground.com/ weatherstation/WXDailyHistory.asp?ID=KWASEATT206&day=31&year=2012&month=1&graphspan=week.

- provided in Attachment 3. Figure 4 presents PID measurements over time at various points in the ERH/SVE system VR system.
- Groundwater sampling from deep groundwater monitoring wells (MW-2 through MW-5) indicate that PCE, TCE, VC, and cis-1,2-dichloroethene (cis-1,2-DCE) were not detected at concentrations greater than the laboratory reporting limits in groundwater samples collected from the deep aquifer. Shallow monitoring wells were all dry during the sampling event. Table 3 summarizes cumulative laboratory analytical results for groundwater. Laboratory analytical reports for groundwater sampling are provided in Attachment 4.
- Approximately 103,436 gallons of condensate was generated and treated through the LGAC system during the reporting period. All of the treated condensate plus 12 gallons of blowdown, for a total of approximately 103,448 gallons, were discharged to the sanitary sewer. Influent and effluent (sewer discharge) samples were not collected during this reporting period (not required by discharge authorization). Analytical results for previous condensate samples indicate that VOC concentrations in water being discharged to the sewer are below King County discharge limits.
- Approximately 45,150 gallons of potable water (from the municipal water supply) was used for drip feed into the electrode borings to maintain adequate soil moisture for electrode conductance.

PROBLEMS ENCOUNTERED, RESOLUTION, DEVIATIONS FROM WORK PLAN, AND EXPLANATION FOR DEVIATIONS DURING REPORTING PERIOD (JUNE 2013)

The following summarizes deviations during the reporting period from the performance monitoring schedule outlined in the Cleanup Action Plan (Landau Associates 2012):

- Indoor air samples were not collected at the following locations and dates:
 - Privacy FOIA (b) (6) residence the week of June 10 and June 17; the residents' schedule could not accommodate sampling on these dates.
 - Privacy FOIA (b) (6) residence in the basement the week of June 10 and the "Tower" sampling location on the week of June 24; the residents' schedule could not accommodate sampling on these dates.
 - residence the week of June 24; the residents' schedule could not accommodate sampling on this date.
- Soil vapor samples were not collected on the week of June 17 because the schedule conflicted with TRS's GAC changeout activities occurring that week.

These deviations from the planned sampling schedule did not result in any significant impact to the results of the overall performance monitoring program for the Site. No other issues or problems were encountered during this reporting period.

SUMMARY OF CLEANUP PROGRESS

The following summarizes progress of the overall Site cleanup through the end of this reporting period:

- Energy delivered to the subsurface by the ERH system resulted in rising subsurface soil temperatures (after the temporary shutdown), and an average temperature of approximately 96°C was reached by July 1.
- Vapor samples and PID measurements taken from various points in the ERH/SVE system VR piping indicate that VOC concentrations peaked in mid-April and have steadily declined since that time, even though active heating has continued to increase soil temperatures across the Site. This continued decrease in extracted vapor VOC concentrations suggests that even though volatilization should continue to increase with increased temperature, sorbed and liquid-phase VOC mass in the subsurface has been significantly depleted resulting in an overall decrease in mass removal rates. Based on VR flow rates and laboratory data through June, an estimated 908 pounds of total VOCs (primarily PCE) were removed from the subsurface through the ERH and SVE system since system startup.
- Although there has been a fair amount of variability, soil vapor sampling data from perimeter
 vapor monitoring wells have shown that VOC concentrations have generally declined or
 remained similar to baseline concentrations around the Site since system operations began.
 More recently, soil vapor PCE concentrations in perimeter soil vapor monitoring wells have
 been mostly stable, except for apparent increases observed in SMW-2, VMW-3, and
 VMW-4. These trends appear to be related to modifications to the site vapor recovery system
 and seasonal variations in temperatures.
- Indoor air sampling data indicate that VOC concentrations were well below Site cleanup levels in all the neighboring residences during the reporting period.
- Groundwater sampling data continue to indicate VOCs are not present in the deep aquifer beneath the Site.

REFERENCES

Ecology. 2012. Letter: *Voluntary Cleanup Site No. NW1698 – 7009 Greenwood Avenue/Approval of Cleanup Action Plan (CAP of November 7, 2012)*. From Michael Kuntz, Site Manager, Washington State Department of Ecology, to Sue Wollenberg, Former Heavens Supply Company Property Owner. November 16.

Landau Associates. 2012. Final Cleanup Action Plan (Revision 1), Former Heavens Supply Company Property, 7009 Greenwood Avenue North, Seattle, Washington. November 7.

ATTACHMENTS

Figure 1: Vicinity Map Figure 2: Site Map

Figure 3: Soil Vapor VOC Concentrations / Correlation of PCE Concentrations in Soil Vapor

(VMW-3/VMW-4) with Ambient Temperature

Figure 4: PID Measurements in ERH/SVE System

Table 1: Indoor Air Analytical Results
 Table 2: Soil Vapor Analytical Results
 Table 3: Groundwater Analytical Results
 Table 4: SVE Vapor Analytical Results

Table 5: Influent, Mid-Point, and Effluent Vapor Analytical Results


Attachment 1: TRS Electrical Resistance Heating Weekly Status Reports for May 7 to July 1, 2013


(on DVD)


Attachment 2: Laboratory Analytical Reports – Indoor Air (on DVD)


Attachment 3: Laboratory Analytical Reports – Vapor (Soil and ERH/SVE System) (on DVD)


Attachment 4: Laboratory Analytical Reports – Groundwater (on DVD)















07/15/13 P:\583\002.050\FileRm\R\Remediation Progress Reports\June 2013\06-13 Remediation Status_fig3b.docx










Heavens Supply Company Seattle, Washington PID Measurements in ERH/SVE System

Figure 4a









Heavens Supply Company Seattle, Washington PID Measurements in ERH/SVE System

Figure 4b

TABLE 1 INDOOR AIR ANALYTICAL RESULTS FORMER HEAVENS SUPPLY COMPANY SITE SEATTLE, WASHINGTON

	Privacy -Basement (µg/m³)					Privacy -Base	ement (µg/m³)		Privacy -Basement (µg/m³)				
Sample Date	Vinyl Chloride ci	is-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE	
Sample Date 3/5-3/6/2013 (baseline) 3/19/2013 3/27-3/28/2013 4/3/2013 4/09-4/11/13 4/17/2013 5/1/2013 5/15/2013 5/22/2013 6/5/2013 6/12/2013 6/19/2013 6/19/2013 6/26/2013	Vinyl Chloride ci			0.23 U 0.49 0.26 0.33 7.8 1.2 0.74 2.8 0.21 U 0.23 U 0.20 NS 0.24 U NS 0.22 U	Vinyl Chloride 0 037 U NS 0 038 U NS 0 046 U 0 041 U 0 041 U 0 037 U 0 039 U 0 046 U 0 050 U 0 042 UJ 0 043 U 0 033 U			0.74 NS 0.45 NS 16 2.2 0.38 0.92 0.32 0.27 0.24 U 0.26 U 0.22 UJ 0.23 U 0.17 U	0.041 U 0.035 U 0.042 U 0.032 U 0.040 U 0.036 U 0.035 U 0.049 U 0.049 U 0.044 U 0.044 U 0.044 U NS			0.22 U 0.57 0.89 0.91 11 8.0 0.34 0.21 U 2.3 0.30 0.22 0.23 U 0.24 U 0.23 U NS	

TABLE 1 INDOOR AIR ANALYTICAL RESULTS FORMER HEAVENS SUPPLY COMPANY SITE **SEATTLE, WASHINGTON**

		Privacv	Basement (µg/m³)			Privacv	-Tower (μg/m³)			Church-Basen	nent (µg/m³)			Heaven Supply-C	Outside (µg/m³)	
Sample Date	Vinyl Chloride	cis-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE
Sample Date 3/5-3/6/2013 (baseline); 3/19/2013 3/27-3/28/2013 4/09-4/11/13 4/17/2013 5/1/2013 5/8/2013 5/15/2013 5/29/2013 6/5/2013 6/12/2013 6/19/2013 6/26/2013	0.040 U 0.035 U 0.034 U 0.033 U 0.033 U 0.036 U 0.043 U 0.056 U 0.041 U 0.039 U 0.040 U 0.043 NS 0.041 U 0.044 U 0.044 U 0.045 U 0.046 U 0.047 U 0.048 U 0.049	0.12 U 0.11 U 0.11 U 0.10 U 0.11 U 0.13 U 0.17 U 0.13 U 0.12 U 0.12 U 0.12 U 0.14 U 0.14 U 0.15 U 0.19 U 0.	0.025 0.039 0.026 0.021 0.15 0.031 0.030 0.035 U 0.040 0.033 0.095 0.039 0.029 NS 0.055 0.054	0.21 U 0.38 0.19 0.34 5.7 1.9 0.23 0.30 U 0.30 0.21 U 0.18 U 0.20 U NS 0.26 0.25	0 042 U	Cis-1,2-DCE 0.13 U NS NS 0.14 U NS NS 0.11 U NS NS NS 0.13 U NS	0.026 U NS NS 0.028 U NS NS 0.023 U NS	0 22 U NS	0.041 U	0.13 U NS	0.028 NS NS	0.22 U NS	0.037 U 0.036 U NS NS NS 0.046 U NS NS NS 0.044 U NS	0.12 U 0.11 U NS NS NS 0.14 U NS NS 0.14 U NS	0.079 0.38 NS NS NS 0.029 U NS NS 0.028 U NS	0.23 0.79 NS NS NS 0.23 U NS NS 0.22 U NS NS

NS = Not analyzed.

U = Indicates the compound was not detected at the reported concentration.

J = Indicates the analyte was positively identified; the associated numerical value is the approximate concentration of the analyte in the sample.

UJ = The analyte was not detected in the sample; the reported sample reporting limit is an estimate.

Bold = Detected compound.

Box = Exceedance of cleanup level.

cis-1,2-DCE = cis-1,2-Dichloroethene

TCE = Trichloroethene

PCE = Tetrachloroethane

μg/m³ = micrograms per cubic meter

TABLE 2 SOIL VAPOR ANALYTICAL RESULTS FORMER HEAVENS SUPPLY COMPANY SITE SEATTLE, WASHINGTON

	SMW-2 (μg/m³)				SMW-3 (µg/m³)				SMW-4 (μg/m³)				VMW-1 (μg/m³)			
Sample Date	Vinyl Chloride	cis-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE
2/28/2013 3/6/2013 3/14/2013 3/19/2013 4/2/2013 4/3/2013 4/3/2013 4/30/2013 5/3/2013 5/3/2013 5/3/2013 5/21/2013 5/28/2013 6/4/2013 6/4/2013	3.1 U N/A 5.7 3.1 U N/A 3.1 U 3.1 U 3.1 U 3.1 U 3.1 U 0.511 U 0.511 U 0.511 U 0.511 U 0.511 U	6 8 U N/A 6 8 U 6 8 U 0.793 U 0.793 U 0.793 U 0.793 U 0.793 U	21 N/A 63 140 N/A 200 290 N/A 5.4 U 5.4 U 43 5.4 U 35 1.07 U 1.07 U 2.15 1.07 U 1.07 U	260 N/A 300 330 N/A 400 550 N/A 320 82 180 240 2.3 U 44 155 371 437 814 764 1,150	3.1 U N/A 3.1 U 3.1 U 3.1 U 3.1 U 3.1 U 3.1 U 3.1 U 0.511 U 0.511 U 0.511 U 0.511 U 0.511 U	6.8 U N/A 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 0.793 U 0.793 U 0.793 U 0.793 U 0.793 U	41 N/A 57 67 N/A 210 290 N/A 5.4 U 5.4 U 5.4 U 5.4 U 3.2 1.07 U 1.07 U 1.07 U 1.07 U 1.07 U	1,800 N/A 1,600 1,400 N/A 1,800 2,100 N/A 1,000 1,200 1,000 530 2,800 981 1,240 994 1,430 1,040 1,150	3.1 U N/A 3.1 U 3.1 U N/A 3.1 U N/A 3.1 U 3.1 U 3.1 U 3.1 U 3.1 U 0.511 U 0.511 U 0.511 U 0.511 U 0.511 U	6.8 U N/A 6.8 U N/A 6.8 U N/A 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 0.793 U 0.793 U 0.793 U 0.793 U 0.793 U 0.793 U	18 N/A 56 52 N/A 230 310 N/A 5.4 U 5.4 U 5.4 U 5.4 U 1.07 U	460 N/A 520 400 N/A 490 690 N/A 260 240 360 380 97 7770 346 338 234 488 289 346	3.1 U N/A 3.1 U 3.1 U N/A 3.1 U 3.1 U N/A 3.1 U 3.1 U 3.1 U 3.1 U 0.511 U 0.511 U 0.511 U 0.511 U 0.511 U	6.8 U N/A 6.8 U N/A 6.8 U N/A 6.8 U N/A 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 0.793 U 0.793 U 0.793 U 0.793 U 0.793 U	19 N/A 85 55 N/A 290 350 N/A 5.4 U 5.4 U 36 5.4 U 98 1.07 U 1.50 1.07 U 1.07 U 1.07 U	4,100 N/A 1,600 360 N/A 520 340 N/A 190 51 15 33 2.3 U 160 2.03 U 35.5 179 256 64.0 96.6

TABLE 2 SOIL VAPOR ANALYTICAL RESULTS FORMER HEAVENS SUPPLY COMPANY SITE **SEATTLE, WASHINGTON**

		VMW-2 (µ	ıg/m³)			VMW-3 (ug/m³)		VMW-4 (μg/m³)				VP-1 (μg/m³)			
Sample Date	e Vinyl Chloride	cis-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE	Vinyl Chloride	cis-1,2-DCE	TCE	PCE
2/28/2013 3/6/2013 3/14/2013 3/19/2013 3/27/2013 4/2/2013 4/3/2013 4/16/2013 4/30/2013 5/3/2013 5/3/2013 5/21/2013 5/28/2013 6/4/2013 6/4/2013	3.1 U N/A 3.1 U 3.1 U N/A 3.1 U 3.1 U 3.1 U 3.1 U 3.1 U 0.511 U 0.511 U 0.511 U 0.511 U	N/A N/A N/A 6 8 U 6 8 U N/A 6 8 U 6 8 U 6 8 U 6 8 U 0.793 U 0.793 U 0.793 U 0.793 U 0.793 U	N/A N/A N/A (63 N/A 200 250 N/A 5.4 U 5.4 U N/A 240 5.4 U 29 1.07 U 1.07 U 1.07 U 1.07 U 1.07 U	N/A N/A N/A 110 N/A 270 360 N/A 440 23 N/A 76 2.3 U 22.0 2.71 10.3 2.03 U 2.03 U 2.03 U	3.1 U N/A 7.8 4.6 N/A 3.1 U 3.1 U 3.1 U 3.1 U 0.511 U 0.511 U 0.511 U 0.511 U	6.8 U N/A 6.8 U N/A 6.8 U N/A 6.8 U 41 44 6.8 U 6.8 U 24 3.17 16.8 13.5 14.3 17.8 16.5	75 N/A 91 130 N/A 240 360 N/A 20 77 5.4 U 180 5.4 U 220 13.8 92.4 87.7 95.2 95.9 115	1,500 N/A 1,300 1,400 1,400 1,700 N/A 1,800 1,800 1,800 2,500 219 1,570 1,580 2,200 1,560 2,080	3.1 U N/A 3.1 U 3.1 U 3.1 U 3.1 U 3.1 U 3.1 U 3.1 U 3.1 U 0.511 U 0.511 U 0.511 U 0.511 U	6.8 U N/A 6.8 U N/A 6.8 U N/A 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 0.793 U 0.793 U 0.793 U 0.793 U 0.793 U	18 N/A 53 75 N/A 200 250 N/A 5.4 U 5.4 U 5.4 U 86 23.2 25.6 28.2 31.8 34.4 44.7	1,400 N/A 1,800 640 N/A 1,500 1,400 N/A 3,00 1,700 2,100 1,900 660 3,300 1,690 2,110 2,210 3,420 2,590 2,990	N/A 3.1 U N/A 3.1 U 0.511 U 0.511 U 0.511 U 0.511 U 0.511 U 0.511 U	N/A 6.8 U N/A 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 6.8 U 0.793 U 0.793 U 0.793 U 0.793 U 0.793 U	N/A 260 N/A N/A 62 200 N/A 320 5.4 U 5.4 U 22 N/A 20 1.07 U 1.07 U 1.07 U 1.07 U 1.07 U 1.07 U	N/A 1,400 N/A 120 260 N/A 350 180 18 19 350 N/A 210 2.03 U 9.77 4.34 4.34 N/A 2.03 U

U = Indicates the compound was not detected at the reported concentration.

J = Indicates the analyte was positively identified; the associated numerical value is the approximate concentration of the analyte in the sample.

UJ = The analyte was not detected in the sample; the reported sample reporting limit is an estimate.

Bold = Detected compound.

Box = Exceedance of cleanup level.
cis-1,2-DCE = cis-1,2-Dichloroethene
TCE = Trichloroethene
PCE = Tetrachloroethane

 $[\]mu$ g/m³ = micrograms per cubic meter

TABLE 3
GROUNDWATER ANALYTICAL RESULTS
FORMER HEAVENS SUPPLY COMPANY SITE
SEATTLE, WASHINGTON

		Shallow Wells				Deep	Wells		
	SMW-2 EV13030039-01 03/06/2013	SMW-3 EV13030039-02 03/06/2013	SMW-4 EV13030039-03 03/06/2013	MW-2 EV13030127-04 03/21/2013	Dup of MW-2 DUP EV13030127-02 03/21/2013	MW-2 EV13060095-01 06/18/2013	MW-3 EV13030127-05 03/21/2013	MW-3 EV13060095-02 06/18/2013	MW-4 EV13030127-03 03/21/2013
VOLATILES (μg/L) Method EPA 8260B									_
Dichlorodifluoromethane	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Chloromethane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Vinyl Chloride	0.20 U	0.20 U	0.20 U	0.20 U	0.20 U	0.20 U	0.20 U	0.20 U	0.20 U
Bromomethane	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
Chloroethane	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
Carbon Tetrachloride	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
Trichlorofluoromethane	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Carbon Disulfide	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Acetone	25 U		25 U	25 U	25 U	25 U	25 U	25 U	25 U
1,1-Dichloroethene	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Methylene Chloride	5.0 U		5.0 U	5.0 U	5.0 U	5.0 U	5 0 U	5.0 U	5.0 U
Acrylonitrile	10 U		10 U	10 U	10 U	10 U	10 U	10 U	10 U
Methyl t-butyl ether	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Trans-1,2-Dichloroethene	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
1,1-Dichloroethane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
2-Butanone	10 U		10 U	10 U	10 U	10 U	10 U	10 U	10 U
Cis-1,2-Dichloroethene	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
2,2-Dichloropropane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Bromochloromethane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Chloroform	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
1,1,1-Trichloroethane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
1,1-Dichloropropene	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
1,2-Dichloroethane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Benzene	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Trichloroethene	2.0 U		2.0 U	2.0 U 2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
1,2-Dichloropropane Dibromomethane	2.0 U 2.0 U		2.0 U 2.0 U	2.0 U	2.0 U 2.0 U	2.0 U 2.0 U	2 0 U 2 0 U	2.0 U 2.0 U	2.0 U 2.0 U
Bromodichloromethane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U		2.0 U	
Trans-1,3-Dichloropropene	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
4-Me hyl-2-Pentanone	10 U		2.0 U	2.0 U	2.0 U	2.0 U	10 U	2.0 U	2.0 U
Toluene	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Cis-1,3-Dichloropropene	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
1,1,2-Trichloroethane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
2-Hexanone	10 U		10 U	10 U	10 U	10 U	10 U	10 U	10 U
1,3-Dichloropropane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Tetrachloroethylene	4.4	9.8	4.2	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Dibromochloromethane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
1.2-Dibromoethane	0.010 U		0.010 U	0.010 U	0.010 U	0.010 U	0.010 U	0.010 U	0.010 U
Chlorobenzene	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
1,1,1,2-Tetrachloroethane	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Ethylbenzene	2.0 U		2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
m,p-Xylene	4.0 U	4.0 U	4.0 U	4.0 U	4.0 U	4.0 U	4 0 U	4.0 U	4.0 U

TABLE 3
GROUNDWATER ANALYTICAL RESULTS
FORMER HEAVENS SUPPLY COMPANY SITE
SEATTLE, WASHINGTON

		Shallow Wells				Deep	o Wells		
	SMW-2 EV13030039-01 03/06/2013	SMW-3 EV13030039-02 03/06/2013	SMW-4 EV13030039-03 03/06/2013	MW-2 EV13030127-04 03/21/2013	Dup of MW-2 DUP EV13030127-02 03/21/2013	MW-2 EV13060095-01 06/18/2013	MW-3 EV13030127-05 03/21/2013	MW-3 EV13060095-02 06/18/2013	MW-4 EV13030127-03 03/21/2013
Styrene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
o-Xylene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
Bromoform	2.0 U		2.0 U	2.0 U		2.0 U		2.0 U	2.0 U
Isopropylbenzene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
1,1,2,2-Tetrachloroethane	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
1,2,3-Trichloropropane	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
Bromobenzene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
n-Propylbenzene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
2-Chlorotoluene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
1,3,5-Trimethylbenzene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
4-Chlorotoluene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
tert-Butylbenzene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
1,2,4-Trimethylbenzene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U
s-Butylbenzene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	20 U	2.0 U	2.0 U
p-lsopropyltoluene	2.0 U			2.0 U		2.0 U		2.0 U	2.0 U
1,3-Dichlorobenzene	2.0 U			2.0 U		2.0 U	2 0 U	2.0 U	2.0 U
1,4-Dichlorobenzene	2.0 U		2.0 U	2.0 U		2.0 U	2 0 U	2.0 U	2.0 U
n-Butylbenzene	2.0 U		2.0 U	2.0 U		2.0 U	2 0 U	2.0 U	2.0 U
1,2-Dichlorobenzene	2.0 U		2.0 U	2.0 U		2.0 U	2 0 U	2.0 U	2.0 U
1,2-Dibromo-3-Chloropropane	10 U		10 U	10 U		10 U	10 U	10 U	10 U
1,2,4-Trichlorobenzene	2.0 U		2.0 U	2.0 U		2.0 U	2 0 U	2.0 U	2.0 U
Hexachlorobutadiene	2.0 U		2.0 U	2.0 U		2.0 U	2 0 U	2.0 U	2.0 U
Naphthalene	2.0 U		2.0 U	2.0 U		2.0 U	20 U	2.0 U	2.0 U
1,2,3-Trichlorobenzene	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2.0 U	2 0 U	2.0 U	2.0 U

TABLE 3
GROUNDWATER ANALYTICAL RESULTS
FORMER HEAVENS SUPPLY COMPANY SITE
SEATTLE, WASHINGTON

		Deep Wells	
	MW-4 EV13060095-03 06/18/2013	MW-5 EV13030127-01 03/21/2013	MW-5 EV13060095-04 06/18/2013
VOLATILES (μg/L)			
Method EPA 8260B			
Dichlorodifluoromethane	2.0 U	2.0 U	2.0 U
Chloromethane	2.0 U	2.0 U	2.0 U
Vinyl Chloride	0.20 U	0.20 U	0.20 U
Bromomethane	2.0 U	2.0 U	2.0 U
Chloroethane	2.0 U	2.0 U	2.0 U
Carbon Tetrachloride	2.0 U	2.0 U	2.0 U
Trichlorofluoromethane	2.0 U	2.0 U	2.0 U
Carbon Disulfide	2.0 U	2.0 U	2.0 U
Acetone	25 U	25 U	25 U
1,1-Dichloroethene	2.0 U	2.0 U	2.0 U
Methylene Chloride	5.0 U	5.0 U	5.0 U
Acrylonitrile	10 U	10 U	10 U
Methyl t-butyl ether	2.0 U	2.0 U	2.0 U
Trans-1,2-Dichloroethene	2.0 U	2.0 U 2.0 U	2.0 U 2.0 U
1,1-Dichloroethane 2-Butanone	2.0 U 10 U	2.0 U	2.0 U
Cis-1.2-Dichloroethene	2.0 U	2.0 U	2.0 U
2,2-Dichloropropane	2.0 U	2.0 U	2.0 U
Bromochloromethane	2.0 U	2.0 U	2.0 U
Chloroform	2.0 U	2.0 U	2.0 U
1.1.1-Trichloroethane	2.0 U	2.0 U	2.0 U
1,1-Dichloropropene	2.0 U	2.0 U	2.0 U
1.2-Dichloroethane	2.0 U	2.0 U	2.0 U
Benzene	2.0 U	2.0 U	2.0 U
Trichloroethene	2.0 U	2.0 U	2.0 U
1,2-Dichloropropane	2.0 U	2.0 U	2.0 U
Dibromomethane	2.0 U	2.0 U	2.0 U
Bromodichloromethane	2.0 U	2.0 U	2.0 U
Trans-1,3-Dichloropropene	2.0 U	2.0 U	2.0 U
4-Me hyl-2-Pentanone	10 U	10 U	10 U
Toluene	2.0 U	2.0 U	2.0 U
Cis-1,3-Dichloropropene	2.0 U	2.0 U	2.0 U
1,1,2-Trichloroethane	2.0 U	2.0 U	2.0 U
2-Hexanone	10 U	10 U	10 U
1,3-Dichloropropane	2.0 U	2.0 U	2.0 U
Tetrachloroethylene	2.0 U	2.0 U	2.0 U
Dibromochloromethane	2.0 U	2.0 U	2.0 U
1,2-Dibromoethane	0.010 U	0.010 U	0.010 U
Chlorobenzene	2.0 U	2.0 U	2.0 U
1,1,1,2-Tetrachloroethane	2.0 U	2.0 U	2.0 U
Ethylbenzene	2.0 U	2.0 U	2.0 U
m,p-Xylene	4.0 U	4.0 U	4.0 U

TABLE 3
GROUNDWATER ANALYTICAL RESULTS
FORMER HEAVENS SUPPLY COMPANY SITE
SEATTLE, WASHINGTON

		Deep Wells	
	MW-4 EV13060095-03 06/18/2013	MW-5 EV13030127-01 03/21/2013	MW-5 EV13060095-04 06/18/2013
Styrene	2.0 U	2.0 U	2.0 U
o-Xylene	2.0 U	2.0 U	2.0 U
Bromoform	2.0 U	2.0 U	2.0 U
Isopropylbenzene	2.0 U	2.0 U	2.0 U
1,1,2,2-Tetrachloroethane	2.0 U	2.0 U	2.0 U
1,2,3-Trichloropropane	2.0 U	2.0 U	2.0 U
Bromobenzene	2.0 U	2.0 U	2.0 U
n-Propylbenzene	2.0 U	2.0 U	2.0 U
2-Chlorotoluene	2.0 U	2.0 U	2.0 U
1,3,5-Trimethylbenzene	2.0 U	2.0 U	2.0 U
4-Chlorotoluene	2.0 U	2.0 U	2.0 U
tert-Butylbenzene	2.0 U	2.0 U	2.0 U
1,2,4-Trimethylbenzene	2.0 U	2.0 U	2.0 U
s-Butylbenzene	2.0 U	2.0 U	2.0 U
p-Isopropyltoluene	2.0 U	2.0 U	2.0 U
1,3-Dichlorobenzene	2.0 U	2.0 U	2.0 U
1,4-Dichlorobenzene	2.0 U	2.0 U	2.0 U
n-Butylbenzene	2.0 U	2.0 U	2.0 U
1,2-Dichlorobenzene	2.0 U	2.0 U	2.0 U
1,2-Dibromo-3-Chloropropane	10 U	10 U	10 U
1,2,4-Trichlorobenzene	2.0 U	3.2	2.0 U
Hexachlorobutadiene	2.0 U	2.5	2.0 U
Naphthalene	2.0 U	4.0	2.0 U
1,2,3-Trichlorobenzene	2.0 U	4.1	2.0 U

 $\label{eq:U} \textbf{U} = \text{Indicates the compound was not detected at } \ \ \text{he reported concentration}.$ $\label{eq:Bold} \textbf{Bold} = \textbf{Detected compound}.$

TABLE 4 SVE VAPOR ANALYTICAL RESULTS FORMER HEAVENS SUPPLY COMPANY SITE SEATTLE, WASHINGTON

	SVE-North EV13030086-10 03/14/2013	SVE-North EV13030119-08 03/19/2013	SVE-North EV13030152-04 03/27/2013	SVE-Nor h EV13040012-01 04/02/2013	SVE-North EV13040048-04 04/09/2013
VOLATILES (µg/m³)					
Method EPA 8260B					
Dichlorodifluoromethane	9.4 U				
Chloromethane	210	23 U	23 U	23 U	23 U
Vinyl Chloride	5.4	3.1 U	3.1 U	3.1 U	3.1 U
Bromomethane	14 U				
Chloroethane	12 U				
Carbon Tetrachloride	2.5 U	2.5 U	2.5 U	25 U	2.5 U
Trichlorofluoromethane	4.5 U	4.5 U	4.5 U	4 5 U	4.5 U
1,1-Dichloroethene	1.4 U				
Methylene Chloride	68 U	68 U	250	68 U	68 U
Trans-1,2-Dichloroethene	9.7 U				
1,1-Dichloroethane	3.0 U	3.0 U	3.0 U	3 U	3 U
Cis-1,2-Dichloroethene	6.8 U	6.8 U	6.8 U	6 8 U	6.8 U
2,2-Dichloropropane	4.1 U				
Bromochloromethane	11 U				
Chloroform	120	130	140	14 U	14 U
1,1,1-Trichloroethane	19	5.9 U	5.9 U	5 9 U	5.9 U
1,1-Dichloropropene	6.7 U				
1,2-Dichloroethane	1.4 U				
Trichloroethene	21	68	200	260	5.4 U
1,2-Dichloropropane	6.3 U	6.3 U	6.3 U	6 3 U	6.3 U
Dibromomethane	7.1 U				
Bromodichloromethane	5.9 U	5.9 U	5.9 U	5 9 U	5.9 U
Trans-1,3-Dichloropropene	5.8 U	5.8 U	5.8 U	5 8 U	5.8 U
Cis-1,3-Dichloropropene	4.8 U	4.8 U	4.8 U	4 8 U	4.8 U
1,1,2-Trichloroethane	5.2 U	5.2 U	5.2 U	5 2 U	5.2 U
1,3-Dichloropropane	6.6 U				
Tetrachloroethylene	400	1,700	5,300	30,000	2,600
Dibromochloromethane	7.4 U				
1,2-Dibromoethane	1.0 U	1.0 U	1.0 U	1 U	1 U
Chlorobenzene	2.4 U				
1,1,1,2-Tetrachloroethane	8.7 U				
Bromoform	5.3 U	5.3 U	5.3 U	5 3 U	5.3 U
1,1,2,2-Tetrachloroethane	2.9 U	2.9 U	2.9 U	29 U	2.9 U
1,2,3-Trichloropropane	2.3 U	2.3 U	2.3 U	2 3 U	2.3 U
Bromobenzene	4.1 U	4.1 U	24	4.1 U	4.1 U
2-Chlorotoluene	13	19	3.2 U	3 2 U	7.3
4-Chlorotoluene	9.2	4.0 U	4.0 U	4 U	4 U
1,3-Dichlorobenzene	4.1 U	4.1 U	4.1 U	4.9	4.1 U
1,4-Dichlorobenzene	4.5 U	8.9	4.5 U	4 5 U	8.4
1,2-Dichlorobenzene	2.8 U	21	2.8 U	2 8 U	12
1,2-Dibromo-3-Chloropropane	12	10 U	10 U	10 U	10 U
1,2,4-Trichlorobenzene	4.7 U	4.7 U	4.7 U	26	4.7 U
Hexachlorobutadiene	6.9 U	6.9 U	6.9 U	6 9 U	6.9 U
1,2,3-Trichlorobenzene	4.5 U	6.3	4.5 U	4 5 U	4.5 U

TABLE 4 SVE VAPOR ANALYTICAL RESULTS FORMER HEAVENS SUPPLY COMPANY SITE SEATTLE, WASHINGTON

	North-SVE EV13050038-01 05/07/2013
VOLATILES (µg/m³) Method EPA 8260B Dichlorodifluoromethane Chloromethane Vinyl Chloride Bromomethane Chloroethane Carbon Tetrachloride Trichlorofluoromethane 1,1-Dichloroethane Methylene Chloride Trans-1,2-Dichloroethene 1,1-Dichloroethane Cis-1,2-Dichloroethene 2,2-Dichloropropane Bromochloromethane Chloroform 1,1,1-Trichloroethane 1,1-Dichloropropane Bromochloromethane Trichloroethane Trichloroethane Trichloroethane Trichloroethane Trichloropropane Bromodichloromethane Trans-1,3-Dichloropropene 1,2-Dichloropropane Cis-1,3-Dichloropropene 1,1,2-Trichloroethane 1,3-Dichloropropane Tetrachloroethylene Dibromochloromethane 1,2-Dibromoethane 1,2-Dibromoethane 1,2-Tetrachloroethane Bromoform 1,1,2-Tetrachloroethane Bromoform 1,1,2,2-Tetrachloroethane Bromoform 1,1,2,3-Trichloropropane Bromobenzene 2-Chlorotoluene 4-Chlorotoluene 1,3-Dichlorobenzene 1,4-Dichlorobenzene	EV13050038-01
1,2-Dibromo-3-Chloropropane 1,2,4-Trichlorobenzene Hexachlorobutadiene 1,2,3-Trichlorobenzene	10 U 4.7 U 6.9 U 4.5 U

 $\mbox{U} = \mbox{Indicates}$ the compound was not detected at he reported concentration. $\mbox{Bold} = \mbox{Detected compound}.$

TABLE 5 INFLUENT, MID-POINT, AND EFFLUENT VAPOR ANALYTICAL RESULTS FORMER HEAVENS SUPPLY COMPANY SITE SEATTLE, WASHINGTON

•					Influent Vapor							Mid-P	oint Vapor		
	ERH-INF EV13030027-03			ERH-INF EV13030152-01	ERH-INF EV13040012-02	ERH-INF EV13040048-01	ERH-INF EV13050022-08	ERH-INF EV13050038-03	ERH-INF 1306022-001A	ERH-MID1 EV13030027-02	ERH-MID2 EV13030086-09	ERH-MID2 EV13030119-10	ERH-MID2 EV13030152-02	ERH-MID2 EV13040012-03	ERH-MID2 EV13040048-02
	3/5/2013	3/14/2013	3/19/2013	3/27/2013	4/2/2013	4/9/2013	5/3/2013	05/07/2013	6/4/2013	03/05/2013	03/14/2013	03/19/2013	03/27/2013	04/02/2013	04/09/2013
VOLATILES (µg/m³) Method EPA 8260B/TO-15															
Dichlorodifluoromethane	9.4 U	9.4 U	9.4 U	9.4 U	9.4 U	9.4 U	9.4 U	9.4 U	1.48 U	9.4 U	9.4 U	9.4 U	9.4 U	9.4 U	9.4 U
Chloromethane	23 U	240	23 U	23 U	23 U	23 U	53	23 U	9.75	23 U	220	23 U		23 U	23 U
Vinyl Chloride	3.1 U	3.1 U	3.1 U	3.1 U	3.1 U	3.1 U	3.1 U	3.1 U	0 511 U	3.1 U	3.1 U				3.1 U
Bromomethane	14 U	14 U	14 U	14 U	14 U	14 U	14 U	14 U	NA NA	14 U	14 U				14 U
Chloroethane	12 U	12 U	12 U	12 U	12 U	12 U	12 U	12 U	3.48	12 U	12 U			12 U	12 U
Carbon Tetrachloride	2.5 U	2.5 U	2.5 U	2.5 U	2.5 U	2.5 U	2.5 U	2.5 U	1.26 U	2.5 U	2.5 U			2.5 U	2.5 U
Trichlorofluoromethane	4.5 U	4.5 U	21	4.5 U	1.69 U	4.5 U	4.5 U			4.5 U	4.5 U				
1.1-Dichloroethene	1.4 U	1.4 U	51	1.4 U	1.4 U	61	1.4 U	13	0.793 U	1.4 U	1.4 U				13
Methylene Chloride	68 U	68 U	68 U	68 U	68 U	68 U	68 U	68 U	NA	68 U	68 U		780	68 U	68 U
Trans-1,2-Dichloroethene	9.7 U	9.7 U	120	9.7 U	0.793 U	9.7 U	9.7 U			9.7 U	9.7 U				
1,1-Dichloroethane	3.0 U	3.0 U	3.0 U	3.0 U	3 U	3 U	3 U	3 U	0 810 U	3.0 U	3.0 U				3 U
Cis-1,2-Dichloroethene	6.8 U	80	81	69	6.8 U	190	65	70	40.0	6.8 U					
2,2-Dichloropropane	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	NA	10	4.1 U			4.1 U	4.1 U
Bromochloromethane	11 U	13	11 U	11 U	11 U	11 U	11 U	11 U	NA	11 U	11 U			_	11 U
Chloroform	110	130	150	160	14 U	14 U	14 U	14 U	0 977 U	100	120	170	120	14 U	14 U
1,1,1-Trichloroethane	5.9 U	5.9 U	5.9 U	5.9 U	5.9 U	5.9 U	5.9 U	5.9 U	1.09 U	26	5.9 U			5.9 U	5.9 U
1,1-Dichloropropene	6.7 U	6.7 U	6.7 U	6.7 U	6.7 U	6.7 U	6.7 U	6.7 U	NA	6.7 U	6.7 U				6.7 U
1,2-Dichloroethane	12	1.4 U	1.4 U	1.4 U	1.4 U	1.4 U	1.4 U	1.4 U	0 809 U	12	1.4 U			1.4 U	1.4 U
Trichloroethene	340	79	430	390	470	850	66	360	291	250	25	67	230	330	5.4 U
1,2-Dichloropropane	6.3 U	6.3 U	6.3 U	6.3 U	6.3 U	6.3 U	6.3 U	6.3 U	2.31 U	6.3 U	6.3 U			6.3 U	6.3 U
Dibromomethane	7.1 U	7.1 U	7.1 U	7.1 U	7.1 U	7.1 U	7.1 U	7.1 U	NA NA	7.1 U	7.1 U				7.1 U
Bromodichloromethane	5.9 U	5.9 U	5.9 U	5.9 U	5.9 U	5.9 U	5.9 U	5.9 U	2.01 U	5.9 U	5.9 U		5.9 U	5.9 U	5.9 U
Trans-1,3-Dichloropropene	5.8 U	5.8 U	5.8 U	5.8 U	5.8 U	5.8 U	5.8 U	5.8 U	2.27 U	5.8 U	5.8 U			5.8 U	5.8 U
Cis-1,3-Dichloropropene	4.8 U	4.8 U	4.8 U	4.8 U	4.8 U	4.8 U	4.8 U	4.8 U	2.27 U	4.8 U	4.8 U			4.8 U	4.8 U
1,1,2-Trichloroethane	5.2 U	5.2 U	5.2 U	5.2 U	5.2 U	5.2 U	5.2 U	5.2 U	2.73 U	5.2 U	5.2 U				5.2 U
1,3-Dichloropropane	6.6 U	6.6 U	6.6 U	6.6 U	6.6 U	6.6 U	6.6 U	6.6 U	NA NA	6.6 U	6.6 U		6.6 U	6.6 U	6.6 U
Tetrachloroethylene	83,000	28,000	120,000	110,000	150,000	1,100,000	55,000	42,000	8,680	130	130	2.3 U		370	1,100
Dibromochloromethane	7.4 U	7.4 U	7.4 U	7.4 U	7.4 U	7.4 U	7.4 U	7.4 U	4.26 U	7.4 U	7.4 U				7.4 U
1.2-Dibromoethane	1.0 U	1.0 U	1.0 U	1.0 U	1 U	1 U	1 U	1 U	NA	1.0 U	1.0 U			1 U	1 U
Chlorobenzene	2.4 U	2.4 U	2.4 U	2.4 U	2.4 U	35	2.4 U	2.4 U	4.05	2.4 U	2.4 U				2.4 U
1.1.1.2-Tetrachloroethane	8.7 U	8.7 U	8.7 U	8.7 U	8.7 U	160	8.7 U	8.7 U	NA	8.7 U	8.7 U			_	8.7 U
Bromoform	5.3 U	5.3 U	5.3 U	5.3 U	5.3 U	5.3 U	5.3 U	5.3 U	NA	5.3 U					
1,1,2,2-Tetrachloroethane	2.9 U	2.9 U	2.9 U	2.9 U	2.9 U	2.9 U	2.9 U	2.9 U	2.06 U	2.9 U	2.9 U		2.9 U	2.9 U	2.9 U
1,2,3-Trichloropropane	2.3 U	2.3 U	2.3 U	2.3 U	2.3 U	2.3 U	2.3 U	2.3 U	NA	2.3 U	2.3 U				2.3 U
Bromobenzene	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	NA	4.1 U	4.1 U		4.1 U	4.1 U	4.1 U
2-Chlorotoluene	53	3.2 U	3.2 U	12	3.2 U	3.2 U	3.2 U	3.2 U	NA	67	17	3.2 U	3.2 U	3.2 U	3.2 U
4-Chlorotoluene	20	4.0 U	11	4.0 U	4 U	4 U	17	4 U	NA	18	7.3	4.0 U	4.0 U		4 U
1,3-Dichlorobenzene	4.1 U	4.1 U	11	4.1 U	4.1 U	12	20	4.1 U	1.80 U	16	17	8.3	4.1 U	7	4.1 U
1.4-Dichlorobenzene	4.5 U	13	11	12	4.5 U	14	26	4.5 U	1.80 U	4.5 U	4.5 U		4.5 U	4.5 U	16
1,2-Dichlorobenzene	26	2.8 U	2.8 U	2.8 U	2.8 U	46	26	2.8 U	1.80 U	27	2.8 U		2.8 U	28	26
1,2-Dibromo-3-Chloropropane	10 U	50	320	10 U	NA	10 U	10 U			10 U	10 U				
1,2,4-Trichlorobenzene	4.7 U	23	4.7 U	14	43	4.7 U	4.7 U	4.7 U	2.23 U	32	4.7 U			4.7 U	4.7 U
Hexachlorobutadiene	6.9 U	6.9 U	36	35	6.9 U	6.9 U	6.9 U	6.9 U	10.7 U	6.9 U	6.9 U			6.9 U	6.9 U
1,2,3-Trichlorobenzene	35	4.5 U	4.5 U	4.5 U	4.5 U	4.5 U	4.5 U	4.5 U	NA	27	4.5 U			4.5 U	27
CFC-113 (1,1,2-Trichloro-1,2,2-trifluoroethane)	NA	NA	NA	NA	NA	NA	NA	NA	3.83 U	NA	NA	NA	NA	NA	NA
Benzyl chloride	NA	NA	NA	NA	NA	NA	NA	NA	2.59 U	NA	NA	NA	NA	NA	NA
Dichlorotetrafluoroethane (CFC-114)	NA	NA	NA	NA	NA	NA	NA	NA	3.50 U	NA	NA	NA	NA	NA	NA

TABLE 5 INFLUENT, MID-POINT, AND EFFLUENT VAPOR ANALYTICAL RESULTS FORMER HEAVENS SUPPLY COMPANY SITE SEATTLE, WASHINGTON

	Mid-Poi	nt Vapor	1			Efflue	ent Vapor			
	ERH-MID2	ERH-MID2	ERH-EFF	ERH-EFF	ERH-EFF	ERH-EFF	ERH-EFF	ERH-EFF	ERH-EFF	ERH-EFF
	EV13050038-04 05/07/2013	1306022-003A 6/4/2013	EV13030027-01 03/05/2013	EV13030086-07 3/14/2013	EV13030119-09 03/19/2013	EV13030152-03 03/27/2013	EV13040012-04 04/02/2013	EV13040048-03 04/09/2013	EV13050038-02 05/07/2013	1306022-002A 6/4/2013
VOLATILES (µg/m³)										
Method EPA 8260B/TO-15										
Dichlorodifluoromethane	9.4 U	1.48 U	9.4 U	9.4 U	9.4 U	9.4 U	9.4 U	9.4 U	9.4 U	3.46
Chloromethane	23 U	12.9	23 U	220	23 U	13.4				
Vinyl Chloride	3.1 U	0.511 U	3.1 U	33	3.1 U	0.511 U				
Bromomethane	14 U	NA	14 U	14 U	14 U	14 U	14 U	14 U	14 U	NA NA
Chloroethane	12 U	1.32 U	12 U	12 U	12 U	12 U	12 U	12 U	12 U	1.32 U
Carbon Tetrachloride	2.5 U	1.26 U	2.5 U	2.5 U	2.5 U	2.5 U	2.5 U	2.5 U	25 U	1.26 U
Trichlorofluoromethane	4.5 U	1.69 U	4.5 U	4.5 U	4.5 U	4.5 U	4.5 U	4.5 U	4 5 U	1.69 U
1.1-Dichloroethene	1.4 U	103	1.4 U	1.4 U	1.4 U	1.4 U	1.4 U	1.4 U	1.4 U	5.71
Methylene Chloride	68 U	NA	68 U	68 U	68 U	230	68 U	68 U	68 U	NA
Trans-1,2-Dichloroethene	9.7 U	0.793 U	9.7 U	9.7 U	9.7 U	9.7 U	9.7 U	9.7 U	9.7 U	0.793 U
1.1-Dichloroethane	3.7 U	0.810 U	3.0 U	3.0 U	3.0 U	3.0 U	3.7 U	3.7 U	3.7 U	0.810 U
Cis-1,2-Dichloroethene	6.8 U	11.7	6.8 U	20	100	6.8 U	6.8 U	6.8 U	68 U	7.22
2,2-Dichloropropane	4.1 U	NA	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	NA
Bromochloromethane	11 U	NA	11 U	11 U	11 U	11 U	11 U	11 U	11 U	NA NA
Chloroform	14 U	0.977 U	110	120	130	140	14 U	14 U	14 U	0.977 U
1,1,1-Trichloroethane	5.9 U	1.09 U	29	5.9 U	5.9 U	5.9 U	5.9 U	5.9 U	59 U	1.09 U
1,1-Dichloropropene	6.7 U	1.09 U NA	6.7 U	6.7 U	6.7 U	6.7 U	6.7 U	6.7 U	6.7 U	NA
1,2-Dichloroethane	1.4 U	0.809 U	17	1.4 U		1.4 U	1.4 U	1.4 U	1.4 U	1.94
Trichloroethene	45	1.07 U	430	28	78	200	220	5.4 U	5.4 U	8.28
	6.3 U	2.31 U	6.3 U	6.3 U	6.3 U	6.3 U	6.3 U	6.3 U	6.4 U	2.31 U
1,2-Dichloropropane				7.1 U						
Dibromomethane	7.1 U 5.9 U	NA 2.01 U	7.1 U 5.9 U	7.1 U 5.9 U	7.1 U 5.9 U	7.1 U 5.9 U	7.1 U 5.9 U	7.1 U 5.9 U	7.1 U 5 9 U	NA 2.01 U
Bromodichloromethane	5.9 U 5.8 U		5.9 U		5.9 U 5.8 U		5.9 U 5.8 U		5 9 U	
Trans-1,3-Dichloropropene		2.27 U		5.8 U		5.8 U		5.8 U		2.27 U
Cis-1,3-Dichloropropene	4.8 U	2.27 U	4.8 U	4.8 U	4.8 U	4.8 U	4.8 U	4.8 U	4 8 U	2.27 U
1,1,2-Trichloroethane	5.2 U 6.6 U	2.73 U	5.2 U 6.6 U	5.2 U 6.6 U	5.2 U 6.6 U	5.2 U	5.2 U 6.6 U	5.2 U	5 2 U 6.6 U	2.73 U
1,3-Dichloropropane		NA 0.00 II				6.6 U		6.6 U		NA 24.0
Tetrachloroethylene	520	2.03 U	160	2.3 U	100	330	370	520	23 U	24.0
Dibromochloromethane	7.4 U	4.26 U	7.4 U	7.4 U	7.4 U	7.4 U	7.4 U	7.4 U	7.4 U	4.26 U
1,2-Dibromoethane	1 U	NA 0.004 H	1.0 U	1.0 U	1.0 U	1.0 U	1 U	1 U	1 U	NA
Chlorobenzene	2.4 U	0.921 U	2.4 U	2.4 U	2.4 U	2.4 U	2.4 U	2.4 U	2.4 U	2.12
1,1,1,2-Tetrachloroethane	8.7 U	NA	8.7 U	8.7 U	8.7 U	8.7 U	8.7 U	8.7 U	8.7 U	NA
Bromoform	5.3 U	NA	5.3 U	5.3 U	5.3 U	5.3 U	5.3 U	5.3 U	5 3 U	NA
1,1,2,2-Tetrachloroethane	2.9 U	2.06 U	2.9 U	2.9 U	2.9 U	2.9 U	2.9 U	2.9 U	29 U	2.06 U
1,2,3-Trichloropropane	2.3 U	NA	2.3 U	2.3 U	2.3 U	2.3 U	2.3 U	2.3 U	2 3 U	NA
Bromobenzene	4.1 U	NA	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	NA
2-Chlorotoluene	37	NA	130	17	21	3.2 U	3.2 U	3.2 U	3 2 U	NA
4-Chlorotoluene	4 U	NA	22	12	4.0 U	4.0 U	4 U	4 U	4 U	NA
1,3-Dichlorobenzene	4.1 U	1.80 U	20	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	4.1 U	1.80 U
1,4-Dichlorobenzene	4.5 U	1.80 U	27	12	4.5 U	17	4.5 U	4.5 U	4 5 U	1.80 U
1,2-Dichlorobenzene	2.8 U	1.80 U	43	25	2.8 U	2.8 U	2.8 U	11	28 U	1.80 U
1,2-Dibromo-3-Chloropropane	10 U	NA	10 U	10 U	10 U	10 U	10 U	10 U	10 U	NA
1,2,4-Trichlorobenzene	4.7 U	2.23 U	43	4.7 U	26	4.7 U	4.7 U	18	4.7 U	2.23 U
Hexachlorobutadiene	6.9 U	10.7 U	6.9 U		6.9 U	6.9 U	6.9 U	6.9 U	69 U	10.7 U
1,2,3-Trichlorobenzene	4.5 U	NA	4.5 U	4.5 U	4.5 U	4.5 U	4.5 U	4.5 U	4 5 U	NA
CFC-113 (1,1,2-Trichloro-1,2,2-trifluoroethane)	NA	3.83 U	NA	NA	NA	NA	NA	NA	NA	3.83 U
Benzyl chloride	NA	2.59 U	NA	NA	NA	NA	NA	NA	NA	2.59 U
Dichlorotetrafluoroethane (CFC-114)	NA	3.50 U	NA	NA	NA	NA	NA	NA	NA	3.50 U

U = Indicates the compound was not detected at the reported concentration. Bold = Detected compound.

TRS Electrical Resistance Heating Weekly Status Reports for May 27 to July 1, 2013



June 5, 2013

Ms. Mindy DeYoung Riddell Williams P.S. 1001 Fourth Avenue, Suite 4500 Seattle, WA 98154-1192

Subject: Electrical Resistance Heating Weekly Status Report May 27, 2013 to June 3, 2013 Heavens Supply Site 7009 Greenwood Avenue, Seattle, Washington 98103

Dear Ms. DeYoung,

This status report presents a summary of the Electrical Resistance Heating (ERH) related activities at 7009 Greenwood Avenue, Seattle, Washington (Site). The time period addressed in this report is from May 27, 2013 through June 3, 2013. A summary of field activities, ERH system status, and upcoming work are presented in the following sections.

ERH Application Summary

The key ERH system operational parameters for the reporting period are presented in **Table 1**, which includes data from the previous reporting period for comparison.

ERH System ParametersJune 3, 2013May 27, 2013Weekly Average Power (kW)8251,058Cumulative Energy Applied (kWh)1,233,6521,095,010Average Subsurface Temperature (°C)93.990.4Average Vapor System Flow Rate (scfm)686685

Table 1. ERH System Operating Parameters

TRS personnel were onsite throughout the reporting period. Tasks accomplished during the reporting period included:

- Daily collection of ERH system operation data and optimization of system performance.
- Completed routine equipment maintenance activities.
- Collected weekly vacuum readings from all available VR piping headers.
- Collected vacuum readings from each of the nine vacuum control points (VCPs) as well as from each side of the newly installed vent/block/vent utility abandonment.

The vapor recovery and vapor abatement systems operated within design parameters and in compliance with the Puget Sound Clean Air Agency (PSCAA) air permit conditions during the reporting period.

Treatment Region Temperatures

Treatment region temperatures are monitored at twelve temperature monitoring points (TMPs) containing thermocouples arrayed vertically. The average subsurface temperature for the site prior to the initial start of power application was 16.4 degrees Celsius (°C). The average subsurface temperature at the end of this reporting period was 93.9°C, an increase of 77.5°C since the start of operations and an increase of 3.5°C within this reporting period. The highest observed subsurface temperature for this reporting period was 106.2°C, at a depth of 12 feet below grade surface (ft bgs) at TMP D7 on May 30, 2013.

For the purpose of adequately illustrating the temperature change, the data was segregated into twelve separate graphs based on the TMP location. Temperatures relative to depth for each TMP are presented in **Figures 2a** through **2l.** Average subsurface temperature over time is presented in **Figure 3**.

Power and Energy

The PCU averaged 825 kilowatts (kW) of applied power to the treatment volume during the reporting period. A total of 1,233,652 kilowatt-hours (kWh) of energy have been applied to the subsurface as of June 3, 2013. This is approximately 41% of the design energy input.

ERH Vapor Recovery and Mass Removal

The vapor stream flow rate as measured after the vapor recovery blower averaged 686 standard cubic feet per minute (scfm) throughout the operating period.

Vapor samples are collected with the other operational data and analyzed onsite using a photo ionization detector (PID) as well as by laboratory analysis. This data and information is used to measure system performance (i.e. pounds of contaminant removed), air permit compliance, and are also factored into future system operations and adjustments. **Table 2** presents the cumulative recovery rate and estimated removed volatile organic compound (VOC) mass based on influent analytical data collected through May 7, 2013. **Figure 4** presents a graph of the cumulative VOC mass removed over time for both analytical data as well as PID field screening. As of May 7, 2013 the estimated total mass recovered is 864 pounds of VOCs.

Planned Activities

TRS personnel will visit the site the week of June 3, 2013 to continue full time operations of the ERH system.

Should you have any questions concerning this report, or if you would like any additional information, please contact either me or Lynette Stauch by phone at (720) 940-4885 and (505) 281-9553, respectively.

Sincerely,

TRS Group, Inc.



MBL

Jeff Brink

Project Manager

Attachments: Figure 1 – Site Plan

Table 2 – Mass Removed


Figure 2a – TMP B4 Temperature vs. Depth Figure 2b – TMP B7 Temperature vs. Depth Figure 2c – TMP C3 Temperature vs. Depth Figure 2d – TMP D7 Temperature vs. Depth Figure 2e – TMP E4 Temperature vs. Depth Figure 2f – TMP E9 Temperature vs. Depth Figure 2g – TMP F6 Temperature vs. Depth Figure 2h – TMP F7 Temperature vs. Depth Figure 2j – TMP H7 Temperature vs. Depth Figure 2j – TMP H10 Temperature vs. Depth Figure 2k – TMP K8 Temperature vs. Depth Figure 2l – TMP K10 Temperature vs. Depth


Figure 3 – Average Subsurface Temperature vs. Time

Figure 4 – Cumulative Mass Removed

cc: Lynette Stauch, TRS
Piper Roelen, Landau
Tim Warner, TRS







- SHALLOW ELECTRODE (8)
- **▼** TEMPERATURE MONITORING POINT (12)

20'

THERMOCOUPLE (4)



CONFIDENTIAL: INFORMATION CONTAINED IN THIS DOCUMENT IS CONFIDENTIAL AND THE PROPERTY OF TRS GROUP, INC. NO INFORMATION CONTAINED HEREIN MAY BE DUPLICATED, USED OR DISTRIBUTED WITHOUT THE EXPRESSED WRITTEN PERMISSION OF TRS GROUP, INC, LONGVIEW, WA.

40'

DESIGNED BY C. CROWNOVER	FOR	HEAVEN SUPPLY		
DRAWN BY C. CROWNOVER		SEATTLE, WASHINGTON		
CHECKED BY TRS	22			
PROJECT MANAGER J. BRINK	ERH	ERH SYSTEM DESIGN		
APPROVED FOR IMPLEMENTATION		DATE 12/06/11	PROJECT SEA19	
FOR	DATE	SHEET FIGU	JRE 1	

Table 2. ERH System VOC Mass Removal (based on analytical data)

Date	Mass Removed (lb)	Total Mass Removed (lb)
3-5-13	9	9
3-14-13	21	30
3-19-13	18	48
3-27-13	38	87
4-2-13	39	126
4-9-13	335	461
5-3-13	393	854
5-7-13	10	864




Figure 2a. TMP B4 Temperature vs. Depth






Figure 2b. TMP B7 Temperature vs. Depth






Figure 2c. TMP C3 Temperature vs. Depth






Figure 2d. TMP D7 Temperature vs. Depth






Figure 2e. TMP E4 Temperature vs. Depth






Figure 2f. TMP E9 Temperature vs. Depth






Figure 2g. TMP F6 Temperature vs. Depth






Figure 2h. TMP F7 Temperature vs. Depth






Figure 2i. TMP H7 Temperature vs. Depth






Figure 2j. TMP H10 Temperature vs. Depth






Figure 2k. TMP K8 Temperature vs. Depth






Figure 21. TMP K10 Temperature vs. Depth






Figure 3. Average Subsurface Temperatures






Figure 4. Cumulative Mass Removed







June 12, 2013

Ms. Mindy DeYoung Riddell Williams P.S. 1001 Fourth Avenue, Suite 4500 Seattle, WA 98154-1192

Subject: Electrical Resistance Heating Weekly Status Report June 3, 2013 to June 10, 2013 Heavens Supply Site 7009 Greenwood Avenue, Seattle, Washington 98103

Dear Ms. DeYoung,

This status report presents a summary of the Electrical Resistance Heating (ERH) related activities at 7009 Greenwood Avenue, Seattle, Washington (Site). The time period addressed in this report is from June 3, 2013 through June 10, 2013. A summary of field activities, ERH system status, and upcoming work are presented in the following sections.

ERH Application Summary

The key ERH system operational parameters for the reporting period are presented in **Table 1**, which includes data from the previous reporting period for comparison.

Table 1. ERH System Operating Parameters

ERH System Parameters	June 10, 2013	June 3, 2013
Weekly Average Power (kW)	757	825
Cumulative Energy Applied (kWh)	1,360,875	1,233,652
Average Subsurface Temperature (°C)	97.2	93.9
Average Vapor System Flow Rate (scfm)	692	686

TRS personnel were onsite throughout the reporting period. Tasks accomplished during the reporting period included:

- Daily collection of ERH system operation data and optimization of system performance.
- Completed routine equipment maintenance activities.
- Collected weekly vacuum readings from all available VR piping headers.
- Collected vacuum readings from each of the nine vacuum control points (VCPs) as well as from each side of the newly installed vent/block/vent utility abandonment.

The vapor recovery and vapor abatement systems operated within design parameters and in compliance with the Puget Sound Clean Air Agency (PSCAA) air permit conditions during the reporting period.

Treatment Region Temperatures

Treatment region temperatures are monitored at twelve temperature monitoring points (TMPs) containing thermocouples arrayed vertically. The average subsurface temperature for the site prior to the initial start of power application was 16.4 degrees Celsius (°C). The average subsurface temperature at the end of this reporting period was 97.2°C, an increase of 80.8°C since the start of operations and an increase of 3.3°C within this reporting period. The highest observed subsurface temperature for this reporting period was 108.8°C, at a depth of 12 feet below grade surface (ft bgs) at TMP B7 on June 9, 2013.

For the purpose of adequately illustrating the temperature change, the data was segregated into twelve separate graphs based on the TMP location. Temperatures relative to depth for each TMP are presented in **Figures 2a** through **2l.** Average subsurface temperature over time is presented in **Figure 3**.

Power and Energy

The PCU averaged 757 kilowatts (kW) of applied power to the treatment volume during the reporting period. A total of 1,360,875 kilowatt-hours (kWh) of energy have been applied to the subsurface as of June 10, 2013. This is approximately 45% of the design energy input.

ERH Vapor Recovery and Mass Removal

The vapor stream flow rate as measured after the vapor recovery blower averaged 692 standard cubic feet per minute (scfm) throughout the operating period.

Vapor samples are collected with the other operational data and analyzed onsite using a photo ionization detector (PID) as well as by laboratory analysis. This data and information is used to measure system performance (i.e. pounds of contaminant removed), air permit compliance, and are also factored into future system operations and adjustments. **Table 2** presents the cumulative recovery rate and estimated removed volatile organic compound (VOC) mass based on influent analytical data collected through June 4, 2013. **Figure 4** presents a graph of the cumulative VOC mass removed over time for both analytical data as well as PID field screening. As of June 4, 2013 the estimated total mass recovered is 908 pounds of VOCs.

Planned Activities

TRS personnel will visit the site the week of June 10, 2013 to continue full time operations of the ERH system.

Based on ERH operational parameters and recent influent concentrations to the VGAC, TRS has requested that Landau and Associates complete the first round of soil sampling as soon as possible. This data will allow TRS to focus energy on areas that may still require additional remediation and should result in a net energy savings to the project. The first sampling event is currently scheduled to begin on June 27, 2013.

Should you have any questions concerning this report, or if you would like any additional information, please contact either me or Lynette Stauch by phone at (720) 940-4885 and (505) 281-9553, respectively.



Sincerely,

TRS Group, Inc.

Jeff Brink

Project Manager

Attachments: Figure 1 – Site Plan

Table 2 - Mass Removed


Figure 2a – TMP B4 Temperature vs. Depth Figure 2b – TMP B7 Temperature vs. Depth Figure 2c – TMP C3 Temperature vs. Depth Figure 2d – TMP D7 Temperature vs. Depth Figure 2e – TMP E4 Temperature vs. Depth Figure 2f – TMP E9 Temperature vs. Depth Figure 2g – TMP F6 Temperature vs. Depth Figure 2h – TMP F7 Temperature vs. Depth Figure 2i – TMP H7 Temperature vs. Depth Figure 2j – TMP H10 Temperature vs. Depth Figure 2k – TMP K8 Temperature vs. Depth Figure 2l – TMP K8 Temperature vs. Depth Figure 2l – TMP K10 Temperature vs. Depth


Figure 3 – Average Subsurface Temperature vs. Time

Figure 4 – Cumulative Mass Removed

cc: Lynette Stauch, TRS
Piper Roelen, Landau
Tim Warner, TRS







- SHALLOW ELECTRODE (8)
- **▼** TEMPERATURE MONITORING POINT (12)

20'

THERMOCOUPLE (4)



CONFIDENTIAL: INFORMATION CONTAINED IN THIS DOCUMENT IS CONFIDENTIAL AND THE PROPERTY OF TRS GROUP, INC. NO INFORMATION CONTAINED HEREIN MAY BE DUPLICATED, USED OR DISTRIBUTED WITHOUT THE EXPRESSED WRITTEN PERMISSION OF TRS GROUP, INC, LONGVIEW, WA.

40'

DESIGNED BY C. CROWNOVER	FOR	HEAVEN SUPPLY SEATTLE, WASHINGTON ERH SYSTEM DESIGN	
DRAWN BY C. CROWNOVER			
CHECKED BY TRS			
PROJECT MANAGER J. BRINK	ERH		
APPROVED FOR IMPLEME	NTATION	DATE 12/06/11	PROJECT SEA19
FOR	DATE	SHEET FIGU	JRE 1

Table 2. ERH System VOC Mass Removal (based on analytical data)

Mass Removed (lb)	Total Mass Removed (lb)
9	9
21	30
18	48
38	87
39	126
335	461
393	854
10	864
44	908
	9 21 18 38 39 335 393 10




Figure 2a. TMP B4 Temperature vs. Depth






Figure 2b. TMP B7 Temperature vs. Depth






Figure 2c. TMP C3 Temperature vs. Depth






Figure 2d. TMP D7 Temperature vs. Depth






Figure 2e. TMP E4 Temperature vs. Depth






Figure 2f. TMP E9 Temperature vs. Depth






Figure 2g. TMP F6 Temperature vs. Depth






Figure 2h. TMP F7 Temperature vs. Depth






Figure 2i. TMP H7 Temperature vs. Depth






Figure 2j. TMP H10 Temperature vs. Depth






Figure 2k. TMP K8 Temperature vs. Depth






Figure 21. TMP K10 Temperature vs. Depth






Figure 3. Average Subsurface Temperatures






Figure 4. Cumulative Mass Removed





June 19, 2013

Ms. Mindy DeYoung Riddell Williams P.S. 1001 Fourth Avenue, Suite 4500 Seattle, WA 98154-1192

Subject: Electrical Resistance Heating Weekly Status Report June 10, 2013 to June 17, 2013 Heavens Supply Site 7009 Greenwood Avenue, Seattle, Washington 98103

Dear Ms. DeYoung,

This status report presents a summary of the Electrical Resistance Heating (ERH) related activities at 7009 Greenwood Avenue, Seattle, Washington (Site). The time period addressed in this report is from June 10, 2013 through June 17, 2013. A summary of field activities, ERH system status, and upcoming work are presented in the following sections.

ERH Application Summary

The key ERH system operational parameters for the reporting period are presented in **Table 1**, which includes data from the previous reporting period for comparison.

Table 1. ERH System Operating Parameters

ERH System Parameters	June 17, 2013	June 10, 2013
Weekly Average Power (kW)	832	757
Cumulative Energy Applied (kWh)	1,500,609	1,360,875
Average Subsurface Temperature (°C)	97.3	97.2
Average Vapor System Flow Rate (scfm)	702	686

TRS personnel were onsite throughout the reporting period. Tasks accomplished during the reporting period included:

- Daily collection of ERH system operation data and optimization of system performance.
- Completed routine equipment maintenance activities.
- Collected weekly vacuum readings from all available VR piping headers.
- Collected vacuum readings from each of the nine vacuum control points (VCPs) as well as from each side of the vent/block/vent utility abandonment.

The vapor recovery and vapor abatement systems operated within design parameters and in compliance with the Puget Sound Clean Air Agency (PSCAA) air permit conditions during the reporting period.

Treatment Region Temperatures

Treatment region temperatures are monitored at twelve temperature monitoring points (TMPs) containing thermocouples arrayed vertically. The average subsurface temperature for the site prior to the initial start of power application was 16.4 degrees Celsius (°C). The average subsurface temperature at the end of this reporting period was 97.3°C, an increase of 80.9°C since the start of operations and an increase of 0.1°C within this reporting period. The highest observed subsurface temperature for this reporting period was 108.1°C, at a depth of 15 feet below grade surface (ft bgs) at TMP F7 on June 15, 2013. For the purpose of adequately illustrating the temperature change, the data was segregated into twelve separate graphs based on the TMP location. Temperatures relative to depth for each TMP are presented in **Figures 2a** through **21.** Average subsurface temperature over time is presented in **Figure 3**.

Power and Energy

The PCU averaged 832 kilowatts (kW) of applied power to the treatment volume during the reporting period. A total of 1,500,609 kilowatt-hours (kWh) of energy have been applied to the subsurface as of June 17, 2013. This is approximately 51% of the design energy input.

ERH Vapor Recovery and Mass Removal

The vapor stream flow rate as measured after the vapor recovery blower averaged 702 standard cubic feet per minute (scfm) throughout the operating period.

Vapor samples are collected with the other operational data and analyzed onsite using a photo ionization detector (PID) as well as by laboratory analysis. This data and information is used to measure system performance (i.e. pounds of contaminant removed), air permit compliance, and are also factored into future system operations and adjustments. **Table 2** presents the cumulative recovery rate and estimated removed volatile organic compound (VOC) mass based on influent analytical data collected through June 4, 2013. **Figure 4** presents a graph of the cumulative VOC mass removed over time for both analytical data as well as PID field screening. As of June 4, 2013 the estimated total mass recovered is 908 pounds of VOCs.

Planned Activities

TRS personnel will visit the site the week of June 17, 2013 to continue full time operations of the ERH system.

Based on ERH operational parameters and recent influent concentrations to the Vapor Granular Activated Carbon (VGAC), TRS has requested that Landau and Associates complete the first round of soil sampling as soon as possible. This data will allow TRS to focus energy on areas that may still require additional remediation and should result in a net energy savings to the project. The first sampling event is currently scheduled to begin on June 27, 2013. A carbon change out for both the vapor and liquid phase GAC is scheduled to be completed on June 19, 2013.

Should you have any questions concerning this report, or if you would like any additional information, please contact either me or Lynette Stauch by phone at (720) 940-4885 and (505) 281-9553, respectively.



Sincerely,

TRS Group, Inc.

Jeff Brink

Project Manager

Attachments: Figure 1 – Site Plan

Table 2 – Mass Removed


Figure 2a – TMP B4 Temperature vs. Depth
Figure 2b – TMP B7 Temperature vs. Depth
Figure 2c – TMP C3 Temperature vs. Depth
Figure 2d – TMP D7 Temperature vs. Depth
Figure 2e – TMP E4 Temperature vs. Depth
Figure 2f – TMP E9 Temperature vs. Depth
Figure 2g – TMP F6 Temperature vs. Depth
Figure 2h – TMP F7 Temperature vs. Depth
Figure 2i – TMP H7 Temperature vs. Depth
Figure 2j – TMP H10 Temperature vs. Depth
Figure 2k – TMP K8 Temperature vs. Depth
Figure 2l – TMP K8 Temperature vs. Depth


Figure 3 – Average Subsurface Temperature vs. Time

Figure 4 – Cumulative Mass Removed

cc: Lynette Stauch, TRS Piper Roelen, Landau Tim Warner, TRS







- SHALLOW ELECTRODE (8)
- **▼** TEMPERATURE MONITORING POINT (12)

20'

THERMOCOUPLE (4)



CONFIDENTIAL: INFORMATION CONTAINED IN THIS DOCUMENT IS CONFIDENTIAL AND THE PROPERTY OF TRS GROUP, INC. NO INFORMATION CONTAINED HEREIN MAY BE DUPLICATED, USED OR DISTRIBUTED WITHOUT THE EXPRESSED WRITTEN PERMISSION OF TRS GROUP, INC, LONGVIEW, WA.

40'

DESIGNED BY C. CROWNOVER	FOR	HEAVEN SUPPLY SEATTLE, WASHINGTON ERH SYSTEM DESIGN	
DRAWN BY C. CROWNOVER			
CHECKED BY TRS			
PROJECT MANAGER J. BRINK	ERH		
APPROVED FOR IMPLEME	NTATION	DATE 12/06/11	PROJECT SEA19
FOR	DATE	SHEET FIGU	JRE 1

Table 2. ERH System VOC Mass Removal (based on analytical data)

Date	Mass Removed (lb)	Total Mass Removed (lb)
3-5-13	9	9
3-14-13	21	30
3-19-13	18	48
3-27-13	38	87
4-2-13	39	126
4-9-13	335	461
5-3-13	393	854
5-7-13	10	864
6-4-13	44	908




Figure 2a. TMP B4 Temperature vs. Depth






Figure 2b. TMP B7 Temperature vs. Depth






Figure 2c. TMP C3 Temperature vs. Depth






Figure 2d. TMP D7 Temperature vs. Depth






Figure 2e. TMP E4 Temperature vs. Depth






Figure 2f. TMP E9 Temperature vs. Depth






Figure 2g. TMP F6 Temperature vs. Depth






Figure 2h. TMP F7 Temperature vs. Depth






Figure 2i. TMP H7 Temperature vs. Depth






Figure 2j. TMP H10 Temperature vs. Depth






Figure 2k. TMP K8 Temperature vs. Depth






Figure 21. TMP K10 Temperature vs. Depth






Figure 3. Average Subsurface Temperatures






Figure 4. Cumulative Mass Removed







June 26, 2013

Ms. Mindy DeYoung Riddell Williams P.S. 1001 Fourth Avenue, Suite 4500 Seattle, WA 98154-1192

Subject: Electrical Resistance Heating Weekly Status Report June 17, 2013 to June 24, 2013 Heavens Supply Site 7009 Greenwood Avenue, Seattle, Washington 98103

Dear Ms. DeYoung,

This status report presents a summary of the Electrical Resistance Heating (ERH) related activities at 7009 Greenwood Avenue, Seattle, Washington (Site). The time period addressed in this report is from June 17, 2013 through June 24, 2013. A summary of field activities, ERH system status, and upcoming work are presented in the following sections.

ERH Application Summary

The key ERH system operational parameters for the reporting period are presented in **Table 1**, which includes data from the previous reporting period for comparison.

Table 1. ERH System Operating Parameters

June 24, 2013

ERH System Parameters	June 24, 2013	June 17, 2013
Weekly Average Power (kW)	660	832
Cumulative Energy Applied (kWh)	1,611,414	1,500,609
Average Subsurface Temperature (°C)	97.3	97.3
Average Vapor System Flow Rate (scfm)	676	702

TRS personnel were onsite throughout the reporting period. Tasks accomplished during the reporting period included:

- Daily collection of ERH system operation data and optimization of system performance.
- Completed routine equipment maintenance activities.
- Collected weekly vacuum readings from all available VR piping headers.
- Collected vacuum readings from each of the nine vacuum control points (VCPs) as well as from each side of the vent/block/vent utility abandonment.
- Completed a 4,000 pound vapor phase granular activated carbon (VGAC) changeout from both secondary vessels.

• Completed a 400 pound liquid phase granular activated carbon (LGAC) changeout from both the primary and secondary LGAC vessels.

The vapor recovery and vapor abatement systems operated within design parameters and in compliance with the Puget Sound Clean Air Agency (PSCAA) air permit conditions during the reporting period.

Treatment Region Temperatures

Treatment region temperatures are monitored at twelve temperature monitoring points (TMPs) containing thermocouples arrayed vertically. The average subsurface temperature for the site prior to the initial start of power application was 16.4 degrees Celsius (°C). The average subsurface temperature at the end of this reporting period was 97.3°C, an increase of 80.9°C since the start of operations and no change in average temperature over this reporting period. The highest observed subsurface temperature for this reporting period was 109.8°C, at a depth of 28 feet below grade surface (ft bgs) at TMP E9 on June 19, 2013. For the purpose of adequately illustrating the temperature change, the data was segregated into twelve separate graphs based on the TMP location. Temperatures relative to depth for each TMP are presented in **Figures 2a** through **21.** Average subsurface temperature over time is presented in **Figure 3**.

Power and Energy

The PCU averaged 660 kilowatts (kW) of applied power to the treatment volume during the reporting period. A total of 1,611,414 kilowatt-hours (kWh) of energy have been applied to the subsurface as of June 24, 2013. This is approximately 53% of the design energy input.

ERH Vapor Recovery and Mass Removal

The vapor stream flow rate as measured after the vapor recovery blower averaged 676 standard cubic feet per minute (scfm) throughout the operating period.

Vapor samples are collected with the other operational data and analyzed onsite using a photo ionization detector (PID) as well as by laboratory analysis. This data and information is used to measure system performance (i.e. pounds of contaminant removed), air permit compliance, and are also factored into future system operations and adjustments. **Table 2** presents the cumulative recovery rate and estimated removed volatile organic compound (VOC) mass based on influent analytical data collected through June 4, 2013. **Figure 4** presents a graph of the cumulative VOC mass removed over time for both analytical data as well as PID field screening. As of June 4, 2013 the estimated total mass recovered is 908 pounds of VOCs.

Planned Activities

TRS personnel will visit the site the week of June 24, 2013 to continue full time operations of the ERH system. The ERH system will be shut down the morning of June 26, 2013 to allow the site to be down for approximately 24 hours prior to the hot soil sampling that will commence on June 27, 2013. While the active heating will be temporarily discontinued for approximately 5-7 days for the soil sampling effort, the vapor recovery system will continue to operate.



Should you have any questions concerning this report, or if you would like any additional information, please contact either me or Lynette Stauch by phone at (720) 940-4885 and (505) 281-9553, respectively.

Sincerely,

TRS Group, Inc.

Jeff Brink

Project Manager

Attachments: Figure 1 – Site Plan

Table 2 - Mass Removed

Figure 2a – TMP B4 Temperature vs. Depth Figure 2b – TMP B7 Temperature vs. Depth Figure 2c – TMP C3 Temperature vs. Depth Figure 2d – TMP D7 Temperature vs. Depth Figure 2e – TMP E4 Temperature vs. Depth Figure 2f – TMP E9 Temperature vs. Depth Figure 2g – TMP F6 Temperature vs. Depth Figure 2h – TMP F7 Temperature vs. Depth Figure 2i – TMP H7 Temperature vs. Depth Figure 2i – TMP H7 Temperature vs. Depth


Figure 2i – TMP H7 Temperature vs. Depth Figure 2j – TMP H10 Temperature vs. Depth Figure 2k – TMP K8 Temperature vs. Depth Figure 2l – TMP K10 Temperature vs. Depth


Figure 3 – Average Subsurface Temperature vs. Time

Figure 4 – Cumulative Mass Removed

cc: Lynette Stauch, TRS Piper Roelen, Landau Tim Warner, TRS







- SHALLOW ELECTRODE (8)
- **▼** TEMPERATURE MONITORING POINT (12)

20'

THERMOCOUPLE (4)



CONFIDENTIAL: INFORMATION CONTAINED IN THIS DOCUMENT IS CONFIDENTIAL AND THE PROPERTY OF TRS GROUP, INC. NO INFORMATION CONTAINED HEREIN MAY BE DUPLICATED, USED OR DISTRIBUTED WITHOUT THE EXPRESSED WRITTEN PERMISSION OF TRS GROUP, INC, LONGVIEW, WA.

40'

DESIGNED BY C. CROWNOVER	FOR	HEAVEN SUPPLY SEATTLE, WASHINGTON		
DRAWN BY C. CROWNOVER				
CHECKED BY TRS	2			
PROJECT MANAGER J. BRINK	ERH	ERH SYSTEM DESIGN		
APPROVED FOR IMPLEMENTATION		DATE 12/06/11	PROJECT SEA19	
FOR	DATE	SHEET FIGU	JRE 1	

Table 2. ERH System VOC Mass Removal (based on analytical data)

Date	Mass Removed (lb)	Total Mass Removed (lb)
3-5-13	9	9
3-14-13	21	30
3-19-13	18	48
3-27-13	38	87
4-2-13	39	126
4-9-13	335	461
5-3-13	393	854
5-7-13	10	864
6-4-13	44	908




Figure 2a. TMP B4 Temperature vs. Depth






Figure 2b. TMP B7 Temperature vs. Depth






Figure 2c. TMP C3 Temperature vs. Depth






Figure 2d. TMP D7 Temperature vs. Depth






Figure 2e. TMP E4 Temperature vs. Depth






Figure 2f. TMP E9 Temperature vs. Depth






Figure 2g. TMP F6 Temperature vs. Depth






Figure 2h. TMP F7 Temperature vs. Depth






Figure 2i. TMP H7 Temperature vs. Depth






Figure 2j. TMP H10 Temperature vs. Depth






Figure 2k. TMP K8 Temperature vs. Depth






Figure 21. TMP K10 Temperature vs. Depth






Figure 3. Average Subsurface Temperatures






Figure 4. Cumulative Mass Removed







July 9, 2013

Ms. Mindy DeYoung Riddell Williams P.S. 1001 Fourth Avenue, Suite 4500 Seattle, WA 98154-1192

Subject: Electrical Resistance Heating Weekly Status Report June 24, 2013 to July 1, 2013 Heavens Supply Site 7009 Greenwood Avenue, Seattle, Washington 98103

Dear Ms. DeYoung,

This status report presents a summary of the Electrical Resistance Heating (ERH) related activities at 7009 Greenwood Avenue, Seattle, Washington (Site). The time period addressed in this report is from June 24, 2013 through July 1, 2013. A summary of field activities, ERH system status, and upcoming work are presented in the following sections.

ERH Application Summary

The key ERH system operational parameters for the reporting period are presented in **Table 1**, which includes data from the previous reporting period for comparison.

ERH System ParametersJuly 1, 2013June 24, 2013Weekly Average Power (kW)182660Cumulative Energy Applied (kWh)1,642,0451,611,414Average Subsurface Temperature (°C)96.397.3Average Vapor System Flow Rate (scfm)709676

Table 1. ERH System Operating Parameters

TRS personnel were onsite throughout the reporting period. Tasks accomplished during the reporting period included:

- Daily collection of ERH system operation data and optimization of system performance.
- Completed routine equipment maintenance activities.
- Collected weekly vacuum readings from all available VR piping headers.
- Collected vacuum readings from each of the nine vacuum control points (VCPs) as well as from each side of the vent/block/vent utility abandonment.
- Power application was shut down on June 26, 2013 in preparation for the first round of confirmation soil sampling that began on June 27, 2013. TRS anticipates completion of soil

sampling event on Monday, July 8, 2013. to optimize the power application after receipt of the analytical results and TRS will optimize the system based on analytical results and resume normal operations on July 8, 2013.

The vapor recovery and vapor abatement systems operated within design parameters and in compliance with the Puget Sound Clean Air Agency (PSCAA) air permit conditions during the reporting period. At the time of this report we are at approximately 50% of our allowable runtime as specified in the approved PSCAA air permit.

Treatment Region Temperatures

Treatment region temperatures are monitored at twelve temperature monitoring points (TMPs) containing thermocouples arrayed vertically. The average subsurface temperature for the site prior to the initial start of power application was 16.4 degrees Celsius (°C). The average subsurface temperature at the end of this reporting period was 96.3°C, an increase of 79.9°C since the start of operations and a reduction of 1.0°C over this reporting period. The highest observed subsurface temperature for this reporting period was 109.7°C, at a depth of 28 feet below grade surface (ft bgs) at TMP E9 on June 29, 2013. For the purpose of adequately illustrating the temperature change, the data was segregated into twelve separate graphs based on the TMP location. Temperatures relative to depth for each TMP are presented in **Figures 2a** through **21.** Average subsurface temperature over time is presented in **Figure 3**.

Power and Energy

The PCU averaged 182 kilowatts (kW) of applied power to the treatment volume during the reporting period. This number is low and is to be expected as a result of temporarily discontinuing the power application on June 26, 2013 to allow for safe soil sampling. A total of 1,642,045 kilowatt-hours (kWh) of energy have been applied to the subsurface as of July 1, 2013. This is approximately 54% of the design energy input.

ERH Vapor Recovery and Mass Removal

The vapor stream flow rate as measured after the vapor recovery blower averaged 709 standard cubic feet per minute (scfm) throughout the operating period.

Vapor samples are collected with the other operational data and analyzed onsite using a photo ionization detector (PID) as well as by laboratory analysis. This data and information is used to measure system performance (i.e. pounds of contaminant removed), air permit compliance, and are also factored into future system operations and adjustments. **Table 2** presents the cumulative recovery rate and estimated removed volatile organic compound (VOC) mass based on influent analytical data collected through June 4, 2013. **Figure 4** presents a graph of the cumulative VOC mass removed over time for both analytical data as well as PID field screening. As of June 4, 2013 the estimated total mass recovered is 908 pounds of VOCs.

Planned Activities

TRS personnel will visit the site the week of July 1, 2013 to continue full time operations of the ERH system. While the ERH system will remain shut down for the soil sampling effort, the vapor recovery system will continue to operate.



Should you have any questions concerning this report, or if you would like any additional information, please contact either me or Lynette Stauch by phone at (720) 940-4885 and (505) 281-9553, respectively.

Sincerely,

TRS Group, Inc.

Jeff Brink

Project Manager

Attachments: Figure 1 – Site Plan

Table 2 - Mass Removed


Figure 2a – TMP B4 Temperature vs. Depth Figure 2b – TMP B7 Temperature vs. Depth Figure 2c – TMP C3 Temperature vs. Depth Figure 2d – TMP D7 Temperature vs. Depth Figure 2e – TMP E4 Temperature vs. Depth Figure 2f – TMP E9 Temperature vs. Depth Figure 2g – TMP F6 Temperature vs. Depth Figure 2h – TMP F7 Temperature vs. Depth Figure 2i – TMP H7 Temperature vs. Depth Figure 2j – TMP H10 Temperature vs. Depth Figure 2k – TMP K8 Temperature vs. Depth Figure 2l – TMP K8 Temperature vs. Depth Figure 2l – TMP K10 Temperature vs. Depth


Figure 3 – Average Subsurface Temperature vs. Time

Figure 4 – Cumulative Mass Removed

cc: Lynette Stauch, TRS Piper Roelen, Landau Tim Warner, TRS







- SHALLOW ELECTRODE (8)
- **▼** TEMPERATURE MONITORING POINT (12)

20'

THERMOCOUPLE (4)



CONFIDENTIAL: INFORMATION CONTAINED IN THIS DOCUMENT IS CONFIDENTIAL AND THE PROPERTY OF TRS GROUP, INC. NO INFORMATION CONTAINED HEREIN MAY BE DUPLICATED, USED OR DISTRIBUTED WITHOUT THE EXPRESSED WRITTEN PERMISSION OF TRS GROUP, INC, LONGVIEW, WA.

40'

DESIGNED BY C. CROWNOVER	FOR	HEAVEN SUPPLY		
DRAWN BY C. CROWNOVER		SEATTLE, WASHINGTON		
CHECKED BY TRS				
PROJECT MANAGER J. BRINK	ERH	ERH SYSTEM DESIGN		
APPROVED FOR IMPLEME	NTATION	DATE 12/06/11	PROJECT SEA19	
FOR	DATE	SHEET FIGU	JRE 1	

Table 2. ERH System VOC Mass Removal (based on analytical data)

Date	Mass Removed (lb)	Total Mass Removed (lb)
3-5-13	9	9
3-14-13	21	30
3-19-13	18	48
3-27-13	38	87
4-2-13	39	126
4-9-13	335	461
5-3-13	393	854
5-7-13	10	864
6-4-13	44	908




Figure 2a. TMP B4 Temperature vs. Depth






Figure 2b. TMP B7 Temperature vs. Depth






Figure 2c. TMP C3 Temperature vs. Depth






Figure 2d. TMP D7 Temperature vs. Depth






Figure 2e. TMP E4 Temperature vs. Depth






Figure 2f. TMP E9 Temperature vs. Depth






Figure 2g. TMP F6 Temperature vs. Depth






Figure 2h. TMP F7 Temperature vs. Depth






Figure 2i. TMP H7 Temperature vs. Depth






Figure 2j. TMP H10 Temperature vs. Depth






Figure 2k. TMP K8 Temperature vs. Depth






Figure 21. TMP K10 Temperature vs. Depth






Figure 3. Average Subsurface Temperatures






Figure 4. Cumulative Mass Removed



Laboratory Analytical Reports – Indoor Air



6/7/2013

Mr. Piper Roelen Landau Associates, Inc. 130 2nd Avenue South

Edmonds WA 98020

Project Name: Heaven Supply Project #: 583002.050.057 Workorder #: 1306105

Dear Mr. Piper Roelen

The following report includes the data for the above referenced project for sample(s) received on 6/7/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 SIM are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Elly Butte



WORK ORDER #: 1306105

Work Order Summary

CLIENT: Mr. Piper Roelen BILL TO: Mr. Piper Roelen

> Landau Associates, Inc. Landau Associates, Inc. 130 2nd Avenue South 130 2nd Avenue South Edmonds, WA 98020 Edmonds, WA 98020

PHONE: 800-552-5957 P.O. # 583002.050.057

FAX: 425-778-6409 PROJECT # 583002.050.057 Heaven Supply

DATE RECEIVED: 06/07/2013 **CONTACT:** Kelly Buettner **DATE COMPLETED:** 06/07/2013

			RECEIPT	FINAL
FRACTION #	<u>NAME</u>	<u>TEST</u>	VAC./PRES.	PRESSURE
01A	Privacy FOIA - Basement:060513	Modified TO-15 SIM	3.1 "Hg	5 psi
02A	Lab Blank	Modified TO-15 SIM	NA	NA
03A	CCV	Modified TO-15 SIM	NA	NA
04A	LCS	Modified TO-15 SIM	NA	NA
04AA	LCSD	Modified TO-15 SIM	NA	NA

	14	ude Tlayer		
CERTIFIED BY:			DATE: 06/07/13	

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935

Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program) Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.

Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.







LABORATORY NARRATIVE Modified TO-15 SIM Landau Associates, Inc. Workorder# 1306105

One 6 Liter Summa Canister sample was received on June 07, 2013. The laboratory performed analysis via modified EPA Method TO-15 using GC/MS in the SIM acquisition mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

Requirement	TO-15	ATL Modifications
ICAL %RSD acceptance criteria	=30% RSD with 2<br compounds allowed out to < 40% RSD	Project specific; default criteria is =30% RSD with 10% of compounds allowed out to < 40% RSD</td
Daily Calibration	+- 30% Difference	Project specific; default criteria is = 30% Difference with 10% of compounds allowed out up to </=40%.; flag and narrate outliers</td
Blank and standards	Zero air	Nitrogen
Method Detection Limit	Follow 40CFR Pt.136 App. B	The MDL met all relevant requirements in Method TO-15 (statistical MDL less than the LOQ). The concentration of the spiked replicate may have exceeded 10X the calculated MDL in some cases

Receiving Notes

There were no receiving discrepancies.

Analytical Notes

There were no analytical discrepancies.

Definition of Data Qualifying Flags

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

- B Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
 - J Estimated value.
 - E Exceeds instrument calibration range.
 - S Saturated peak.
 - Q Exceeds quality control limits.
- U Compound analyzed for but not detected above the reporting limit, LOD, or MDL value. See data page for project specific U-flag definition.
 - UJ- Non-detected compound associated with low bias in the CCV
 - N The identification is based on presumptive evidence.



File extensions may have been used on the data analysis sheets and indicates as follows:

a-File was requantified

b-File was quantified by a second column and detector

r1-File was requantified for the purpose of reissue



Summary of Detected Compounds MODIFIED EPA METHOD TO-15 GC/MS SIM

Client Sample ID: Privacy FOIA - Basement:060513

Lab ID#: 1306105-01A

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Vinyl Chloride	0.015	0.017	0.038	0.043
Trichloroethene	0.0045	0.0055	0.024	0.029



Client Sample ID: Privacy FOIA - Basement:060513

Lab ID#: 1306105-01A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	c060711sim	Date of Collection: 6/5/13 5:32:00 PM
Dil. Factor:	1.49	Date of Analysis: 6/7/13 04:15 PM

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.015	0.017	0.038	0.043
Trichloroethene	0.0045	0.0055	0.024	0.029
Tetrachloroethene	0.030	Not Detected	0.20	Not Detected
cis-1,2-Dichloroethene	0.030	Not Detected	0.12	Not Detected

Container Type: 6 Liter Summa Canister

		wethod	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	114	70-130	
Toluene-d8	94	70-130	
4-Bromofluorobenzene	106	70-130	



Client Sample ID: Lab Blank Lab ID#: 1306105-02A

MODIFIED EPA METHOD TO-15 GC/MS SIM

Dil. Factor:	1.00	Date of Analysis: 6/7/13 12:44 PM
File Name:	c060707asim	Date of Collection: NA

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.010	Not Detected	0.026	Not Detected
Trichloroethene	0.0030	Not Detected	0.016	Not Detected
Tetrachloroethene	0.020	Not Detected	0.14	Not Detected
cis-1,2-Dichloroethene	0.020	Not Detected	0.079	Not Detected

		Wethod
Surrogates	%Recovery	Limits
1,2-Dichloroethane-d4	112	70-130
Toluene-d8	95	70-130
4-Bromofluorobenzene	102	70-130



Client Sample ID: CCV Lab ID#: 1306105-03A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	c060703sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/7/13 09:24 AM

Compound	%Recovery
Vinyl Chloride	88
Trichloroethene	91
Tetrachloroethene	112
cis-1.2-Dichloroethene	105

,		Method		
Surrogates	%Recovery	Limits		
1,2-Dichloroethane-d4	102	70-130		
Toluene-d8	98	70-130		
4-Bromofluorobenzene	98	70-130		



Client Sample ID: LCS Lab ID#: 1306105-04A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	c060704sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/7/13 10:07 AM

Compound	%Recovery
Vinyl Chloride	97
Trichloroethene	102
Tetrachloroethene	119
cis-1.2-Dichloroethene	114

		wethod		
Surrogates	%Recovery	Limits		
1,2-Dichloroethane-d4	101	70-130		
Toluene-d8	100	70-130		
4-Bromofluorobenzene	100	70-130		



Client Sample ID: LCSD Lab ID#: 1306105-04AA

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	c060705sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/7/13 10:50 AM

Compound	%Recovery
Vinyl Chloride	93
Trichloroethene	100
Tetrachloroethene	117
cis-1.2-Dichloroethene	110

		wethod		
Surrogates	%Recovery	Limits		
1,2-Dichloroethane-d4	100	70-130		
Toluene-d8	99	70-130		
4-Bromofluorobenzene	100	70-130		

☐ Tacoma (25) LANDAU ☐ Spokane (50) ASSOCIATES ☐ Portland (50)		Cha	ain-of-	.C.	etody.	, Ba	cord			Date 6/5/13 Page(of
Project Name Herry's Supply Project Location/Event Serthle, Sampler's Name Dylon Fra 2. Project Contact Apr Rock Send Results To Apr Rock	Projec	ot No. <u>583</u>	002.05t	2, 057	7.5	T	esting Para	ameters	S	Turnaround Time ☐ Standard ☐ Accelerated ✓ Same day
Sample I.D. 7013 Greenwood - Biscourt, 0605/3	Date Time 6/5/13 1732	Matrix (Containers /						_X Allow water sa aliquot from clear p	s/Comments , mples to settle, collect portion un acid wash/silica gel cleanup
									Analyze for EP product identified VOC/BTEX/VPH non-preserved	oroduct H if no specific soll):
		\$ 21.	30610						preserved w/m preserved w/su Freeze upon re Dissolved meta	odium bisulfate
			Seal Inta						Inital Press	ne: -29 JoHz
Relinquished by	Received t	X(V)X			Relinquis	shed by		Method Shipme		
Signature Out Funce Printed Name Company	Signature LATAC Printed Nam Company	peckey			Signature Printed Na	ìme			Signature Printed Name	
Date 6/4/3 Time 1500		7 [[3	ime <u>075</u> 0	5	Company Date		Time	Trap, side	Company	Time



6/7/2013

Mr. Piper Roelen Landau Associates, Inc. 130 2nd Avenue South

Edmonds WA 98020

Project Name: Heaven Supply Project #: 583002.050.057 Workorder #: 1306106

Dear Mr. Piper Roelen

The following report includes the data for the above referenced project for sample(s) received on 6/7/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 SIM are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Elly Butte



WORK ORDER #: 1306106

Work Order Summary

CLIENT: Mr. Piper Roelen BILL TO: Mr. Piper Roelen

Landau Associates, Inc.
Landau Associates, Inc.
130 2nd Avenue South
Edmonds, WA 98020
Landau Associates, Inc.
130 2nd Avenue South
Edmonds, WA 98020

PHONE: 800-552-5957 **P.O.** # 583002.050.057

FAX: 425-778-6409 **PROJECT** # 583002.050.057 Heaven Supply

DATE RECEIVED: 06/07/2013 **CONTACT:** Kelly Buettner 06/07/2013

			RECEIPT	FINAL
FRACTION #	<u>NAME</u>	<u>TEST</u>	VAC./PRES.	PRESSURE
01A	- Basement:060513	Modified TO-15 SIM	9.6 "Hg	4.9 psi
02A	Privacy - Basement:060513	Modified TO-15 SIM	7.3 "Hg	4.8 psi
03A	- Basement:060513	Modified TO-15 SIM	6.7 "Hg	4.9 psi
04A	Lab Blank	Modified TO-15 SIM	NA	NA
05A	CCV	Modified TO-15 SIM	NA	NA
06A	LCS	Modified TO-15 SIM	NA	NA
06AA	LCSD	Modified TO-15 SIM	NA	NA

	fleide payer	
CERTIFIED BY:		DATE: $\frac{06/07/13}{}$

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935

Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)

Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.

Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.





LABORATORY NARRATIVE Modified TO-15 SIM Landau Associates, Inc. Workorder# 1306106

Three 6 Liter Summa Canister (SIM Certified) samples were received on June 07, 2013. The laboratory performed analysis via modified EPA Method TO-15 using GC/MS in the SIM acquisition mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

Requirement	TO-15	ATL Modifications
ICAL %RSD acceptance criteria	<pre><!--=30% RSD with 2 compounds allowed out to < 40% RSD</pre--></pre>	Project specific; default criteria is =30% RSD with 10% of compounds allowed out to < 40% RSD</td
Daily Calibration	+- 30% Difference	Project specific; default criteria is = 30% Difference with 10% of compounds allowed out up to </=40%.; flag and narrate outliers</td
Blank and standards	Zero air	Nitrogen
Method Detection Limit	Follow 40CFR Pt.136 App. B	The MDL met all relevant requirements in Method TO-15 (statistical MDL less than the LOQ). The concentration of the spiked replicate may have exceeded 10X the calculated MDL in some cases

Receiving Notes

There were no receiving discrepancies.

Analytical Notes

There were no analytical discrepancies.

Definition of Data Qualifying Flags

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

- B Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
 - J Estimated value.
 - E Exceeds instrument calibration range.
 - S Saturated peak.
 - Q Exceeds quality control limits.
- U Compound analyzed for but not detected above the reporting limit, LOD, or MDL value. See data page for project specific U-flag definition.
 - UJ- Non-detected compound associated with low bias in the CCV



N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:

- a-File was requantified
- b-File was quantified by a second column and detector
- r1-File was requantified for the purpose of reissue



Summary of Detected Compounds MODIFIED EPA METHOD TO-15 GC/MS SIM

Client Sample ID: Privacy - Basement:060513

Lab ID#: 1306106-01A
No Detections Were Found.

Client Sample ID: Privacy - Basement:060513

Lab ID#: 1306106-02A
No Detections Were Found.

Client Sample ID: Privacy - Basement:060513

Lab ID#: 1306106-03A
No Detections Were Found.



Client Sample ID: Privacy - Basement:060513

Lab ID#: 1306106-01A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	c060708sim	Date of Collection: 6/5/13 7:27:00 AM
Dil. Factor:	1.96	Date of Analysis: 6/7/13 01:38 PM

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Vinyl Chloride	0.020	Not Detected	0.050	Not Detected
Trichloroethene	0.0059	Not Detected	0.032	Not Detected
Tetrachloroethene	0.039	Not Detected	0.26	Not Detected
cis-1.2-Dichloroethene	0.039	Not Detected	0.16	Not Detected

Container Type: 6 Liter Summa Canister (SIM Certified)

		Method	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	113	70-130	
Toluene-d8	94	70-130	
4-Bromofluorobenzene	104	70-130	



Client Sample ID: Privacy - Basement:060513

Lab ID#: 1306106-02A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	c060709sim	Date of Collection: 6/5/13 7:36:00 AM
Dil. Factor:	1.76	Date of Analysis: 6/7/13 02:26 PM

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.018	Not Detected	0.045	Not Detected
Trichloroethene	0.0053	Not Detected	0.028	Not Detected
Tetrachloroethene	0.035	Not Detected	0.24	Not Detected
cis-1,2-Dichloroethene	0.035	Not Detected	0.14	Not Detected

Container Type: 6 Liter Summa Canister (SIM Certified)

		Method	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	114	70-130	
Toluene-d8	94	70-130	
4-Bromofluorobenzene	103	70-130	



Client Sample ID: Privacy - Basement:060513

Lab ID#: 1306106-03A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	c060710sim	Date of Collection: 6/5/13 9:04:00 AM
Dil. Factor:	1.72	Date of Analysis: 6/7/13 03:13 PM

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.017	Not Detected	0.044	Not Detected
Trichloroethene	0.0052	Not Detected	0.028	Not Detected
Tetrachloroethene	0.034	Not Detected	0.23	Not Detected
cis-1,2-Dichloroethene	0.034	Not Detected	0.14	Not Detected

		Method	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	113	70-130	
Toluene-d8	93	70-130	
4-Bromofluorobenzene	106	70-130	



Client Sample ID: Lab Blank Lab ID#: 1306106-04A

MODIFIED EPA METHOD TO-15 GC/MS SIM

Dil. Factor:	1.00	Date of Analysis: 6/7/13 12:44 PM
File Name:	c060707asim	Date of Collection: NA

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.010	Not Detected	0.026	Not Detected
Trichloroethene	0.0030	Not Detected	0.016	Not Detected
Tetrachloroethene	0.020	Not Detected	0.14	Not Detected
cis-1,2-Dichloroethene	0.020	Not Detected	0.079	Not Detected

		wethod	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	112	70-130	
Toluene-d8	95	70-130	
4-Bromofluorobenzene	102	70-130	



Client Sample ID: CCV Lab ID#: 1306106-05A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	c060703sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/7/13 09:24 AM

Compound	%Recovery
Vinyl Chloride	88
Trichloroethene	91
Tetrachloroethene	112
cis-1.2-Dichloroethene	105

		wethod	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	102	70-130	
Toluene-d8	98	70-130	
4-Bromofluorobenzene	98	70-130	



Client Sample ID: LCS Lab ID#: 1306106-06A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	c060704sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/7/13 10:07 AM

Compound	%Recovery
Vinyl Chloride	97
Trichloroethene	102
Tetrachloroethene	119
cis-1.2-Dichloroethene	114

,		Method	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	101	70-130	
Toluene-d8	100	70-130	
4-Bromofluorobenzene	100	70-130	



Client Sample ID: LCSD Lab ID#: 1306106-06AA

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	c060705sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/7/13 10:50 AM

Compound	%Recovery
Vinyl Chloride	93
Trichloroethene	100
Tetrachloroethene	117
cis-1.2-Dichloroethene	110

		wethod
Surrogates	%Recovery	Limits
1,2-Dichloroethane-d4	100	70-130
Toluene-d8	99	70-130
4-Bromofluorobenzene	100	70-130



CHAIN-OF-CUSTODY RECORD

Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

16) 985-1000 FAX (916) 985-1020

Project Manager <u>Proc. Rockers</u> Collected by: (Print and Sign) <u>Design Brandt & Strue</u>			Project Info:		Turn Around Time:	Lab Use Press	<i>Only</i> urized by	
Company Landou Associates Email	· · · · · · · · · · · · · · · · · · ·	F	P.O.# <u>583-07</u> -0	050.053	☐ Normal	Date:		
Address 120 104 AUT South City Edwards		F	Project # <u> </u>	oto.057	Rush	Press	urization	Gas:
Phone (115)718-5907 Fax	_ Otto 21p	li li	Project Name	wns Supply	Same Day specify		N ₂ H	e
		Dat	e Time			ter Pres	sure/Va	cuum
Lab I.D. Field Sample I.D. (Location)	Can #	of Colle	ction of Collection			Final	Receipt	Final (psi)
7010 Palotine - Rosement: 060513	33900	4.5.	13 727	76. F/76 E/6 DCE/VC	- 30	·10.1		
William 7014 Falatine - Busement: 160513	22503	à,	7-36	-to-order	-30	-7,7		
SESSEE 202 Nasth Bosemat : 060513	31140	- Distribution of	904	Short day a support	-30	-8.1.		
andrea Mathagae		\dagger{\psi}		V	2. 100			
					1			
		ij				À		
		v						
					0.5			
Relinquished by: (signature) Date/Time 1356 Relinquished by: (signature) Date/Time Relinquished by: (signature) Date/Time	Received by: (signat	HL W ure) Da ure) Da	tte/Time OH 3 1755 tte/Time	23 hours	14 Palatine Buss			3 031/3
Lab Shipper Name Air Bill #		emp (°C)	Conditio	n Gustody Se	als Intact?	Work (Order#	
Use Ted S	<u>N</u>	<u> </u>	gos	Yes No	None		3061	<u> </u>



6/14/2013 Mr. Piper Roelen Landau Associates, Inc. 130 2nd Avenue South

Edmonds WA 98020

Project Name: Heaven Supply Project #: 583002.050.057 Workorder #: 1306204

Dear Mr. Piper Roelen

The following report includes the data for the above referenced project for sample(s) received on 6/13/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 SIM are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner
Project Manager

July Butte



WORK ORDER #: 1306204

Work Order Summary

CLIENT: Mr. Piper Roelen BILL TO: Mr. Piper Roelen

Landau Associates, Inc.Landau Associates, Inc.130 2nd Avenue South130 2nd Avenue SouthEdmonds, WA 98020Edmonds, WA 98020

PHONE: 800-552-5957 **P.O.** # 583002.050.057

FAX: 425-778-6409 **PROJECT** # 583002.050.057 Heaven Supply

DATE RECEIVED: 06/13/2013 **CONTACT:** Kelly Buettner **DATE COMPLETED:** 06/14/2013

			RECEIPT	FINAL
FRACTION #	NAME	<u>TEST</u>	VAC./PRES.	PRESSURE
01A	- Basement:061213	Modified TO-15 SIM	5.4 "Hg	5 psi
02A	Heavens Supply - OD:061213	Modified TO-15 SIM	5.4 "Hg	5 psi
03A	Privacy - Basement:061213	Modified TO-15 SIM	7.6 "Hg	5 psi
04A	Lab Blank	Modified TO-15 SIM	NA	NA
05A	CCV	Modified TO-15 SIM	NA	NA
06A	LCS	Modified TO-15 SIM	NA	NA
06AA	LCSD	Modified TO-15 SIM	NA	NA

CERTIFIED BY: DATE: 06/14/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935

Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)

Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013. Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc. 180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 956:







LABORATORY NARRATIVE Modified TO-15 SIM Landau Associates, Inc. Workorder# 1306204

Three 6 Liter Summa Canister (SIM Certified) samples were received on June 13, 2013. The laboratory performed analysis via modified EPA Method TO-15 using GC/MS in the SIM acquisition mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

Requirement	TO-15	ATL Modifications
ICAL %RSD acceptance criteria	<pre><!--=30% RSD with 2 compounds allowed out to < 40% RSD</pre--></pre>	Project specific; default criteria is =30% RSD with 10% of compounds allowed out to < 40% RSD</td
Daily Calibration	+- 30% Difference	Project specific; default criteria is = 30% Difference with 10% of compounds allowed out up to </=40%.; flag and narrate outliers</td
Blank and standards	Zero air	Nitrogen
Method Detection Limit	Follow 40CFR Pt.136 App. B	The MDL met all relevant requirements in Method TO-15 (statistical MDL less than the LOQ). The concentration of the spiked replicate may have exceeded 10X the calculated MDL in some cases

Receiving Notes

The Summa canister for sample Privacy FOIA - Basement:061213 was leaking upon arrival. The client was notified and the analysis proceeded. Reported analyte concentrations are considered to be estimated.

Analytical Notes

There were no analytical discrepancies.

Definition of Data Qualifying Flags

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

- B Compound present in laboratory blank greater than reporting limit (background subtraction no performed).
 - J Estimated value.
 - E Exceeds instrument calibration range.
 - S Saturated peak.
 - Q Exceeds quality control limits.
- U Compound analyzed for but not detected above the reporting limit, LOD, or MDL value. See data page for project specific U-flag definition.



- UJ- Non-detected compound associated with low bias in the CCV
- N The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:

- a-File was requantified
- b-File was quantified by a second column and detector
- r1-File was requantified for the purpose of reissue



Summary of Detected Compounds MODIFIED EPA METHOD TO-15 GC/MS SIM

Client Sample ID: Privacy - Basement:061213

Lab ID#: 1306204-01A

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Trichloroethene	0.0049	0.0071	0.026	0.038

Client Sample ID: Heavens Supply - OD:061213

Lab ID#: 1306204-02A

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)	
Trichloroethene	0.0049	0.0073	0.026	0.039	

Client Sample ID: 202 N 70th - Basement:061213

Lab ID#: 1306204-03A

	Rpt. Limit	Amount	Rpt. Limit	Amount	
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)	
Trichloroethene	0.0054	0.0074	0.029	0.040	



Client Sample ID: Privacy - Basement:061213

Lab ID#: 1306204-01A

	MODIFIED ETA MET	HOD TO-13 GGWB BI	441		
File Name: Dil. Factor:	a061307sim 1.63	Date of Collection: 6/12/13 7:25:00 AM Date of Analysis: 6/13/13 12:23 PM			
Compound	Rɒt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)	
Vinyl Chloride	0.016	Not Detected	0.042	Not Detected	
Trichloroethene	0.0049	0.0071	0.026	0.038	
Tetrachloroethene	0.033	Not Detected	0.22	Not Detected	
cis-1,2-Dichloroethene	0.033	Not Detected	0.13	Not Detected	
Container Type: 6 Liter Sumn	na Canister (SIM Certified)				
Surrogates		%Recovery		Method Limits	
1,2-Dichloroethane-d4		112		70-130	
Toluene-d8		99		70-130	
4-Bromofluorobenzene		102		70-130	



Client Sample ID: Heavens Supply - OD:061213

Lab ID#: 1306204-02A

File Name: Dil. Factor:	a061308sim 1.63	Date of Collection: 6/12/13 8:53:00 AM Date of Analysis: 6/13/13 01:13 PM			
Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)	
Vinyl Chloride	0.016	Not Detected	0.042	Not Detected	
Trichloroethene	0.0049	0.0073	0.026	0.039	
Tetrachloroethene	0.033	Not Detected	0.22	Not Detected	
cis-1,2-Dichloroethene	0.033	Not Detected	0.13	Not Detected	
Container Type: 6 Liter Sum	ma Canister (SIM Certified)			Method	
Surrogates		%Recovery		Limits	
1,2-Dichloroethane-d4		111		70-130	
Toluene-d8		98		70-130	
4-Bromofluorobenzene		95		70-130	



Client Sample ID: Privacy - Basement:061213

Lab ID#: 1306204-03A

File Name: Dil. Factor:	a061309sim 1.79	Date of Collection: 6/12/13 9:03:00 AM Date of Analysis: 6/13/13 02:03 PM			
Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)	
Vinyl Chloride	0.018	Not Detected	0.046	Not Detected	
Trichloroethene	0.0054	0.0074	0.029	0.040	
Tetrachloroethene	0.036	Not Detected	0.24	Not Detected	
cis-1,2-Dichloroethene	0.036	Not Detected	0.14	Not Detected	
Container Type: 6 Liter Sum	ma Canister (SIM Certified)			Method	
Surrogates		%Recovery		Limits	
1,2-Dichloroethane-d4		112		70-130	
Toluene-d8		98		70-130	
4-Bromofluorobenzene		95		70-130	



Client Sample ID: Lab Blank Lab ID#: 1306204-04A

File Name: Dil. Factor:	a061306asim 1.00	Date of Collection: NA Date of Analysis: 6/13/13 10:45 AM						
Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)				
Vinyl Chloride	0.010	Not Detected	0.026	Not Detected				
Trichloroethene	0.0030	Not Detected	0.016	Not Detected				
Tetrachloroethene	0.020	Not Detected	0.14	Not Detected				
cis-1,2-Dichloroethene	0.020	Not Detected	0.079	Not Detected				
Container Type: NA - Not App	olicable							
				Method				
Surrogates		%Recovery		Limits				
1,2-Dichloroethane-d4		107		70-130				
Toluene-d8		99		70-130				
4-Bromofluorobenzene		98		70-130				



Client Sample ID: CCV Lab ID#: 1306204-05A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	a061302sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/13/13 06:59 AM

Compound	%Recovery
Vinyl Chloride	112
Trichloroethene	105
Tetrachloroethene	111
cis-1,2-Dichloroethene	108

21 bb		Method Limits		
Surrogates	%Recovery			
1,2-Dichloroethane-d4	97	70-130		
Toluene-d8	98	70-130		
4-Bromofluorobenzene	101	70-130		



Client Sample ID: LCS Lab ID#: 1306204-06A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	a061303sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/13/13 07:54 AM

Compound	%Recovery
Vinyl Chloride	98
Trichloroethene	94
Tetrachloroethene	96
cis-1,2-Dichloroethene	96

21		Method Limits		
Surrogates	%Recovery			
1,2-Dichloroethane-d4	98	70-130		
Toluene-d8	98	70-130		
4-Bromofluorobenzene	101	70-130		




Client Sample ID: LCSD Lab ID#: 1306204-06AA

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	a061304sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/13/13 08:41 AM

Compound	%Recovery
Vinyl Chloride	97
Trichloroethene	92
Tetrachloroethene	95
cis-1,2-Dichloroethene	96

		Method Limits		
Surrogates	%Recovery			
1,2-Dichloroethane-d4	100	70-130		
Toluene-d8	99	70-130		
4-Bromofluorobenzene	99	70-130		



Service Corresponding to the acceptable and acceptable and adjacent acceptable and the ECR RAYRE BOAD (1915) is a content of the acceptable and acceptable a

nazi si Webi dayi biri	- Ring - Benton Hannon - Encard - Econold - Line Hannon - Line - Honor		:0 1	ritanto: 39090-03		•	California Pressportation Order & Mysical
Autoriana Africa V	r Arellie de Orthodoxone i Stor Orthodoxonia		: 5	us skijo. :Kama <u>dus</u> s			∰assinizato dasc வி. புத்தேரில் via ப
; · · · · · · · · · · · · · · · · · · ·	Reid Sumple 10 (Sociation)	Canit				ated Program	First Hubble 1- 18
	Nikolov Amerika (1844) 1990 - Berrig Liller (1844) 1990 - Berrig Liller (1844)	95 5 1 3 1 4 2 3 1 7 4 4	\$ 12 35	903 903 903	TOTAL STREET		- 6 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	· <u></u> .				'		
							}
(Cornel to a by Pile law that by	ngwisia district	Produced by Asia Sa Produced by Asia Sa	are) - Discentio EA) - Osciolar	ing)	Notes.		, , , , , , , , , , , , , , , , , , ,
Sein See	See Name		មាន(ជា		Cartony for		was order afform



Semple Transportation Notice

Polinguarang digitation of this socialised features distribute distribution and supplied by form the policy features of the policy form of the policy features and optimized optimized of the policy features and optimized o any shift. All Thomas I croted declarates so likelidy with respect to the collection intunating or enforcing or those exception. Relicipationing agree one into indicases agreement to be a personal, disferid. sold indispertly Air Tables can ited against any ordina demand or archite, of any kind, related to it a correction hamfling, by star party of complete. In OCI incompressions (809), 457,4632.

FO\50M; CA 85538-4719 (916) 965-1000 FAX (216) 985-1020

Page 3 of ____

Project Manager <u>Bigs 5 Buzil (s.</u> Censeted by: 6 exists sign) <u>United f</u>			[Projec	l Info:		·	Tism.	Around Mer	Porse	ČENSTĖ uszaki be	 .
Company Lindon dies and				20. ₩.	Sander Braille	<u> 43</u>	-	Q _N c	ormal	hi Ljúglei		
Address, <u>Gold and Grazer</u> , City ,		≥ (a) √ 2(p) (_\$)	<u> </u>	Ercpect	المتنازة لأثاثا	£<2 0.12.		海出		Fress	eriz geloni	Gaus:
Phone (1994-1995) 17/34				Project	Namo <u>ji</u>	and the Sale	<u>.</u>	Carra s	₩. 940		$N_{2} = id$	l e
Lab LD. Field Sample LD. (Location)	Can #	Do et Code		Time of Collection	Analysa	s Seques	ied			s-um/Va: Repeipt	
MA Assorted Services	20226	1349	†; <u>-1-14</u> -	·		7(3) 1/1/07 1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/	77/2011 15/2011	∸ ∙	-15 % ±	· k		(pul
1981 22 - 32 Supply CD	00 1, <u>210</u> 64:016)34409 <u> </u>			<u> </u>	<u>!</u>	{ 			<u>~4.2.</u> ~(*)		:; :;
								··.	·			
			· · · · · · · · · · · · · · · · · · ·									
		· - ·;				<u> </u> :	, 	·				
	-· · ·									· :		
Polino Pohed by Polgoguse) - Octo Intro 	- 3 - 12 Hacet - 3 - 12 V.M P∄cet	vad bu sagnat (113.)20 ved by, (signat	KALY	hi i	<u> 14/0/ib</u>		ofes:		 .		·	
fletinops (anny (agnature) - Data Time	Pacet	vee by. (signatu	ura; Dy	ale/ imp								3 (
Lein Shipper Name: 300	Alf BR. #			· · · · · · ·	···		istody Sea					
poly texts			<u>ν</u> γ	. <u>l</u>	<u>-3007</u> 1	Q	es No) bior	<u>16 </u> _	قـــــــــــــــــــــــــــــــــــــ	<u>138</u> 25	4



6/26/2013

Mr. Piper Roelen Landau Associates, Inc. 130 2nd Avenue South

Edmonds WA 98020

Project Name: Heavens Supply Project #: 583002.050.057 Workorder #: 1306364

Dear Mr. Piper Roelen

The following report includes the data for the above referenced project for sample(s) received on 6/21/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 SIM are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Elly Butte



WORK ORDER #: 1306364

Work Order Summary

CLIENT: Mr. Piper Roelen BILL TO: Mr. Piper Roelen

> Landau Associates, Inc. Landau Associates, Inc. 130 2nd Avenue South 130 2nd Avenue South Edmonds, WA 98020 Edmonds, WA 98020

PHONE: 800-552-5957 P.O. # 583002.050.057

FAX: 425-778-6409 PROJECT # 583002.050.057 Heavens Supply

DATE RECEIVED: 06/21/2013 **CONTACT:** Kelly Buettner **DATE COMPLETED:** 06/26/2013

			RECEIPT	FINAL
FRACTION #	<u>NAME</u>	<u>TEST</u>	VAC./PRES.	PRESSURE
01A	-Basement:061913	Modified TO-15 SIM	6.5 "Hg	4.8 psi
02A	Privacy -Basement:061913	Modified TO-15 SIM	7.1 "Hg	4.6 psi
03A	Privacy FOIA -Basement:061913	Modified TO-15 SIM	4.9 "Hg	5.1 psi
04A	Lab Blank	Modified TO-15 SIM	NA	NA
05A	CCV	Modified TO-15 SIM	NA	NA
06A	LCS	Modified TO-15 SIM	NA	NA
06AA	LCSD	Modified TO-15 SIM	NA	NA

	10	ide Tayer		
CERTIFIED BY:			DATE: $\frac{06/26/13}{}$	

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935

Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program) Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.

Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards







LABORATORY NARRATIVE Modified TO-15 SIM Landau Associates, Inc. Workorder# 1306364

Three 6 Liter Summa Canister (SIM Certified) samples were received on June 21, 2013. The laboratory performed analysis via modified EPA Method TO-15 using GC/MS in the SIM acquisition mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

Requirement	TO-15	ATL Modifications
ICAL %RSD acceptance criteria	<pre><!--=30% RSD with 2 compounds allowed out to < 40% RSD</pre--></pre>	Project specific; default criteria is =30% RSD with 10% of compounds allowed out to < 40% RSD</td
Daily Calibration	+- 30% Difference	Project specific; default criteria is = 30% Difference with 10% of compounds allowed out up to </=40%.; flag and narrate outliers</td
Blank and standards	Zero air	Nitrogen
Method Detection Limit	Follow 40CFR Pt.136 App. B	The MDL met all relevant requirements in Method TO-15 (statistical MDL less than the LOQ). The concentration of the spiked replicate may have exceeded 10X the calculated MDL in some cases

Receiving Notes

There were no receiving discrepancies.

Analytical Notes

There were no analytical discrepancies.

Definition of Data Qualifying Flags

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

- B Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
 - J Estimated value.
 - E Exceeds instrument calibration range.
 - S Saturated peak.
 - Q Exceeds quality control limits.
- U Compound analyzed for but not detected above the reporting limit, LOD, or MDL value. See data page for project specific U-flag definition.
 - UJ- Non-detected compound associated with low bias in the CCV



N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:

- a-File was requantified
- b-File was quantified by a second column and detector
- r1-File was requantified for the purpose of reissue



Summary of Detected Compounds MODIFIED EPA METHOD TO-15 GC/MS SIM

Client Sample ID: Privacy -Basement:061913

Lab ID#: 1306364-01A
No Detections Were Found.

Client Sample ID: Privacy -Basement:061913

Lab ID#: 1306364-02A
No Detections Were Found.

Client Sample ID: Privacy FOIA -Basement:061913

Lab ID#: 1306364-03A

Compound	Rpt. Limit (ppbv)	Amount (ppbv)	Rpt. Limit (ug/m3)	Amount (ug/m3)
Trichloroethene	0.0048	0.010	0.026	0.055
Tetrachloroethene	0.032	0.038	0.22	0.26



Client Sample ID: Privacy -Basement:061913

Lab ID#: 1306364-01A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	a062407sim	Date of Collection: 6/19/13 7:28:00 AM
Dil. Factor:	1.70	Date of Analysis: 6/24/13 04:20 PM

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.017	Not Detected	0.043	Not Detected
Trichloroethene	0.0051	Not Detected	0.027	Not Detected
Tetrachloroethene	0.034	Not Detected	0.23	Not Detected
cis-1,2-Dichloroethene	0.034	Not Detected	0.13	Not Detected

		Wethod	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	118	70-130	
Toluene-d8	96	70-130	
4-Bromofluorobenzene	93	70-130	



Client Sample ID: Privacy -Basement:061913

Lab ID#: 1306364-02A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	a062408sim	Date of Collection: 6/19/13 9:02:00 AM
Dil. Factor:	1.72	Date of Analysis: 6/24/13 05:13 PM

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.017	Not Detected	0.044	Not Detected
Trichloroethene	0.0052	Not Detected	0.028	Not Detected
Tetrachloroethene	0.034	Not Detected	0.23	Not Detected
cis-1,2-Dichloroethene	0.034	Not Detected	0.14	Not Detected

•	2/2	Method	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	117	70-130	
Toluene-d8	97	70-130	
4-Bromofluorobenzene	96	70-130	



Client Sample ID: Privacy FOIA -Basement:061913

Lab ID#: 1306364-03A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	a062409sim	Date of Collection: 6/19/13 5:33:00 PM
Dil. Factor:	1.61	Date of Analysis: 6/24/13 06:04 PM

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.016	Not Detected	0.041	Not Detected
Trichloroethene	0.0048	0.010	0.026	0.055
Tetrachloroethene	0.032	0.038	0.22	0.26
cis-1,2-Dichloroethene	0.032	Not Detected	0.13	Not Detected

		wethod	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	120	70-130	
Toluene-d8	96	70-130	
4-Bromofluorobenzene	95	70-130	



Client Sample ID: Lab Blank Lab ID#: 1306364-04A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	a062406asim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/24/13 02:35 PM

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.010	Not Detected	0.026	Not Detected
Trichloroethene	0.0030	Not Detected	0.016	Not Detected
Tetrachloroethene	0.020	Not Detected	0.14	Not Detected
cis-1,2-Dichloroethene	0.020	Not Detected	0.079	Not Detected

		Method	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	119	70-130	
Toluene-d8	98	70-130	
4-Bromofluorobenzene	96	70-130	



Client Sample ID: CCV Lab ID#: 1306364-05A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	a062402sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/24/13 10:14 AM

Compound	%Recovery
Vinyl Chloride	120
Trichloroethene	100
Tetrachloroethene	105
cis-1,2-Dichloroethene	100

		wethod	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	103	70-130	
Toluene-d8	97	70-130	
4-Bromofluorobenzene	101	70-130	



Client Sample ID: LCS Lab ID#: 1306364-06A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	a062403sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/24/13 11:05 AM

Compound	%Recovery
Vinyl Chloride	96
Trichloroethene	88
Tetrachloroethene	89
cis-1.2-Dichloroethene	91

		Wethod	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	110	70-130	
Toluene-d8	100	70-130	
4-Bromofluorobenzene	100	70-130	



Client Sample ID: LCSD Lab ID#: 1306364-06AA

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	a062404sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/24/13 11:52 AM

Compound	%Recovery
Vinyl Chloride	93
Trichloroethene	87
Tetrachloroethene	88
cis-1.2-Dichloroethene	91

		wethod		
Surrogates	%Recovery	Limits		
1,2-Dichloroethane-d4	110	70-130		
Toluene-d8	101	70-130		
4-Bromofluorobenzene	99	70-130		



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

•	,			
Page	Î	of	Î	

Project Manager Piper Roelen			Project Info:				Turn Around		Lab Use Only		
Collected by: (Print and Sign) Devan Brandt & Dylan Frozer			DO # Caracia aca			Time:		Pressurized by:			
Company LANDAU ASSOCIATES Email				P.O. # <u>5g3007 @50. @87</u>			Normal		Date:		
Address 130 2nd AUE South City Edmands	30 2nd AUF South City Edmonds State WA Zip 98020			Project # <u>583.002.080.057</u>			Rush		Pressurization Gas:		
Phone (425) 778 - 0907 Fax		8	Proiect	Name Heave	ns Suroly	3 I	A U pecity		N ₂ H	α	
			CO CONTRACTOR NO.			S)	DANGER EXCEPTION OF THE PROPERTY OF THE PROPER	lau Dea	sure/Vac	***************************************	
Lab I.D. Field Sample I.D. (Location)	Can #	Da of Colle		Time of Collection	Analyses Reques	ted	Initial	ier Pres Final	Receipt		
	7.70				PUE/TUE/UDLE/VE		milia		rieceipi	Final (psi)	
Ol P 7010 Palutine - Rosement: 061913	33982	6-19		728	TO-15 SIM		-30	-8			
SLA 202 N 70th - Busement: 061913	347-39	6-19	;	902	PLEHUILDCE/VC TO-15 SIM		-79.6	7.7			
04/X 7013 GRENWOOD - BASEMENT: 061913	25270	6/19/1	13	1733	PCE/TUE/LDCE/VC TD-15 SIM		-28,0	-5,5		The Control of the Co	
								·			
]				
			-								
							1				
								*			
Relinquished by: (signature) Date/Time	Received by: (signati	ure) Da	ate/Tim	e	Notes:		e a marie a ma				
m 6/20/13 / 0900	TO A	TC	6.2	2613 09	229						
Relinquished by: (signature) Date/Time	Received by: (signati	ure) Da	ate/Tim	e							
Relinquished by: (signature) Date/Time	Received by: (signate	ure) Da	ate/Time	₽						No.	
Lab Shipper Name Air Bill #	16	emp (°C	<u> </u>	Condition					Order#	4/-	
Use College		N V		(1) 00	Yes No	No	ne	<u>[</u>	30031	94	
		WWW.									



7/3/2013

Mr. Piper Roelen Landau Associates, Inc. 130 2nd Avenue South

Edmonds WA 98020

Project Name: Heaven Supply Project #: 583002.050.057 Workorder #: 1306507

Dear Mr. Piper Roelen

The following report includes the data for the above referenced project for sample(s) received on 6/28/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 SIM are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Elly Butte



WORK ORDER #: 1306507

Work Order Summary

CLIENT: Mr. Piper Roelen BILL TO: Mr. Piper Roelen

Landau Associates, Inc.
Landau Associates, Inc.
130 2nd Avenue South
Edmonds, WA 98020
Landau Associates, Inc.
130 2nd Avenue South
Edmonds, WA 98020

PHONE: 800-552-5957 **P.O.** # 583002.050.057

FAX: 425-778-6409 **PROJECT** # 583002.050.057 Heaven Supply

DATE RECEIVED: 06/28/2013 **CONTACT:** Kelly Buettner 07/03/2013

			RECEIPT	FINAL
FRACTION #	NAME	<u>TEST</u>	VAC./PRES.	PRESSURE
01A	- Basement:062613	Modified TO-15 SIM	0.5 psi	4.8 psi
02A	- Basement:062613	Modified TO-15 SIM	5.3 "Hg	5.3 psi
03A	Privacy FOIA - Basement:062613	Modified TO-15 SIM	6.7 "Hg	5 psi
04A	Lab Blank	Modified TO-15 SIM	NA	NA
05A	CCV	Modified TO-15 SIM	NA	NA
06A	LCS	Modified TO-15 SIM	NA	NA
06AA	LCSD	Modified TO-15 SIM	NA	NA

	fleide payer	
CERTIFIED BY:	0 0	DATE: $\frac{07/03/13}{}$

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935

Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program) Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.

Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.





LABORATORY NARRATIVE Modified TO-15 SIM Landau Associates, Inc. Workorder# 1306507

Three 6 Liter Summa Canister (SIM Certified) samples were received on June 28, 2013. The laboratory performed analysis via modified EPA Method TO-15 using GC/MS in the SIM acquisition mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

Requirement	TO-15	ATL Modifications
ICAL %RSD acceptance criteria	<pre><!--=30% RSD with 2 compounds allowed out to < 40% RSD</pre--></pre>	Project specific; default criteria is =30% RSD with 10% of compounds allowed out to < 40% RSD</td
Daily Calibration	+- 30% Difference	Project specific; default criteria is = 30% Difference with 10% of compounds allowed out up to </=40%.; flag and narrate outliers</td
Blank and standards	Zero air	Nitrogen
Method Detection Limit	Follow 40CFR Pt.136 App. B	The MDL met all relevant requirements in Method TO-15 (statistical MDL less than the LOQ). The concentration of the spiked replicate may have exceeded 10X the calculated MDL in some cases

Receiving Notes

Despite the use of flow controller for sample collection, the final canister vacuum for sample Priva

- Basement:062613 was measured at ambient pressure in the field. These ambient pressure reading was confirmed by the laboratory upon sample receipt.

Analytical Notes

There were no analytical discrepancies.

Definition of Data Qualifying Flags

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

- B Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
 - J Estimated value.
 - E Exceeds instrument calibration range.
 - S Saturated peak.



- Q Exceeds quality control limits.
- U Compound analyzed for but not detected above the reporting limit, LOD, or MDL value. See data page for project specific U-flag definition.
 - UJ- Non-detected compound associated with low bias in the CCV
 - N The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:

- a-File was requantified
- b-File was quantified by a second column and detector
- r1-File was requantified for the purpose of reissue



Summary of Detected Compounds MODIFIED EPA METHOD TO-15 GC/MS SIM

Client Sample ID: Privacy - Basement:062613

Lab ID#: 1306507-01A

	Rpt. Limit	Amount	Rpt. Limit	Amount	
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)	
Trichloroethene	0.0038	0.0048	0.021	0.026	

Client Sample ID: Privacy - Basement:062613

Lab ID#: 1306507-02A

 Compound
 Rpt. Limit (ppbv)
 Amount (ppbv)
 Rpt. Limit (ug/m3)
 Amount (ug/m3)

 Trichloroethene
 0.0050
 0.015
 0.027
 0.080

Client Sample ID: Privacy FOIA - Basement:062613

Lab ID#: 1306507-03A

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Trichloroethene	0.0052	0.010	0.028	0.054
Tetrachloroethene	0.035	0.037	0.23	0.25



Client Sample ID: Privacy - Basement:062613

Lab ID#: 1306507-01A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	v062914sim	Date of Collection: 6/26/13 7:26:00 AM
Dil. Factor:	1.28	Date of Analysis: 6/30/13 12:14 PM

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.013	Not Detected	0.033	Not Detected
Trichloroethene	0.0038	0.0048	0.021	0.026
Tetrachloroethene	0.026	Not Detected	0.17	Not Detected
cis-1,2-Dichloroethene	0.026	Not Detected	0.10	Not Detected

Container Type: 6 Liter Summa Canister (SIM Certified)

		wethod	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	103	70-130	
Toluene-d8	96	70-130	
4-Bromofluorobenzene	104	70-130	



Client Sample ID: Privacy - Basement:062613

Lab ID#: 1306507-02A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	v062915sim	Date of Collection: 6/26/13 7:32:00 AM
Dil. Factor:	1.65	Date of Analysis: 6/30/13 12:49 PM

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.016	Not Detected	0.042	Not Detected
Trichloroethene	0.0050	0.015	0.027	0.080
Tetrachloroethene	0.033	Not Detected	0.22	Not Detected
cis-1,2-Dichloroethene	0.033	Not Detected	0.13	Not Detected

Container Type: 6 Liter Summa Canister (SIM Certified)

		Wetnoa	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	98	70-130	
Toluene-d8	95	70-130	
4-Bromofluorobenzene	107	70-130	



Client Sample ID: Privacy FOIA - Basement:062613

Lab ID#: 1306507-03A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	v062916sim	Date of Collection: 6/26/13 5:33:00 PM
Dil. Factor:	1.73	Date of Analysis: 6/30/13 01:25 PM

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.017	Not Detected	0.044	Not Detected
Trichloroethene	0.0052	0.010	0.028	0.054
Tetrachloroethene	0.035	0.037	0.23	0.25
cis-1,2-Dichloroethene	0.035	Not Detected	0.14	Not Detected

Container Type: 6 Liter Summa Canister (SIM Certified)

		Method	
Surrogates	%Recovery	Limits	
1,2-Dichloroethane-d4	98	70-130	
Toluene-d8	96	70-130	
4-Bromofluorobenzene	104	70-130	



Client Sample ID: Lab Blank Lab ID#: 1306507-04A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	v062907sima	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/29/13 08:56 PM
	B(1.11)	Amount But Unit Amount

	Rpt. Limit	Amount	Rpt. Limit	Amount
Compound	(ppbv)	(ppbv)	(ug/m3)	(ug/m3)
Vinyl Chloride	0.010	Not Detected	0.026	Not Detected
Trichloroethene	0.0030	Not Detected	0.016	Not Detected
Tetrachloroethene	0.020	Not Detected	0.14	Not Detected
cis-1,2-Dichloroethene	0.0030 0.020		0.079	Not Detected

		wethod
Surrogates	%Recovery	Limits
1,2-Dichloroethane-d4	99	70-130
Toluene-d8	96	70-130
4-Bromofluorobenzene	108	70-130



Client Sample ID: CCV Lab ID#: 1306507-05A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	v062902sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/29/13 04:02 PM

Compound	%Recovery
Vinyl Chloride	80
Trichloroethene	104
Tetrachloroethene	104
cis-1,2-Dichloroethene	86

		wethod
Surrogates	%Recovery	Limits
1,2-Dichloroethane-d4	99	70-130
Toluene-d8	97	70-130
4-Bromofluorobenzene	111	70-130



Client Sample ID: LCS Lab ID#: 1306507-06A

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	v062903sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/29/13 04:47 PM

Compound	%Recovery
Vinyl Chloride	74
Trichloroethene	100
Tetrachloroethene	96
cis-1.2-Dichloroethene	84

		Method			
Surrogates	%Recovery	Limits			
1,2-Dichloroethane-d4	99	70-130			
Toluene-d8	97	70-130			
4-Bromofluorobenzene	110	70-130			



Client Sample ID: LCSD Lab ID#: 1306507-06AA

MODIFIED EPA METHOD TO-15 GC/MS SIM

File Name:	v062904sim	Date of Collection: NA
Dil. Factor:	1.00	Date of Analysis: 6/29/13 05:49 PM

Compound	%Recovery
Vinyl Chloride	79
Trichloroethene	101
Tetrachloroethene	98
cis-1.2-Dichloroethene	85

		Method			
Surrogates	%Recovery	Limits			
1,2-Dichloroethane-d4	99	70-130			
Toluene-d8	97	70-130			
4-Bromofluorobenzene	110	70-130			



CHAIN-OF-CUSTODY RECORD

Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with 180 BLUE RAVINE ROAD, SUITE B all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples, D.O.T. Hotline (800) 467-4922

FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

AND EST ASSESSED.	collec	dtion, handl	ling, or shipping	agamsı of sampi	es. D.O.T.	i, demand, or act . Hotline (800) 46	iion, of any kind 37-4922	, related to the	ne 🔩 🛒	faller from the second	Pa	age <u> </u>	of
Project Man	ager Rose Toda				Proje	ct Info:	Andreas and the second	essentia de la constitución de la c		Around	Lab Use		V84110000711/2000001/20
Collected by	: (Print and Sign) Description	A Shaw			DO # # Sam . m sa			Time:		Pressurized by:			
Company 🛴	andan Arsonalis Email _					P.O. #_6\\\2_1\\2_1\\0000\\0000\\0000\\0000\\0000\\0000\\0000			Normal Normal		Date:		
Address <u> </u>	D Z 40E Savis City Fifewards	State	- <u>[]</u> Zip (<u>_⊠.</u>	22	Project	l# <u>593007</u>	(* m + 0) *	· · · · · · · · · · · · · · · · · · ·	□ Ru		Press	urization	Gas:
Phone <u>// 25</u>	Fax				Project	Name	ms Suppl	: 1	1000	pecify		N₂ H	le
			-	1	ate	Time			<i>700-211-2</i> 40,000,000,000	Canist	ier Pre:	ssure/Va	cuum
Lab I.D.	Field Sample I.D. (Location)		Can #	of Co	llection	of Collection	Analyse	es Reques	sted	Initial	Final	Receipt	Final (psi)
DIA 7	4010 Palating - Busement .: (-)	13	05412	06-2	635	716	PUE/TAE/8 DX	15/VZ 15 5 T	.A ~	J. J. J.	·		
	014 Pale inc - Sugment 0626.		4113	- Constant		732	1 1	1	100	4 A	5.7		
1 3 - 1 1	013 GETTERNAND & BEEN COL DE ZON		34201	J		1733				-79			1
									-	5.00			
		·											
								· .					
			<u> </u>										
					-								
	4.		- rea						···				
Delan.	by: (signature) Date/Time Language Garage Page 13 95 by: (signature) Date/Time	Receive	ved by: (signatived by; (signatived by; (signatived)	dre) [ate/Tim		11(S No	otes:	Trickers Indicates and Indicat		naman tirrito est nomen an estad	RIOVIDANA massagyylikini kung ngah	
Water											\$3		
The supposed of the supposed district of the s	by: (signature) Date/Time	Receiv	ved by: (signati	ure) [ate/Time	€ martinger	V 4 6 - 14	$\varphi_{i}(u) = x_{i}(\mathcal{D}_{2})(u)$					Olisadormatica (wals)
In CIV	Shipper Name Air Bl	l #	Те	mp (°0	7)	Condition	\	ustody Sea	als Inta	ct?	Work C	Order #	
Use Only	flator I			NA	-	1000		es No	Noi	ne	1	30650	7
	V · ·		e qui.				A. A			·,::::::::::::::::::::::::::::::::::		5	- Instantia

Laboratory Analytical Reports – Vapor (Soil and ERH SVE System)



3600 Fremont Ave. N.
Seattle, WA 98103
T: (206) 352-3790
F: (206) 352-7178
info@fremontanalytical.com

Landau Associates

Piper Roelen 130 2nd Ave South Edmonds, Washington 98020

RE: Heavens Supply Lab ID: 1306021

June 05, 2013

Attention Piper Roelen:

Fremont Analytical, Inc. received 8 sample(s) on 6/4/2013 for the analyses presented in the following report.

Volatile Organic Compounds by EPA Method TO-15

This report consists of the following:

- Case Narrative
- Analytical Results
- Applicable Quality Control Summary Reports
- Chain of Custody

All analyses were performed consistent with the Quality Assurance program of Fremont Analytical, Inc. Please contact the laboratory if you should have any questions about the results.

Thank you for using Fremont Analytical.

Sincerely,

MGR

Michael Dee

Sr. Chemist / Principal

CC: Ann Halvorsen Martin Valeri

Date: 06/05/2013

06/04/2013 6:00 PM

06/04/2013 6:00 PM

06/04/2013 6:00 PM



1306021

SMW-4:060413

SMW-3:060413

VP-1:060413

Work Order Sample Summary CLIENT: Landau Associates

Project: Heavens Supply Lab Order:

1306021-006

1306021-007

1306021-008

Lab Sample ID **Client Sample ID Date/Time Collected Date/Time Received** 1306021-001 VMW-2:060413 06/04/2013 8:14 AM 06/04/2013 6:00 PM 06/04/2013 8:31 AM 06/04/2013 6:00 PM 1306021-002 VMW-3:060413 1306021-003 VMW-4:060413 06/04/2013 9:32 AM 06/04/2013 6:00 PM 1306021-004 SMW-2:060413 06/04/2013 9:52 AM 06/04/2013 6:00 PM 1306021-005 VMW-1:060413 06/04/2013 10:57 AM 06/04/2013 6:00 PM

06/04/2013 11:11 AM

06/04/2013 11:27 AM

06/04/2013 5:52 PM



Case Narrative

WO#: **1306021**Date: **6/5/2013**

CLIENT: Landau Associates
Project: Heavens Supply

I. SAMPLE RECEIPT:

Samples receipt information is recorded on the attached Sample Receipt Checklist.

II. GENERAL REPORTING COMMENTS:

Air samples are reported in ppbv and ug/m3.

The validity of the analytical procedures for which data is reported in this analytical report is determined by the Laboratory Control Sample (LCS) and the Method Blank (MB). The LCS and the MB are processed with the samples to ensure method criteria are achieved throughout the entire analytical process.

III. ANALYSES AND EXCEPTIONS:

Exceptions associated with this report will be footnoted in the analytical results page(s) or the quality control summary page(s) and/or noted below.



WorkOrder: 1306021

Project: Heavens Supply

 Client Sample ID:
 VMW-2:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306021-001A
 Date Received:
 6/4/2013

Analyte	Concer	itration	Reporting Limit Qual		Test Method	Date Ana /Analy	-
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	<0.793	0.200		TO-15	06/05/2013	MD
Tetrachloroethene (PCE)	1.52	10.3	0.300		TO-15	06/05/2013	MD
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/05/2013	MD
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/05/2013	MD
Surr: 4-Bromofluorobenzene	93.3 %Rec		70-130		TO-15	06/05/2013	MD

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306021

Project: Heavens Supply

 Client Sample ID:
 VMW-3:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306021-002A
 Date Received:
 6/4/2013

Sample Type: Tedlar Bag

Analyte	Concer	Reporting Concentration Limit Qual T Me				Date Ana /Analy	-
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	3.60	14.3	0.200		TO-15	06/05/2013	MD
Tetrachloroethene (PCE)	325	2,200	0.300		TO-15	06/05/2013	MD
Trichloroethene (TCE)	17.7	95.2	0.200		TO-15	06/05/2013	MD
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/05/2013	MD
Surr: 4-Bromofluorobenzene	95.6 %Rec		70-130		TO-15	06/05/2013	MD

- E Value above quantitation range
- J Analyte detected below quantitation limits

D Dilution was required

H Holding times for preparation or analysis exceeded

ND Not detected at the Reporting Limit



WorkOrder: 1306021

Project: Heavens Supply

 Client Sample ID:
 VMW-4:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306021-003A
 Date Received:
 6/4/2013

Analyte	Concer	Reporting ntration Limit Qual Test Method					
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	0.520	2.06	0.200		TO-15	06/05/2013	MD
Tetrachloroethene (PCE)	505	3,420	0.300		TO-15	06/05/2013	MD
Trichloroethene (TCE)	5.92	31.8	0.200		TO-15	06/05/2013	MD
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/05/2013	MD
Surr: 4-Bromofluorobenzene	84.7 %Rec		70-130		TO-15	06/05/2013	MD

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306021

Project: Heavens Supply

 Client Sample ID:
 SMW-2:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306021-004A
 Date Received:
 6/4/2013

Analyte	Concer	ntration	Reporting Limit Qual		Test Method	Date Analyze /Analyst	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/05/2013	MD
Tetrachloroethene (PCE)	120	814	0.300		TO-15	06/05/2013	MD
Trichloroethene (TCE)	0.200	1.07	0.200		TO-15	06/05/2013	MD
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/05/2013	MD
Surr: 4-Bromofluorobenzene	92.9 %Rec		70-130		TO-15	06/05/2013	MD

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306021

Project: Heavens Supply

 Client Sample ID:
 VMW-1:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306021-005A
 Date Received:
 6/4/2013

Analyte	Concer	ntration	Reporting Limit			Date Ana /Analy	-
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/05/2013	MD
Tetrachloroethene (PCE)	37.8	256	0.300		TO-15	06/05/2013	MD
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/05/2013	MD
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/05/2013	MD
Surr: 4-Bromofluorobenzene	97.3 %Rec		70-130		TO-15	06/05/2013	MD

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306021

Project: Heavens Supply

 Client Sample ID:
 SMW-4:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306021-006A
 Date Received:
 6/4/2013

Analyte	Concer	Reporting Concentration Limit Qual Test Method				Date Ana /Analy	-
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	<0.793	0.200		TO-15	06/05/2013	MD
Tetrachloroethene (PCE)	71.9	488	0.300		TO-15	06/05/2013	MD
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/05/2013	MD
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/05/2013	MD
Surr: 4-Bromofluorobenzene	97.0 %Rec		70-130		TO-15	06/05/2013	MD

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306021

Project: Heavens Supply

 Client Sample ID:
 SMW-3:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306021-007A
 Date Received:
 6/4/2013

Sample Type: Tedlar Bag

Analyte	Concer	Reporting Concentration Limit Qual Te Met		' ~ ^		Date Ana /Analy	-
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/05/2013	MD
Tetrachloroethene (PCE)	211	1,430	0.300		TO-15	06/05/2013	MD
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/05/2013	MD
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/05/2013	MD
Surr: 4-Bromofluorobenzene	87.2 %Rec		70-130		TO-15	06/05/2013	MD

E Value above quantitation range

J Analyte detected below quantitation limits

D Dilution was required

H Holding times for preparation or analysis exceeded

ND Not detected at the Reporting Limit



WorkOrder: 1306021

Project: Heavens Supply

 Client Sample ID:
 VP-1:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306021-008A
 Date Received:
 6/4/2013

Analyte	Concer	itration	Reporting Limit	~ Aal Tala		Date Ana /Analy	-
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	<0.793	0.200		TO-15	06/05/2013	MD
Tetrachloroethene (PCE)	0.640	4.34	0.300		TO-15	06/05/2013	MD
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/05/2013	MD
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/05/2013	MD
Surr: 4-Bromofluorobenzene	93.8 %Rec		70-130		TO-15	06/05/2013	MD

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit

Date: 6/5/2013



Work Order: 1306021

QC SUMMARY REPORT

CLIENT: Landau Associates

Volatile Organic Compounds by EPA Method TO-15

Sample ID: 1306021-008AREP	SampType: REP			Units: ppbv		Prep Date	6/5/2013	3	RunNo: 876	64	
Client ID: VP-1:060413	Batch ID: R8764					Analysis Date			SeqNo: 175	5810	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	•		RPD Ref Val	%RPD	RPDLimit	Qual
Vinyl chloride	ND	0.200						0	0	30	
cis-1,2-Dichloroethene	ND	0.200						0	0	30	
Trichloroethene (TCE)	ND	0.200						0	0	30	
Tetrachloroethene (PCE)	0.520	0.300						0.6400	20.7	30	
Surr: 4-Bromofluorobenzene	36.8		40.00		92.1	70	130		0		
Sample ID: LCSD-R8764	SampType: LCSD			Units: ppbv		Prep Date	: 6/5/201	3	RunNo: 876	<u> </u>	
Client ID: LCSW02	Batch ID: R8764					Analysis Date	6/5/2013	3	SeqNo: 175	5812	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit I	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Vinyl chloride	4.58	0.200	5.000	0	91.6	70	130	3.590	24.2	30	
cis-1,2-Dichloroethene	4.60	0.200	5.000	0	92.0	70	130	3.700	21.7	30	
Trichloroethene (TCE)	4.78	0.200	5.000	0	95.6	70	130	4.110	15.1	30	
Tetrachloroethene (PCE)	5.89	0.300	5.000	0	118	70	130	4.900	18.4	30	
Surr: 4-Bromofluorobenzene	9.54		10.00		95.4	70	130		0	30	
Sample ID: MB-R8764	SampType: MBLK			Units: ppbv		Prep Date	: 6/5/201	3	RunNo: 876	64	
Client ID: MBLKW	Batch ID: R8764					Analysis Date	6/5/2013	3	SeqNo: 175	5813	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit I	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Vinyl chloride	ND	0.200									
cis-1,2-Dichloroethene	ND	0.200									
Trichloroethene (TCE)	ND	0.200									
Tetrachloroethene (PCE)	ND	0.300									
Surr: 4-Bromofluorobenzene	10.2		10.00		102	70	130				

Qualifiers: B Analyte detected in the associated Method Blank

Holding times for preparation or analysis exceeded

R RPD outside accepted recovery limits

D Dilution was required


Analyte detected below quantitation limits

RL Reporting Limit

E Value above quantitation range

ND Not detected at the Reporting Limit

S Spike recovery outside accepted recovery limits





Work Order: 1306021

QC SUMMARY REPORT

CLIENT: Landau Associates Project: Heavens Supply

Volatile Organic Compounds by EPA Method TO-15

Sample ID: LCS-R8764	SampType: LCS			Units: ppbv		Prep Da	te: 6/5/201	3	RunNo: 876	64	
Client ID: LCSW	Batch ID: R8764					Analysis Date: 6/5/2013			SeqNo: 175		
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Vinyl chloride	3.59	0.200	5.000	0	71.8	70	130				
cis-1,2-Dichloroethene	3.70	0.200	5.000	0	74.0	70	130				
Trichloroethene (TCE)	4.11	0.200	5.000	0	82.2	70	130				
Tetrachloroethene (PCE)	4.90	0.300	5.000	0	98.0	70	130				
Surr: 4-Bromofluorobenzene	9.31		10.00		93.1	70	130				

H Holding times for preparation or analysis exceeded

R RPD outside accepted recovery limits

D Dilution was required

J Analyte detected below quantitation limits

RL Reporting Limit

E Value above quantitation range

ND Not detected at the Reporting Limit

S Spike recovery outside accepted recovery limits



Sample Log-In Check List

	nt Name: LA ged by: Clare Griggs		Work Order Number: Date Received:	1306021 6/4/2013 6	:00:00 PM	
Cha	ain of Custody					
1.	Were custodial seals present?	,	Yes	No 🗌	Not Required 🗹	
2.	Is Chain of Custody complete	?	Yes 🗸	No \square	Not Present	
3.	How was the sample delivered	?	Client			
Log	g <u>In</u>					
4.	Coolers are present?		Yes	No 🗸	na 🗆	
			Air Samples			
5.	Was an attempt made to cool	the samples?	Yes	No \square	NA 🗹	
6.	Were all coolers received at a	temperature of >0° C to 10.0°C	Yes	No 🗌	NA 🗹	
7.	Sample(s) in proper container	(s)?	Yes 🗸	No 🗌		
8.	Sufficient sample volume for i		Yes 🗸	No 🗆		
9.	Are samples properly preserve	• •	Yes 🗸	No 🗌		
10.			Yes	No 🗸	NA \square	
			\square	\Box		
11.	·		Yes L	No 🗀	NA 🗹	
12.		e in good condition?(unbroken)	Yes ✔ Yes ✔	No □ No □		
13.	Does paperwork match bottle	labers?	Yes 🗹	No 📙		
14.	Are matrices correctly identifie	d on Chain of Custody?	Yes 🗹	No 🗌		
15.			Yes 🗹	No \square		
16.	Were all holding times able to	be met?	Yes 🔽	No \square		
<u>Spe</u>	ecial Handling (if applic	cable)				
_	Was client notified of all discre	-	Yes	No \square	NA 🗹	
	Person Notified:	D	ate:			
	By Whom:		ia: eMail Phor	ne Fax	In Person	
	Regarding:					
	Client Instructions:					
4.0	Additional remarks/Diaranana					

18. Additional remarks/Disrepancies

Item Information

☐ Tacoma (253) 926-2493

Soil Vapor



LAN DAU ASSOCIATES

Spokane (509) 327-9737 Portland (503) 542-1080

Chain-of-Custody Record

Project Name Heavens	Supplu	Project	No. 59	3002.090	1056	N. S.	4	Testing Pa	rameters	Turnaround Time
Project Location/Event Seet						230	11	111	111	☐ Standard
Sampler's Name Devon Bee	ndt, Steve	Shaw				S. C.	11	1111	111	24 hr
Project Contact Piper Rele	n				1	()	11	111	110	//
Send Results To Piper Rolley		Mackin	Valeo:				11	1111	161	1
Sample I.D.	Date	Time	Matrix	No. of Containers	25	11	11	111	111.	Cbservations/Comments
VMW-2:060 113	6-4-13	814	Air		X					X. Allow water samples to settle, collect
VMW-3:060413		831	1		X					al quot from alear portion
VMW-4:060413		932		1	X					X_NWTPH-Dx - run acid wash/sitica gel deanup
SMW-Z: 060413		952		1 1	X					
VMW-1-060413		1057		1	X					run samples standardized to
SMW-4:060413		11.11		1	X					product
SMW-3:060413	1	1127		į.	X					Analyze for EPH if no specific
VP-1:060413	4	1752	4	1	X					product identified
										VDC/BTEX/VPH (soil):
										Dissolved metal water samples field filtered other ★ TO-15
							1			
		-			1	-	++	1 1 1	\rightarrow	
Special Shipment/Handling or Storage Requirements									Method Shipme	iof Leb dop-off
Relinquished by		Received t	0 0	0		Relin	quished	by		Received by
Signature Special 5 5/4 Signature Signature Signature Signature Printed Name Printed Name		wan)	Signat				Signature		
Pfintéd Name	2	Printed Nam	e			Printe	d Name			Printed Name
Company			Comp	Company			Company			
Date 6/7/12 Time /	800	Date 04	13	Time (000	Date		Time		DateTime



3600 Fremont Ave. N.
Seattle, WA 98103
T: (206) 352-3790
F: (206) 352-7178
info@fremontanalytical.com

Landau Associates

Piper Roelen 130 2nd Ave South Edmonds, Washington 98020

RE: Heavens Supply Lab ID: 1306022

June 06, 2013

Attention Piper Roelen:

Fremont Analytical, Inc. received 3 sample(s) on 6/4/2013 for the analyses presented in the following report.

Volatile Organic Compounds by EPA Method TO-15

This report consists of the following:

- Case Narrative
- Analytical Results
- Applicable Quality Control Summary Reports
- Chain of Custody

All analyses were performed consistent with the Quality Assurance program of Fremont Analytical, Inc. Please contact the laboratory if you should have any questions about the results.

Thank you for using Fremont Analytical.

Sincerely,

MGR

Michael Dee

Sr. Chemist / Principal

CC:

Ann Halvorsen Martin Valeri



CLIENT: Landau Associates Work Order Sample Summary
Project: Heavens Supply

Lab Order: 1306022

Lab Sample ID	Client Sample ID	Date/Time Collected	Date/Time Received
1306022-001	ERH-INF:060413	06/04/2013 10:33 AM	06/04/2013 6:00 PM
1306022-002	ERH-EFF:060413	06/04/2013 10:36 AM	06/04/2013 6:00 PM
1306022-003	ERH-MID2:060413	06/04/2013 10:41 AM	06/04/2013 6:00 PM



Case Narrative

WO#: **1306022** Date: **6/6/2013**

CLIENT: Landau Associates
Project: Heavens Supply

I. SAMPLE RECEIPT:

Samples receipt information is recorded on the attached Sample Receipt Checklist.

II. GENERAL REPORTING COMMENTS:

Air samples are reported in ppbv and ug/m3.

The validity of the analytical procedures for which data is reported in this analytical report is determined by the Laboratory Control Sample (LCS) and the Method Blank (MB). The LCS and the MB are processed with the samples to ensure method criteria are achieved throughout the entire analytical process.

III. ANALYSES AND EXCEPTIONS:

Exceptions associated with this report will be footnoted in the analytical results page(s) or the quality control summary page(s) and/or noted below.



WorkOrder: 1306022

Project: Heavens Supply

 Client Sample ID:
 ERH-INF:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306022-001A
 Date Received:
 6/4/2013

Sample Type: Tedlar Bag

Analyte	Conce	ntration	Reporting Limit	Qual	Test Method	Date Analy /Analyst	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds by	EPA Method TO-15	<u>.</u>					
1,1,1-Trichloroethane	<0.200	<1.09	0.200		TO-15	06/05/2013	SG
1,1,2,2-Tetrachloroethane	< 0.300	<2.06	0.300		TO-15	06/05/2013	SG
CFC-113	<0.500	<3.83	0.500		TO-15	06/05/2013	SG
1,1,2-Trichloroethane (TCA)	<0.500	<2.73	0.500		TO-15	06/05/2013	SG
1,1-Dichloroethane	<0.200	<0.810	0.200		TO-15	06/05/2013	SG
1,1-Dichloroethene (DCE)	<0.200	< 0.793	0.200		TO-15	06/05/2013	SG
1,2,4-Trichlorobenzene	<0.300	<2.23	0.300		TO-15	06/05/2013	SG
1,2-Dichlorobenzene	<0.300	<1.80	0.300		TO-15	06/05/2013	SG
1,2-Dichloroethane	<0.200	< 0.809	0.200		TO-15	06/05/2013	SG
1,2-Dichloropropane	<0.500	<2.31	0.500		TO-15	06/05/2013	SG
1,3-Dichlorobenzene	< 0.300	<1.80	0.300		TO-15	06/05/2013	SG
1,4-Dichlorobenzene	< 0.300	<1.80	0.300		TO-15	06/05/2013	SG
Benzyl chloride	<0.500	<2.59	0.500		TO-15	06/05/2013	SG
Dichlorobromomethane	< 0.300	<2.01	0.300		TO-15	06/05/2013	SG
Carbon tetrachloride	<0.200	<1.26	0.200		TO-15	06/05/2013	SG
Chlorobenzene	0.880	4.05	0.200		TO-15	06/05/2013	SG
D bromochloromethane	< 0.500	<4.26	0.500		TO-15	06/05/2013	SG
Chloroethane	1.32	3.48	0.500		TO-15	06/05/2013	SG
Chloroform	<0.200	< 0.977	0.200		TO-15	06/05/2013	SG
Chloromethane	4.72	9.75	0.500		TO-15	06/05/2013	SG
cis-1,2-Dichloroethene	10.1	40.0	0.200		TO-15	06/05/2013	SG
cis-1,3-dichloropropene	< 0.500	<2.27	0.500		TO-15	06/05/2013	SG
Dichlorodifluoromethane (CFC-12)	< 0.300	<1.48	0.300		TO-15	06/05/2013	SG
Dichlorotetrafluoroethane (CFC-114)	< 0.500	<3.50	0.500		TO-15	06/05/2013	SG
Hexachlorobutadiene	<1.00	<10.7	1.00		TO-15	06/05/2013	SG
Tetrachloroethene (PCE)	1,280	8,680	0.300		TO-15	06/06/2013	SG
trans-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/05/2013	SG
trans-1,3-dichloropropene	<0.500	<2.27	0.500		TO-15	06/05/2013	SG
Trichloroethene (TCE)	54.1	291	0.200		TO-15	06/05/2013	SG
Trichlorofluoromethane (CFC-11)	<0.300	<1.69	0.300		TO-15	06/05/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/05/2013	SG
Surr: 4-Bromofluorobenzene	110 %Rec		70-130		TO-15	06/05/2013	SG

Qualifiers:

- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306022

Project: Heavens Supply

 Client Sample ID:
 ERH-EFF:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306022-002A
 Date Received:
 6/4/2013

Sample Type: Tedlar Bag

Analyte	Conce	ntration	Reporting Limit	Qual	Test Method	Date Ana /Analy	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds by	EPA Method TO-15	<u>.</u>					
1,1,1-Trichloroethane	<0.200	<1.09	0.200		TO-15	06/06/2013	SG
1,1,2,2-Tetrachloroethane	< 0.300	<2.06	0.300		TO-15	06/06/2013	SG
CFC-113	<0.500	<3.83	0.500		TO-15	06/06/2013	SG
1,1,2-Trichloroethane (TCA)	<0.500	<2.73	0.500		TO-15	06/06/2013	SG
1,1-Dichloroethane	<0.200	<0.810	0.200		TO-15	06/06/2013	SG
1,1-Dichloroethene (DCE)	1.44	5.71	0.200		TO-15	06/06/2013	SG
1,2,4-Trichlorobenzene	< 0.300	<2.23	0.300		TO-15	06/06/2013	SG
1,2-Dichlorobenzene	< 0.300	<1.80	0.300		TO-15	06/06/2013	SG
1,2-Dichloroethane	0.480	1.94	0.200		TO-15	06/06/2013	SG
1,2-Dichloropropane	<0.500	<2.31	0.500		TO-15	06/06/2013	SG
1,3-Dichlorobenzene	< 0.300	<1.80	0.300		TO-15	06/06/2013	SG
1,4-Dichlorobenzene	< 0.300	<1.80	0.300		TO-15	06/06/2013	SG
Benzyl chloride	<0.500	<2.59	0.500		TO-15	06/06/2013	SG
Dichlorobromomethane	<0.300	<2.01	0.300		TO-15	06/06/2013	SG
Carbon tetrachloride	<0.200	<1.26	0.200		TO-15	06/06/2013	SG
Chlorobenzene	0.460	2.12	0.200		TO-15	06/06/2013	SG
D bromochloromethane	<0.500	<4.26	0.500		TO-15	06/06/2013	SG
Chloroethane	<0.500	<1.32	0.500		TO-15	06/06/2013	SG
Chloroform	<0.200	< 0.977	0.200		TO-15	06/06/2013	SG
Chloromethane	6.48	13.4	0.500		TO-15	06/06/2013	SG
cis-1,2-Dichloroethene	1.82	7.22	0.200		TO-15	06/06/2013	SG
cis-1,3-dichloropropene	<0.500	<2.27	0.500		TO-15	06/06/2013	SG
Dichlorodifluoromethane (CFC-12)	0.700	3.46	0.300		TO-15	06/06/2013	SG
Dichlorotetrafluoroethane (CFC-114)	<0.500	<3.50	0.500		TO-15	06/06/2013	SG
Hexachlorobutadiene	<1.00	<10.7	1.00		TO-15	06/06/2013	SG
Tetrachloroethene (PCE)	3.54	24.0	0.300		TO-15	06/06/2013	SG
trans-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/06/2013	SG
trans-1,3-dichloropropene	<0.500	<2.27	0.500		TO-15	06/06/2013	SG
Trichloroethene (TCE)	1.54	8.28	0.200		TO-15	06/06/2013	SG
Trichlorofluoromethane (CFC-11)	<0.300	<1.69	0.300		TO-15	06/06/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/06/2013	SG
Surr: 4-Bromofluorobenzene	111 %Rec		70-130		TO-15	06/06/2013	SG

Qualifiers:

- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306022

Project: Heavens Supply

 Client Sample ID:
 ERH-MID2:060413
 Date Sampled:
 6/4/2013

 Lab ID:
 1306022-003A
 Date Received:
 6/4/2013

Sample Type: Tedlar Bag

Analyte	Conce	ntration	Reporting Limit	Qual	Test Method	Date Ana /Analy	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds by	EPA Method TO-15	<u>.</u>					
1,1,1-Trichloroethane	<0.200	<1.09	0.200		TO-15	06/05/2013	SG
1,1,2,2-Tetrachloroethane	< 0.300	<2.06	0.300		TO-15	06/05/2013	SG
CFC-113	<0.500	<3.83	0.500		TO-15	06/05/2013	SG
1,1,2-Trichloroethane (TCA)	<0.500	<2.73	0.500		TO-15	06/05/2013	SG
1,1-Dichloroethane	<0.200	<0.810	0.200		TO-15	06/05/2013	SG
1,1-Dichloroethene (DCE)	26.0	103	0.200		TO-15	06/05/2013	SG
1,2,4-Trichlorobenzene	< 0.300	<2.23	0.300		TO-15	06/05/2013	SG
1,2-Dichlorobenzene	<0.300	<1.80	0.300		TO-15	06/05/2013	SG
1,2-Dichloroethane	<0.200	< 0.809	0.200		TO-15	06/05/2013	SG
1,2-Dichloropropane	<0.500	<2.31	0.500		TO-15	06/05/2013	SG
1,3-Dichlorobenzene	< 0.300	<1.80	0.300		TO-15	06/05/2013	SG
1,4-Dichlorobenzene	< 0.300	<1.80	0.300		TO-15	06/05/2013	SG
Benzyl chloride	<0.500	<2.59	0.500		TO-15	06/05/2013	SG
Dichlorobromomethane	<0.300	<2.01	0.300		TO-15	06/05/2013	SG
Carbon tetrachloride	<0.200	<1.26	0.200		TO-15	06/05/2013	SG
Chlorobenzene	<0.200	< 0.921	0.200		TO-15	06/05/2013	SG
D bromochloromethane	<0.500	<4.26	0.500		TO-15	06/05/2013	SG
Chloroethane	<0.500	<1.32	0.500		TO-15	06/05/2013	SG
Chloroform	<0.200	< 0.977	0.200		TO-15	06/05/2013	SG
Chloromethane	6.24	12.9	0.500		TO-15	06/05/2013	SG
cis-1,2-Dichloroethene	2.96	11.7	0.200		TO-15	06/05/2013	SG
cis-1,3-dichloropropene	<0.500	<2.27	0.500		TO-15	06/05/2013	SG
Dichlorodifluoromethane (CFC-12)	< 0.300	<1.48	0.300		TO-15	06/05/2013	SG
Dichlorotetrafluoroethane (CFC-114)	<0.500	<3.50	0.500		TO-15	06/05/2013	SG
Hexachlorobutadiene	<1.00	<10.7	1.00		TO-15	06/05/2013	SG
Tetrachloroethene (PCE)	< 0.300	<2.03	0.300		TO-15	06/05/2013	SG
trans-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/05/2013	SG
trans-1,3-dichloropropene	<0.500	<2.27	0.500		TO-15	06/05/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/05/2013	SG
Trichlorofluoromethane (CFC-11)	<0.300	<1.69	0.300		TO-15	06/05/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/05/2013	SG
Surr: 4-Bromofluorobenzene	106 %Rec		70-130		TO-15	06/05/2013	SG

Qualifiers:

- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



Work Order: 1306022

QC SUMMARY REPORT

CLIENT: Landau Associates Project: Heavens Supply

Volatile Organic Compounds by EPA Method TO-15

Sample ID: 1306022-003AREP	SampType: REP			Units: ppbv		Prep Da	te: 6/5/20 1	3	RunNo: 878	30	
Client ID: ERH-MID2:060413	Batch ID: R8780					Analysis Da	te: 6/5/20 1	3	SeqNo: 176	201	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Dichlorodifluoromethane (CFC-12)	ND	0.300						0	0	30	
Chloromethane	6.12	0.500						6.240	1.94	30	
Dichlorotetrafluoroethane (CFC-114)	ND	0.500						0	0	30	
Vinyl chloride	ND	0.200						0	0	30	
Trichlorofluoromethane (CFC-11)	ND	0.300						0	0	30	
Chloroethane	ND	0.500						0	0	30	
1,1-Dichloroethene (DCE)	24.1	0.200						26.04	7.66	30	
trans-1,2-Dichloroethene	ND	0.200						0	0	30	
1,1-Dichloroethane	ND	0.200						0	0	30	
cis-1,2-Dichloroethene	2.96	0.200						2.960	0	30	
Chloroform	ND	0.200						0	0	30	
1,1,1-Trichloroethane	ND	0.200						0	0	30	
Carbon tetrachloride	ND	0.200						0	0	30	
1,2-Dichloroethane	ND	0.200						0	0	30	
Trichloroethene (TCE)	ND	0.200						0	0	30	
1,2-Dichloropropane	ND	0.500						0	0	30	
Dichlorobromomethane	ND	0.300						0	0	30	
cis-1,3-dichloropropene	ND	0.500						0	0	30	
trans-1,3-dichloropropene	ND	0.500						0	0	30	
1,1,2-Trichloroethane (TCA)	ND	0.500						0	0	30	
Tetrachloroethene (PCE)	ND	0.300						0	0	30	
Dibromochloromethane	ND	0.500						0	0	30	
Chlorobenzene	ND	0.200						0	0	30	
1,1,2,2-Tetrachloroethane	ND	0.300						0	0	30	
Benzyl chloride	ND	0.500						0	0	30	
1,3-Dichlorobenzene	ND	0.300						0	0	30	
1,4-Dichlorobenzene	ND	0.300						0	0	30	
1,2-Dichlorobenzene	ND	0.300						0	0	30	
1,2,4-Trichlorobenzene	ND	0.300						0	0	30	

Qualifiers:

B Analyte detected in the associated Method Blank

Holding times for preparation or analysis exceeded

R RPD outside accepted recovery limits

D Dilution was required

J Analyte detected below quantitation limits

RL Reporting Limit

E Value above quantitation range

ND Not detected at the Reporting Limit

S Spike recovery outside accepted recovery limits



Work Order: 1306022

QC SUMMARY REPORT

CLIENT: Landau Associates Project: Heavens Supply

Volatile Organic Compounds by EPA Method TO-15

Sample ID: 1306022-003AREP	SampType: REP			Units: ppbv		Prep Da	te: 6/5/201	3	RunNo: 878	30	
Client ID: ERH-MID2:060413	Batch ID: R8780					Analysis Da	te: 6/5/201	3	SeqNo: 176	S201	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Hexachlorobutadiene	ND	1.00						0	0	30	
CFC-113	ND	0.500						0	0	30	
Surr: 4-Bromofluorobenzene	39.8		40.00		99.6	70	130		0		

Sample ID: MB-R8780	SampType: MBLK Units: ppbv Prep Date: 6/5/2013			RunNo: 8780							
Client ID: MBLKW	Batch ID: R8780					Analysis Da	te: 6/5/201	3	SeqNo: 176	3202	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Dichlorodifluoromethane (CFC-12)	ND	0.300									
Chloromethane	ND	0.500									
Dichlorotetrafluoroethane (CFC-114)	ND	0.500									
Vinyl chloride	ND	0.200									
Trichlorofluoromethane (CFC-11)	ND	0.300									
Chloroethane	ND	0.500									
1,1-Dichloroethene (DCE)	ND	0.200									
trans-1,2-Dichloroethene	ND	0.200									
1,1-Dichloroethane	ND	0.200									
cis-1,2-Dichloroethene	ND	0.200									
Chloroform	ND	0.200									
1,1,1-Trichloroethane	ND	0.200									
Carbon tetrachloride	ND	0.200									
1,2-Dichloroethane	ND	0.200									
Trichloroethene (TCE)	ND	0.200									
1,2-Dichloropropane	ND	0.500									
Dichlorobromomethane	ND	0.300									
cis-1,3-dichloropropene	ND	0.500									
trans-1,3-dichloropropene	ND	0.500									
1,1,2-Trichloroethane (TCA)	ND	0.500									

Qualifiers: B Analyte detected in the associated Method Blank

H Holding times for preparation or analysis exceeded

R RPD outside accepted recovery limits

D Dilution was required

Analyte detected below quantitation limits

L Reporting Limit

E Value above quantitation range

ND Not detected at the Reporting Limit

S Spike recovery outside accepted recovery limits



Work Order: 1306022

QC SUMMARY REPORT

CLIENT: Landau Associates **Project:** Heavens Supply

Volatile Organic Compounds by EPA Method TO-15

Sample ID: MB-R8780 Client ID: MBLKW	SampType: MBLK Batch ID: R8780			Units: ppbv		Prep Date: Analysis Date:			RunNo: 878 SeqNo: 176		
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit H	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Tetrachloroethene (PCE)	ND	0.300									
Dibromochloromethane	ND	0.500									
Chlorobenzene	ND	0.200									
1,1,2,2-Tetrachloroethane	ND	0.300									
Benzyl chloride	ND	0.500									
1,3-Dichlorobenzene	ND	0.300									
1,4-Dichlorobenzene	ND	0.300									
1,2-Dichlorobenzene	ND	0.300									
1,2,4-Trichlorobenzene	ND	0.300									
Hexachlorobutadiene	ND	1.00									
CFC-113	ND	0.500									
Surr: 4-Bromofluorobenzene	11.2		10.00		112	70	130				

Sample ID: LCS-R8780	SampType: LCS			Units: ppbv		Prep Da	te: 6/5/201	3	RunNo: 878	30	
Client ID: LCSW	Batch ID: R8780					Analysis Da	te: 6/5/201	3	SeqNo: 176	5203	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Dichlorodifluoromethane (CFC-12)	5.31	0.300	5.000	0	106	70	130				
Chloromethane	5.72	0.500	5.000	0	114	70	130				
Dichlorotetrafluoroethane (CFC-114)	5.61	0.500	5.000	0	112	70	130				
Vinyl chloride	5.34	0.200	5.000	0	107	70	130				
Trichlorofluoromethane (CFC-11)	5.64	0.300	5.000	0	113	70	130				
Chloroethane	5.90	0.500	5.000	0	118	70	130				
1,1-Dichloroethene (DCE)	5.59	0.200	5.000	0	112	70	130				
trans-1,2-Dichloroethene	5.49	0.200	5.000	0	110	70	130				
1,1-Dichloroethane	5.41	0.200	5.000	0	108	70	130				
cis-1,2-Dichloroethene	5.61	0.200	5.000	0	112	70	130				
Chloroform	5.78	0.200	5.000	0	116	70	130				

Analyte detected in the associated Method Blank Qualifiers:

Holding times for preparation or analysis exceeded

R RPD outside accepted recovery limits

Dilution was required D

Analyte detected below quantitation limits

Reporting Limit

Е Value above quantitation range

ND Not detected at the Reporting Limit

Spike recovery outside accepted recovery limits



Work Order: 1306022

QC SUMMARY REPORT

CLIENT: Landau Associates Project: Heavens Supply

Volatile Organic Compounds by EPA Method TO-15

Sample ID: LCS-R8780	SampType: LCS			Units: ppbv		Prep Da	te: 6/5/201	3	RunNo: 878	30	
Client ID: LCSW	Batch ID: R8780					Analysis Da	te: 6/5/201	3	SeqNo: 176	203	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
1,1,1-Trichloroethane	5.91	0.200	5.000	0	118	70	130				
Carbon tetrachloride	5.04	0.200	5.000	0	101	70	130				
1,2-Dichloroethane	5.35	0.200	5.000	0	107	70	130				
Trichloroethene (TCE)	5.55	0.200	5.000	0	111	70	130				
1,2-Dichloropropane	5.21	0.500	5.000	0	104	70	130				
Dichlorobromomethane	5.81	0.300	5.000	0	116	70	130				
cis-1,3-dichloropropene	5.67	0.500	5.000	0	113	70	130				
trans-1,3-dichloropropene	5.52	0.500	5.000	0	110	70	130				
1,1,2-Trichloroethane (TCA)	5.88	0.500	5.000	0	118	70	130				
Tetrachloroethene (PCE)	5.86	0.300	5.000	0	117	70	130				
Dibromochloromethane	4.94	0.500	5.000	0	98.8	70	130				
Chlorobenzene	5.43	0.200	5.000	0	109	70	130				
1,1,2,2-Tetrachloroethane	6.04	0.300	5.000	0	121	70	130				
Benzyl chloride	5.63	0.500	5.000	0	113	70	130				
1,3-Dichlorobenzene	5.61	0.300	5.000	0	112	70	130				
1,4-Dichlorobenzene	6.35	0.300	5.000	0	127	70	130				
1,2-Dichlorobenzene	5.80	0.300	5.000	0	116	70	130				
1,2,4-Trichlorobenzene	6.44	0.300	5.000	0	129	70	130				
Hexachlorobutadiene	5.85	1.00	5.000	0	117	70	130				
CFC-113	5.92	0.500	5.000	0	118	70	130				
Surr: 4-Bromofluorobenzene	11.1		10.00		111	70	130				

Sample ID: LCSD-R8780	SampType: LCSD			Units: ppbv		Prep Da	te: 6/5/201	3	RunNo: 878	30	
Client ID: LCSW02	Batch ID: R8780					Analysis Da	te: 6/5/201	3	SeqNo: 176	S205	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Dichlorodifluoromethane (CFC-12)	5.58	0.300	5.000	0	112	70 70	130	5.310	4.96	30	
Chloromethane	5.69	0.500	5.000	0	114	70	130	5.720	0.526	30	

Qualifiers: B Analyte detected in the associated Method Blank

Holding times for preparation or analysis exceeded

R RPD outside accepted recovery limits

- D Dilution was required
- J Analyte detected below quantitation limits
- RL Reporting Limit

- E Value above quantitation range
- ND Not detected at the Reporting Limit
- S Spike recovery outside accepted recovery limits

Date: 6/6/2013



Work Order: 1306022

QC SUMMARY REPORT

CLIENT: Landau Associates Project: Heavens Supply

Volatile Organic Compounds by EPA Method TO-15

Sample ID: LCSD-R8780	SampType: LCSD			Units: ppbv		Prep Da	te: 6/5/201	3	RunNo: 878	30	
Client ID: LCSW02	Batch ID: R8780					Analysis Da	te: 6/5/201	3	SeqNo: 176	205	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Dichlorotetrafluoroethane (CFC-114)	5.54	0.500	5.000	0	111	70	130	5.610	1.26	30	
Vinyl chloride	5.14	0.200	5.000	0	103	70	130	5.340	3.82	30	
Trichlorofluoromethane (CFC-11)	5.49	0.300	5.000	0	110	70	130	5.640	2.70	30	
Chloroethane	6.08	0.500	5.000	0	122	70	130	5.900	3.01	30	
1,1-Dichloroethene (DCE)	5.48	0.200	5.000	0	110	70	130	5.590	1.99	30	
trans-1,2-Dichloroethene	5.17	0.200	5.000	0	103	70	130	5.490	6.00	30	
1,1-Dichloroethane	5.64	0.200	5.000	0	113	70	130	5.410	4.16	30	
cis-1,2-Dichloroethene	5.43	0.200	5.000	0	109	70	130	5.610	3.26	30	
Chloroform	5.80	0.200	5.000	0	116	70	130	5.780	0.345	30	
1,1,1-Trichloroethane	6.30	0.200	5.000	0	126	70	130	5.910	6.39	30	
Carbon tetrachloride	5.23	0.200	5.000	0	105	70	130	5.040	3.70	30	
1,2-Dichloroethane	5.64	0.200	5.000	0	113	70	130	5.350	5.28	30	
Trichloroethene (TCE)	5.42	0.200	5.000	0	108	70	130	5.550	2.37	30	
1,2-Dichloropropane	5.27	0.500	5.000	0	105	70	130	5.210	1.15	30	
Dichlorobromomethane	5.62	0.300	5.000	0	112	70	130	5.810	3.32	30	
cis-1,3-dichloropropene	5.38	0.500	5.000	0	108	70	130	5.670	5.25	30	
trans-1,3-dichloropropene	5.41	0.500	5.000	0	108	70	130	5.520	2.01	30	
1,1,2-Trichloroethane (TCA)	5.53	0.500	5.000	0	111	70	130	5.880	6.13	30	
Tetrachloroethene (PCE)	5.66	0.300	5.000	0	113	70	130	5.860	3.47	30	
Dibromochloromethane	4.89	0.500	5.000	0	97.8	70	130	4.940	1.02	30	
Chlorobenzene	5.67	0.200	5.000	0	113	70	130	5.430	4.32	30	
1,1,2,2-Tetrachloroethane	6.48	0.300	5.000	0	130	70	130	6.040	7.03	30	
Benzyl chloride	6.21	0.500	5.000	0	124	70	130	5.630	9.80	30	
1,3-Dichlorobenzene	6.07	0.300	5.000	0	121	70	130	5.610	7.88	30	
1,4-Dichlorobenzene	6.02	0.300	5.000	0	120	70	130	6.350	5.34	30	
1,2-Dichlorobenzene	6.18	0.300	5.000	0	124	70	130	5.800	6.34	30	
1,2,4-Trichlorobenzene	6.42	0.300	5.000	0	128	70	130	6.440	0.311	30	
Hexachlorobutadiene	6.48	1.00	5.000	0	130	70	130	5.850	10.2	30	
CFC-113	5.91	0.500	5.000	0	118	70	130	5.920	0.169	30	

Qualifiers: B Analyte detected in the associated Method Blank

H Holding times for preparation or analysis exceeded

R RPD outside accepted recovery limits

D Dilution was required

J Analyte detected below quantitation limits

RL Reporting Limit

E Value above quantitation range

ND Not detected at the Reporting Limit

S Spike recovery outside accepted recovery limits



Date: 6/6/2013

Work Order: 1306022

QC SUMMARY REPORT

CLIENT: Landau Associates
Project: Heavens Supply

Volatile Organic Compounds by EPA Method TO-15

Sample ID: LCSD-R8780	SampType: LCSD			Units: ppbv		Prep Da	te: 6/5/201	3	RunNo: 878	30	
Client ID: LCSW02	Batch ID: R8780					Analysis Da	te: 6/5/201	3	SeqNo: 176	205	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Surr: 4-Bromofluorobenzene	10.8		10.00		108	70	130		0		

H Holding times for preparation or analysis exceeded

RL Reporting Limit

E Value above quantitation range

ND Not detected at the Reporting Limit



Sample Log-In Check List

	nt Name: LA ged by: Clare Griggs	Work Order Number: Date Received:	1306022 6/4/2013 6:00:0	00 PM
<u>Cha</u>	ain of Custody			
1.	Were custodial seals present?	Yes	No 🗌 No	ot Required 🗹
2.	Is Chain of Custody complete?	Yes 🗹	No 🗆 🛮 N	Not Present
3.	How was the sample delivered?	Client		
Log	<u>g In</u>			
4.	Coolers are present?	Yes	No 🗹	NA \square
5.	Was an attempt made to cool the samples?	Air Samples Yes	No 🗆	NA 🗹
6.	Were all coolers received at a temperature of >0° C to 10.0°C	Yes	No 🗆	NA 🗹
7.	Sample(s) in proper container(s)?	Yes 🗸	No 🗌	
8.	Sufficient sample volume for indicated test(s)?	Yes 🗸	No 🗌	
9.	Are samples properly preserved?	Yes 🗹	No 🗌	
10.	Was preservative added to bottles?	Yes	No 🗹	na 🗆
11	Is there headensee present in VOA viole?	Yes	No 🗆	NA 🗹
11. 12.	Is there headspace present in VOA vials? Did all sample containers arrive in good condition?(unbroken)	Yes ✓	No \square	NA 🖭
13.		Yes 🗹	No \square	
14	Are matrices correctly identified on Chain of Custody?	Yes 🗹	No 🗌	
15.		Yes 🗹	No 🗆	
_	Were all holding times able to be met?	Yes 🔽	No 🗆	
	ecial Handling (if applicable)			
17.	Was client notified of all discrepancies with this order?	Yes 🗆	No 🗀	NA 🗹
	Person Notified: By Whom: Regarding: Client Instructions:	'	ne Fax Ir	n Person

18. Additional remarks/Disrepancies

Item Information

ERH Vapor

1306022

Tacoma (253) 926-2493 Spokane (509) 327-3737 LANDAU Spokane (509) 327-3737
ASSOCIATES Portland (503) 542-1080

Chain-of-Custody Record

Date **6** - 4 - 13
Page Loi 1

Project Name Heavens Su	pply	Projec	t No. 58	3002.0	50.056	1	7 0	Testing	Parameter	TOTAL COURSE A (TAILO
Project Location/Event Sear						/in/	//	111	1111	☐ Standard Accelerated
Sampler's Name Devon						20	11	111	///	1 48 hour
Project Contact Piper Roc					/		11	111	111	11
Send Results To Piper Lock	n, Anie Halve			No. of		1//	1/	1//	1///	Observations/Comments
Sample I.D. ERH-INF: 06 0H13	0-4-13	Time	Matrix Azr	Containe	SIS /	11	1	111	111	(
ERH-EFF 060913	6-1-15	1036	ALC:	11	1	++			+++	Allow water samples to settle, collect aliquot from clear portion
ERH-MIDZ . 060413	4	1041	+	11	X					X NWTPH-Dx - run acid wasivslica gel cleanup
										rur-samples standardized to product
										Analyze for EPH if no specific product identified
										VOC/BTEX/VPH (soll):non-preservedpreserved w/methanolpreserved w/sodium bisuifatefreeze upon receipt
										Dissolved metal water samples field filtered
										Oner
						1				
					++	1	-			
Special Shioment/Handing or Storage Requirements									Metho Shipm	od of Lab Drop off
Relinguished by		Received	by D	0		Relin	quished	i by		Received by
Strature 54 cm		Sanatae		James		Signa	ture			Signature
Printed Name Conda Associa	h .	Printed Nam	15 CAL	W.C.		Printe	c Name			Printed Name
and the same		Company	ONTRA			Comp	any			Company
Date 6/9/13 Time /	800	Date Ce	4/13	Time	800	Date		Tim	g	DateTime



3600 Fremont Ave. N.
Seattle, WA 98103
T: (206) 352-3790
F: (206) 352-7178
info@fremontanalytical.com

Landau Associates

Piper Roelen 130 2nd Ave South Edmonds, Washington 98020

RE: Heavens Supply Lab ID: 1306074

June 12, 2013

Attention Piper Roelen:

Fremont Analytical, Inc. received 7 sample(s) on 6/11/2013 for the analyses presented in the following report.

Volatile Organic Compounds by EPA Method TO-15

This report consists of the following:

- Case Narrative
- Analytical Results
- Applicable Quality Control Summary Reports
- Chain of Custody

All analyses were performed consistent with the Quality Assurance program of Fremont Analytical, Inc. Please contact the laboratory if you should have any questions about the results.

Thank you for using Fremont Analytical.

Sincerely,

Michael Dee

MGR

Sr. Chemist / Principal

CC:

Ann Halvorsen Martin Valeri

Date: 06/12/2013



CLIENT: Landau Associates Work Order Sample Summary

Project: Heavens Supply Lab Order: 1306074

Lab Sample ID	Client Sample ID	Date/Time Collected	Date/Time Received
1306074-001	VMW-2:061113	06/11/2013 9:39 AM	06/11/2013 6:21 PM
1306074-002	VMW-3:061113	06/11/2013 9:56 AM	06/11/2013 6:21 PM
1306074-003	VMW-4:061113	06/11/2013 10:18 AM	06/11/2013 6:21 PM
1306074-004	SMW-2:061113	06/11/2013 10:39 AM	06/11/2013 6:21 PM
1306074-005	VMW-1:061113	06/11/2013 11:13 AM	06/11/2013 6:21 PM
1306074-006	SMW-4:061113	06/11/2013 11:33 AM	06/11/2013 6:21 PM
1306074-007	SMW-3:061113	06/11/2013 11:51 AM	06/11/2013 6:21 PM



Case Narrative

WO#: **1306074**Date: **6/12/2013**

CLIENT: Landau Associates
Project: Heavens Supply

I. SAMPLE RECEIPT:

Samples receipt information is recorded on the attached Sample Receipt Checklist.

II. GENERAL REPORTING COMMENTS:

Air samples are reported in ppbv and ug/m3.

The validity of the analytical procedures for which data is reported in this analytical report is determined by the Laboratory Control Sample (LCS) and the Method Blank (MB). The LCS and the MB are processed with the samples to ensure method criteria are achieved throughout the entire analytical process.

III. ANALYSES AND EXCEPTIONS:

Exceptions associated with this report will be footnoted in the analytical results page(s) or the quality control summary page(s) and/or noted below.



WorkOrder: 1306074

Project: Heavens Supply

 Client Sample ID:
 VMW-2:061113
 Date Sampled:
 6/11/2013

 Lab ID:
 1306074-001A
 Date Received:
 6/11/2013

Analyte	Concer	Reporting Limit	Qual	Test Method	Date Analyze /Analyst		
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	<0.793	0.200		TO-15	06/12/2013	SG
Tetrachloroethene (PCE)	< 0.300	<2.03	0.300		TO-15	06/12/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/12/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/12/2013	SG
Surr: 4-Bromofluorobenzene	110 %Rec		70-130		TO-15	06/12/2013	SG

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306074

Project: Heavens Supply

 Client Sample ID:
 VMW-3:061113
 Date Sampled:
 6/11/2013

 Lab ID:
 1306074-002A
 Date Received:
 6/11/2013

Analyte	Concer	Reporting Limit	Qual	Test Method	Date Analy /Analyst		
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	4.48	17.8	0.200		TO-15	06/12/2013	SG
Tetrachloroethene (PCE)	230	1,560	0.300		TO-15	06/12/2013	SG
Trichloroethene (TCE)	17.8	95.9	0.200		TO-15	06/12/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/12/2013	SG
Surr: 4-Bromofluorobenzene	101 %Rec		70-130		TO-15	06/12/2013	SG

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306074

Project: Heavens Supply

 Client Sample ID:
 VMW-4:061113
 Date Sampled:
 6/11/2013

 Lab ID:
 1306074-003A
 Date Received:
 6/11/2013

Sample Type: Tedlar Bag

Analyte	Concer	ntration	Reporting Limit	Qual	Test Method	Date Analyz /Analyst	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/12/2013	SG
Tetrachloroethene (PCE)	382	2,590	0.300		TO-15	06/12/2013	SG
Trichloroethene (TCE)	6.40	34.4	0.200		TO-15	06/12/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/12/2013	SG
Surr: 4-Bromofluorobenzene	93.0 %Rec		70-130		TO-15	06/12/2013	SG

E Value above quantitation range

J Analyte detected below quantitation limits

D Dilution was required

H Holding times for preparation or analysis exceeded

ND Not detected at the Reporting Limit



WorkOrder: 1306074

Project: Heavens Supply

 Client Sample ID:
 SMW-2:061113
 Date Sampled:
 6/11/2013

 Lab ID:
 1306074-004A
 Date Received:
 6/11/2013

Sample Type: Tedlar Bag

Analyte	Concer	Concentration			Test Method	Date Analya /Analyst	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/12/2013	SG
Tetrachloroethene (PCE)	113	764	0.300		TO-15	06/12/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/12/2013	
							SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/12/2013	SG SG

E Value above quantitation range

J Analyte detected below quantitation limits

D Dilution was required

H Holding times for preparation or analysis exceeded

ND Not detected at the Reporting Limit



WorkOrder: 1306074

Project: Heavens Supply

 Client Sample ID:
 VMW-1:061113
 Date Sampled:
 6/11/2013

 Lab ID:
 1306074-005A
 Date Received:
 6/11/2013

Analyte	Concer	Concentration			Test Method	Date Analyze /Analyst	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	<0.793	0.200		TO-15	06/12/2013	SG
Tetrachloroethene (PCE)	9.44	64.0	0.300		TO-15	06/12/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/12/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/12/2013	SG
Surr: 4-Bromofluorobenzene	96.6 %Rec		70-130		TO-15	06/12/2013	SG

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306074

Project: Heavens Supply

 Client Sample ID:
 SMW-4:061113
 Date Sampled:
 6/11/2013

 Lab ID:
 1306074-006A
 Date Received:
 6/11/2013

Analyte	Concer	itration	Reporting Limit	Qual	Test Method	Date Analya /Analyst	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	<0.793	0.200		TO-15	06/12/2013	SG
Tetrachloroethene (PCE)	42.6	289	0.300		TO-15	06/12/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/12/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/12/2013	SG
Surr: 4-Bromofluorobenzene	92.1 %Rec		70-130		TO-15	06/12/2013	SG

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306074

Project: Heavens Supply

 Client Sample ID:
 SMW-3:061113
 Date Sampled:
 6/11/2013

 Lab ID:
 1306074-007A
 Date Received:
 6/11/2013

Analyte	Concer	Reporting Limit	Qual	Test Method	Date Analyz /Analyst		
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/12/2013	SG
Tetrachloroethene (PCE)	154	1,040	0.300		TO-15	06/12/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/12/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/12/2013	SG
Surr: 4-Bromofluorobenzene	115 %Rec		70-130		TO-15	06/12/2013	SG

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit

Date: 6/12/2013



Work Order: 1306074

QC SUMMARY REPORT

CLIENT: Landau Associates **Project: Heavens Supply**

Volatile Organic Compounds by EPA Method TO-15

Sample ID: LCSD-R8853	SampType: LCS			Units: ppbv		Prep Date	e: 6/11/20	13	RunNo: 885	53	
Client ID: LCSW	Batch ID: R8853					Analysis Date	e: 6/11/20	13	SeqNo: 177	670	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Vinyl chloride	4.35	0.200	5.000	0	87.0	70	130	4.250	2.33		
cis-1,2-Dichloroethene	5.61	0.200	5.000	0	112	70	130	5.580	0.536		
Trichloroethene (TCE)	5.67	0.200	5.000	0	113	70	130	5.600	1.24		
Tetrachloroethene (PCE)	4.52	0.300	5.000	0	90.4	70	130	4.460	1.34		
Surr: 4-Bromofluorobenzene	9.45		10.00		94.5	70	130		0		
Sample ID: LCS-R8853	SampType: LCS			Units: ppbv		Prep Date	e: 6/11/20	13	RunNo: 885	53	
Client ID: LCSW	Batch ID: R8853					Analysis Date	e: 6/11/20	13	SeqNo: 177	7671	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Vinyl chloride	4.25	0.200	5.000	0	85.0	70	130				
cis-1,2-Dichloroethene	5.58	0.200	5.000	0	112	70	130				
Trichloroethene (TCE)	5.60	0.200	5.000	0	112	70	130				
Tetrachloroethene (PCE)	4.46	0.300	5.000	0	89.2	70	130				
Surr: 4-Bromofluorobenzene	9.49		10.00		94.9	70	130				
Sample ID: MB-R8853	SampType: MBLK			Units: ppbv		Prep Date	e: 6/12/20	13	RunNo: 885	53	
Client ID: MBLKW	Batch ID: R8853					Analysis Date	e: 6/12/20	13	SeqNo: 177	672	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qua
Vinyl chloride	ND	0.200									
cis-1,2-Dichloroethene	ND	0.200									
Trichloroethene (TCE)	ND	0.200									
Tetrachloroethene (PCE)	ND	0.300									
Surr: 4-Bromofluorobenzene	10.4		10.00		104	70	130				

Analyte detected in the associated Method Blank Qualifiers:

Dilution was required D Holding times for preparation or analysis exceeded


Analyte detected below quantitation limits

RL Reporting Limit

Value above quantitation range Е

ND Not detected at the Reporting Limit

Spike recovery outside accepted recovery limits





Work Order: 1306074

QC SUMMARY REPORT

CLIENT: Landau Associates
Project: Heavens Supply

Volatile Organic Compounds by EPA Method TO-15

Sample ID: 1306074-007AREP	SampType: REP			Units: ppbv		Prep Da	te: 6/12/20	13	RunNo: 885	i3	
Client ID: SMW-3:061113	Batch ID: R8853		Analysis Date: 6/12/2013 SeqNo: 177908							908	
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Vinyl chloride	ND	0.200						0	0	30	
cis-1,2-Dichloroethene	ND	0.200						0	0	30	
Trichloroethene (TCE)	ND	0.200						0	0	30	
Tetrachloroethene (PCE)	167	0.300						153.9	8.22	30	
Surr: 4-Bromofluorobenzene	83.9		80.00		105	70	130		0		

Holding times for preparation or analysis exceeded

Analyte detected below quantitation limits

RL Reporting Limit

E Value above quantitation range

ND Not detected at the Reporting Limit

S Spike recovery outside accepted recovery limits




Sample Log-In Check List

	nt Name: LA ged by: Clare Griggs		Work Order Number: Date Received:		6:21:00 PM	
Cha	ain of Custody					
1.	Were custodial seals pres	ent?	Yes	No 🗌	Not Required ✓	
2.	Is Chain of Custody compl	ete?	Yes 🗸	No \square	Not Present	
3.	How was the sample delive	ered?	Client			
Log	g In					
4.	Coolers are present?		Yes	No 🗸	NA \square	
			Air Samples			
5.	Was an attempt made to c	cool the samples?	Yes	No \square	NA 🗹	
6.	Were all coolers received a	at a temperature of >0° C to 10.0°C	Yes	No \square	NA 🗹	
7.	Sample(s) in proper contain	iner(s)?	Yes 🗹	No 🗆		
7. 8.	Sufficient sample volume t		Yes ⊻	No \square		
9.	Are samples properly pres	, ,	Yes 🗹	No \square		
9. 10.			Yes	No 🗹	NA 🗆	
10.	Trac processans added to		.00			
11.	Is there headspace preser	nt in VOA vials?	Yes	No \square	NA 🔽	
12.	Did all sample containers a	arrive in good condition?(unbroken)	Yes 🗹	No \square		
13.	Does paperwork match bo	ttle labels?	Yes 🗹	No 🗌		
14.	Are matrices correctly iden	tified on Chain of Custody?	Yes 🗹	No 🗌		
15.	Is it clear what analyses w	ere requested?	Yes 🗹	No \square		
16.	Were all holding times able	e to be met?	Yes 🗹	No 🗌		
Spe	ecial Handling (if app	olicable)				
_		screpancies with this order?	Yes	No \square	NA 🗹	
	Person Notified:	D	ate:			
	By Whom:	Vi	ia: eMail Phor	ne 🗌 Fax	☐ In Person	
	Regarding:				_	
	Client Instructions:					
	Additional remarks/Discon					

18. Additional remarks/Disrepancies

Item Information







Date 6-11-13

Chain-of-Custody Record

Project Name Heavens 5	ערפע	Project	No. 583	3002.05	0.056	I		Testin	g Param	eters	Turnaround Time
Project Location/Event Sea	1 -1		110. 199			11	1	111	11	11	Standard
Sampler's Name Devan 1			A 54	141		14	11	11	111	1	XACC elerated
		STE	C 3/	47.00	1	11	1	1//	11	11	//
Project Contact Riger Rock		4.		- 1	15	2//	11	11	111	1	/ /
Send Results To 7 per Roelen	n, Anne Halvo	rson, Mar	fin Vou	No. of	10	11	1.	///	11	11	
Sample I.D.	Date	Time		Containers	17	11	11	11	111	1	Cbservations/Comments
VMW-2:061113	6-11-13	939	Air	1	X						X Allow water samples to settle, collect
VMW-3:06113		9 56	1	1	X						aliquot from clear portion
VMW-4:06113		1018		1	K				L.J.		X NWTPH-Dx - run acid wesh sti ca get cleanup
SMW-2.061113		1039			5						
NWM-1: 001113	1111	1113		1	×					-	run samples standardized to
SMW-4:061113		1133	1460.0	1	X			1-1-1		1	product
SMW-31061113	4	1151	+	1	×	++-		++		+	Analyze for EPH f no specific product identified
Special Shipment/Handling or Storage Requirements										Method	ent deliver
Signature Steven DJHL Printed Name CANDA ASJOC Dompany Date 6/11/12 Time		Signature Signature Printed Nam Frem Company Date	ont A	In Time 18	er 1 221	Relind Signati Printed Compa	Name		Time		Received by Signature Printed Name Company Date Time



3600 Fremont Ave. N.
Seattle, WA 98103
T: (206) 352-3790
F: (206) 352-7178
info@fremontanalytical.com

Landau Associates

Piper Roelen 130 2nd Ave South Edmonds, Washington 98020

RE: Heavens Supply Lab ID: 1306185

June 27, 2013

Attention Piper Roelen:

Fremont Analytical, Inc. received 8 sample(s) on 6/25/2013 for the analyses presented in the following report.

Volatile Organic Compounds by EPA Method TO-15

This report consists of the following:

- Case Narrative
- Analytical Results
- Applicable Quality Control Summary Reports
- Chain of Custody

All analyses were performed consistent with the Quality Assurance program of Fremont Analytical, Inc. Please contact the laboratory if you should have any questions about the results.

Thank you for using Fremont Analytical.

Sincerely,

MGR

Michael Dee

Sr. Chemist / Principal

CC:

Ann Halvorsen Martin Valeri

Date: 06/27/2013



CLIENT: Landau Associates Work Order Sample Summary

Project: Heavens Supply

Lab Order: 1306185

Lab Cample ID	Client Semple ID	Date/Time Collected	Date/Time Received
Lab Sample ID	Client Sample ID	Date/Time Conected	Date/Time Received
1306185-001	VMW-2:062513	06/25/2013 8:21 AM	06/25/2013 6:06 PM
1306185-002	VMW-3:062513	06/25/2013 8:38 AM	06/25/2013 6:06 PM
1306185-003	VMW-4:062513	06/25/2013 8:59 AM	06/25/2013 6:06 PM
1306185-004	SMW-2:062513	06/25/2013 9:37 AM	06/25/2013 6:06 PM
1306185-005	VMW-1:062513	06/25/2013 10:11 AM	06/25/2013 6:06 PM
1306185-006	SMW-4:062513	06/25/2013 11:00 AM	06/25/2013 6:06 PM
1306185-007	SMW-3:062513	06/25/2013 11:15 AM	06/25/2013 6:06 PM
1306185-008	VP-1:062513	06/25/2013 5:50 PM	06/25/2013 6:06 PM



Case Narrative

WO#: **1306185**Date: **6/27/2013**

CLIENT: Landau Associates
Project: Heavens Supply

I. SAMPLE RECEIPT:

Samples receipt information is recorded on the attached Sample Receipt Checklist.

II. GENERAL REPORTING COMMENTS:

Air samples are reported in ppbv and ug/m3.

The validity of the analytical procedures for which data is reported in this analytical report is determined by the Laboratory Control Sample (LCS) and the Method Blank (MB). The LCS and the MB are processed with the samples to ensure method criteria are achieved throughout the entire analytical process.

III. ANALYSES AND EXCEPTIONS:

Exceptions associated with this report will be footnoted in the analytical results page(s) or the quality control summary page(s) and/or noted below.



WorkOrder: 1306185

Project: Heavens Supply

 Client Sample ID:
 VMW-2:062513
 Date Sampled:
 6/25/2013

 Lab ID:
 1306185-001A
 Date Received:
 6/25/2013

Analyte	Concentration		Reporting Limit Qua		Test Method	Date Analyze /Analyst	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/26/2013	SG
Tetrachloroethene (PCE)	<0.300	<2.03	0.300		TO-15	06/26/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/26/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/26/2013	SG
Surr: 4-Bromofluorobenzene	106 %Rec		70-130		TO-15	06/26/2013	SG

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306185

Project: Heavens Supply

 Client Sample ID:
 VMW-3:062513
 Date Sampled:
 6/25/2013

 Lab ID:
 1306185-002A
 Date Received:
 6/25/2013

Sample Type: Tedlar Bag

Analyte	Concer	Reporting Limit	ng Qual	I Test Method	Date Analyz /Analyst		
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	4.16	16.5	0.200		TO-15	06/26/2013	SG
Tetrachloroethene (PCE)	307	2,080	0.300		TO-15	06/26/2013	SG
Trichloroethene (TCE)	21.4	115	0.200		TO-15	06/26/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/26/2013	SG
Surr: 4-Bromofluorobenzene	109 %Rec		70-130		TO-15	06/26/2013	SG

J Analyte detected below quantitation limits

D Dilution was required

H Holding times for preparation or analysis exceeded

ND Not detected at the Reporting Limit

E Value above quantitation range



WorkOrder: 1306185

Project: Heavens Supply

 Client Sample ID:
 VMW-4:062513
 Date Sampled:
 6/25/2013

 Lab ID:
 1306185-003A
 Date Received:
 6/25/2013

Sample Type: Tedlar Bag

Analyte	Concer	Reporting Limit	Qual	Test Method	Date Analyze /Analyst		
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/26/2013	SG
Tetrachloroethene (PCE)	441	2,990	0.300		TO-15	06/26/2013	SG
Trichloroethene (TCE)	8.32	44.7	0.200		TO-15	06/26/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/26/2013	SG
Surr: 4-Bromofluorobenzene	107 %Rec		70-130		TO-15	06/26/2013	SG

E Value above quantitation range

J Analyte detected below quantitation limits

D Dilution was required

H Holding times for preparation or analysis exceeded

ND Not detected at the Reporting Limit



WorkOrder: 1306185

Project: Heavens Supply

 Client Sample ID:
 SMW-2:062513
 Date Sampled:
 6/25/2013

 Lab ID:
 1306185-004A
 Date Received:
 6/25/2013

Analyte	Concentration		Reporting Limit	Qual	Test Method	Date Analy /Analys	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	<0.793	0.200		TO-15	06/26/2013	SG
Tetrachloroethene (PCE)	169	1,150	0.300		TO-15	06/26/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/26/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/26/2013	SG
Surr: 4-Bromofluorobenzene	98.3 %Rec		70-130		TO-15	06/26/2013	SG

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306185

Project: Heavens Supply

 Client Sample ID:
 VMW-1:062513
 Date Sampled:
 6/25/2013

 Lab ID:
 1306185-005A
 Date Received:
 6/25/2013

Analyte	Concentration		Reporting Limit	Qual	tual Test Method	Date Analyze /Analyst	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/26/2013	SG
Tetrachloroethene (PCE)	14.2	96.6	0.300		TO-15	06/26/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/26/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/26/2013	SG
Surr: 4-Bromofluorobenzene	104 %Rec		70-130		TO-15	06/26/2013	SG

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306185

Project: Heavens Supply

 Client Sample ID:
 SMW-4:062513
 Date Sampled:
 6/25/2013

 Lab ID:
 1306185-006A
 Date Received:
 6/25/2013

Analyte	Concentration		Reporting Limit	Qual	Test Method		
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/26/2013	SG
Tetrachloroethene (PCE)	51.0	346	0.300		TO-15	06/26/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/26/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/26/2013	SG
Surr: 4-Bromofluorobenzene	99.7 %Rec		70-130		TO-15	06/26/2013	SG

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306185

Project: Heavens Supply

 Client Sample ID:
 SMW-3:062513
 Date Sampled:
 6/25/2013

 Lab ID:
 1306185-007A
 Date Received:
 6/25/2013

Analyte	Concer	Reporting Limit	Qual	Test Method			
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/26/2013	SG
Tetrachloroethene (PCE)	169	1,150	0.300		TO-15	06/26/2013	SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/26/2013	SG
Vinyl chloride	<0.200	<0.511	0.200		TO-15	06/26/2013	SG
Surr: 4-Bromofluorobenzene	102 %Rec		70-130		TO-15	06/26/2013	SG

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit



WorkOrder: 1306185

Project: Heavens Supply

 Client Sample ID:
 VP-1:062513
 Date Sampled:
 6/25/2013

 Lab ID:
 1306185-008A
 Date Received:
 6/25/2013

Analyte	Concer	Concentration			Test Method	Date Analyzed /Analyst	
	(ppbv)	(ug/m³)	(ppbv)				
Volatile Organic Compounds b	y EPA Method TO-15						
cis-1,2-Dichloroethene	<0.200	< 0.793	0.200		TO-15	06/26/2013	SG
Tetrachloroethene (PCE)	< 0.300	<2.03	0.300		TO-15	06/26/2013	
							SG
Trichloroethene (TCE)	<0.200	<1.07	0.200		TO-15	06/26/2013	SG SG
Trichloroethene (TCE) Vinyl chloride	<0.200 <0.200	<1.07 <0.511	0.200 0.200		TO-15 TO-15	06/26/2013 06/26/2013	

- E Value above quantitation range
- J Analyte detected below quantitation limits
- D Dilution was required
- H Holding times for preparation or analysis exceeded
- ND Not detected at the Reporting Limit

Date: 6/27/2013



Work Order: 1306185

QC SUMMARY REPORT

CLIENT: Landau Associates

Volatile Organic Compounds by EPA Method TO-15

Project: Heavens Supply							Volatile	Organic	Compound	us by EFA	wethou	10-1
Sample ID: 1306185-008AREP SampType: REP					Units: ppbv		Prep Dat	e: 6/26/2 0	13	RunNo: 904	11	
Client ID: VP-1:062513	Batch ID:	R9041					Analysis Dat	e: 6/26/20	13	SeqNo: 181	852	
Analyte		Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Vinyl chloride		ND	0.200						0	0	30	
cis-1,2-Dichloroethene		ND	0.200						0	0	30	
Trichloroethene (TCE)		ND	0.200						0	0	30	
Tetrachloroethene (PCE)		ND	0.300						0	0	30	
Surr: 4-Bromofluorobenzene		81.0		80.00		101	70	130		0		
Sample ID: LCS-R9041	SampType	e: LCS			Units: ppbv		Prep Dat	e: 6/26/20	13	RunNo: 904	l1	
Client ID: LCSW	Batch ID:	R9041					Analysis Dat	e: 6/26/2 0	13	SeqNo: 181	853	
Analyte		Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Vinyl chloride		7.11	0.200	10.00	0	71.1	70	130				
cis-1,2-Dichloroethene		10.4	0.200	10.00	0	104	70	130				
Trichloroethene (TCE)		9.96	0.200	10.00	0	99.6	70	130				
Tetrachloroethene (PCE)		8.41	0.300	10.00	0	84.1	70	130				
Surr: 4-Bromofluorobenzene		10.9		10.00		109	70	130				
Sample ID: LCS-R9041	SampType	e: LCS			Units: ppbv		Prep Dat	e: 6/26/20	13	RunNo: 904		
Client ID: LCSW	Batch ID:	R9041					Analysis Dat	e: 6/26/20	13	SeqNo: 181	854	
Analyte		Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual
Vinyl chloride		3.92	0.200	5.000	0	78.4	70	130				
cis-1,2-Dichloroethene		5.27	0.200	5.000	0	105	70	130				
Trichloroethene (TCE)		5.25	0.200	5.000	0	105	70	130				
Tetrachloroethene (PCE)		4.76	0.300	5.000	0	95.2	70	130				
Surr: 4-Bromofluorobenzene		9.98		10.00		99.8	70	130				

Qualifiers: B Analyte detected in the associated Method Blank

H Holding times for preparation or analysis exceeded

R RPD outside accepted recovery limits

D Dilution was required


J Analyte detected below quantitation limits

RL Reporting Limit

E Value above quantitation range

ND Not detected at the Reporting Limit

S Spike recovery outside accepted recovery limits





Work Order: 1306185

Project:

QC SUMMARY REPORT

CLIENT: Landau Associates

Heavens Supply

Volatile Organic Compounds by EPA Method TO-15

Sample ID: MB-R9041	SampType: MBLK	ampType: MBLK		Units: ppbv			Prep Date: 6/26/2013			RunNo: 9041		
Client ID: MBLKW	Batch ID: R9041				Analysis Date: 6/26/2013			SeqNo: 181855				
Analyte	Result	RL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual	
Vinyl chloride	ND	0.200										
cis-1,2-Dichloroethene	ND	0.200										
Trichloroethene (TCE)	ND	0.200										
Tetrachloroethene (PCE)	ND	0.300										
Surr: 4-Bromofluorobenzene	9.49		10.00		94.9	70	130					

R RPD outside accepted recovery limits

RL Reporting Limit

S Spike recovery outside accepted recovery limits

Holding times for preparation or analysis exceeded

D Dilution was required

Analyte detected below quantitation limits

E Value above quantitation range

ND Not detected at the Reporting Limit



Sample Log-In Check List

	t Name: LA ed by: Clare Griggs	Work Order Number: Date Received:	1306185 6/25/2013 6:	:06:00 PM	
<u>Cha</u>	nin of Custody				
1.	Were custodial seals present?	Yes	No \square	Not Required 🗹	
2.	Is Chain of Custody complete?	Yes 🗸	No \square	Not Present	
3.	How was the sample delivered?	Client			
Log	<u>ı İn</u>				
4.	Coolers are present?	Yes	No 🗸	na 🗆	
		Air Samples			
5.	Was an attempt made to cool the samples?	Yes	No 🗌	NA 🗹	
6.	Were all coolers received at a temperature of >0° C to 10.0°C	Yes	No 🗌	NA 🗹	
7.	Sample(s) in proper container(s)?	Yes 🗸	No 🗌		
8.	Sufficient sample volume for indicated test(s)?	Yes 🗸	No \square		
9.	Are samples properly preserved?	Yes 🗸	No \square		
10.	Was preservative added to bottles?	Yes	No 🗹	NA 🗆	
11.	Is there headspace present in VOA vials?	Yes	No 🗆	NA 🗹	
12.	Did all sample containers arrive in good condition?(unbroken)	Yes 🗸	No 🗆		
	Does paperwork match bottle labels?	Yes 🗸	No \square		
14.	Are matrices correctly identified on Chain of Custody?	Yes 🔽	No 🗌		
15.	Is it clear what analyses were requested?	Yes 🗹	No \square		
16.	Were all holding times able to be met?	Yes 🗸	No 🗌		
Spe	ecial Handling (if applicable)				
17.	Was client notified of all discrepancies with this order?	Yes	No \square	NA 🗹	
10	Person Notified: By Whom: Regarding: Client Instructions: Additional remarks/Disrepancies	•	ne Fax	In Person	

Additional remarks/Disrepancies

Item Information

Seattle/Edmonds (425) 778-0907

☐ Tacoma (253) 926-2493

☐ Spokane (509) 327-9737

4	alba yang	mo	OE.	210
1	Portland	(503)	542-1	1080



Date 6-25-13

Chain-of-Custody Record

Project Name Heaven's Project Location/Event See		_ Projec	tNo585	007.0 9	0.056	and a second	Testing	Parameters	Standard XAccelerated		
Sampler's Name Daten Br	ondt & St	eve sha	w		_	P) / /	111	1111	1 Z Day		
Project Contact Poer Ro	elen				- /	0////	1///	111	11		
Send Results To Paper Recie Sample I.D.	n, Anne Haluns Date	rime	Matrix	No. of Containe	-/3	111	1//	1111	Observations/Commen;s		
VMU-Z-062513	6-25-13	821	Air	1	×			411 2 11 1	X Allow water samples to settle, collect		
VMW- 3: 062513		833	1	1	×			11111111111	aliquot from clear portion		
VMW-4:062513		859		1	×				X_NWTPH-Ex - run acid wash/silica gel cleanup		
SMW-2:062513		937		1	×						
VMW-1-062513		1011		1	×				run samples standardized to		
SMW- 4: 062513		1100		i	X				product		
SMW-3.062513		1115		1	X			7-14-1	Analyze for EPH if no specific		
VP-1:062513		1750	4		^				product identified VOC/BTEX/VPH (sol):mon-preservedpreserved w/methanolpreserved w/sodium bisulfateFreeze upon receiptDissolved metal_water samples field filtered Other		
Special Shpment/Handling or Storage Requirements								Method Shipme	and Drop off		
Re linquished by		Received I	yu-			Relinquishe Signature	d by		Received by		
Proted Name Lawry ASSISTANCE	1	tto	Anale	ticel	Printed Name			Printed Name			
Company Date 6/27/17 Time	100000			Time L	5:06	Company Date	Firm	10	Company Date Time		

Laboratory Analytical Reports – Groundwater



July 1, 2013

Mr. Piper Roelen Landau Associates, Inc. 130 - 2nd Ave. S. Edmonds, WA 98020

Dear Mr. Roelen,

On June 19th, 5 samples were received by our laboratory and assigned our laboratory project number EV13060095. The project was identified as your Heavens Supply / #583002.050.056. The sample identification and requested analyses are outlined on the attached chain of custody record.

No abnormalities or nonconformances were observed during the analyses of the project samples.

Please do not hesitate to call me if you have any questions or if I can be of further assistance.

Sincerely,

ALS Laboratory Group

Rick Bagan

Laboratory Director



CERTIFICATE OF ANALYSIS

CLIENT: Landau Associates, Inc. DATE:

130 - 2nd Ave. S. ALS JOB#: EV13060095

7/1/2013

Edmonds, WA 98020 ALS SAMPLE#: -01

CLIENT CONTACT: Piper Roelen DATE RECEIVED: 6/19/2013

CLIENT PROJECT: Heavens Supply / #583002.050.056 COLLECTION DATE: 6/18/2013 3:25:00 PM

CLIENT SAMPLE ID MW-2:061813 WDOE ACCREDITATION: C601

DATA RESULTS

ANALYTE	METHOD	RESULTS	REPORTING LIMITS	DILUTION FACTOR	UNITS	ANALYSIS A	ANALYSIS BY	
Dichlorodifluoromethane	EPA-8260	U	2.0	3	UG/L	06/24/2013	GAP	
Chloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Vinyl Chloride	EPA-8260	U	0.20	1	UG/L	06/24/2013	GAP	
Bromomethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Chloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Carbon Tetrachloride	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Trichlorofluoromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Carbon Disulfide	EPA-8260	U	2.0	71	UG/L	06/24/2013	GAP	
Acetone	EPA-8260	U	25	1	UG/L	06/24/2013	GAP	
1,1-Dichloroethene	EPA-8260	U	2.0	71	UG/L	06/24/2013	GAP	
Methylene Chloride	EPA-8260	U	5.0	1	UG/L	06/24/2013	GAP	
Acrylonitrile	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
Methyl T-Butyl Ether	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Trans-1,2-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
2-Butanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
Cis-1,2-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
2,2-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Bromochloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Chloroform	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1,1-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,2-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Trichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,2-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Dibromomethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Bromodichloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Trans-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
4-Methyl-2-Pentanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
Toluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Cis-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1,2-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
2-Hexanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
1,3-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Tetrachloroethylene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Dibromochloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,2-Dibromoethane	EPA-8260	U	0.010	1	UG/L	06/24/2013	GAP	

Page 2

ADDRESS 8620 Holly Drive, Suite 100, Everett, WA 98208 PHONE 425-356-2600 FAX 425-356-2626

ALS Laboratory Group A Campbell Brothers Limited Company





CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S. ALS JOB#: EV13060095

Edmonds, WA 98020 ALS SAMPLE#: -01

CLIENT CONTACT: Piper Roelen DATE RECEIVED: 6/19/2013

		DA	TA RESULTS				
ANALYTE	METHOD	RESULTS	REPORTING LIMITS	DILUTION FACTOR	UNITS	ANALYSIS A	NALYSIS BY
Chlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,1,2-Tetrachloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Ethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
m,p-Xylene	EPA-8260	U	4.0	1	UG/L	06/24/2013	GAP
Styrene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
o-Xylene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromoform	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Isopropylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,2,2-Tetrachloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,3-Trichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
N-Propyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2-Chlorotoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,3,5-Trimethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
4-Chlorotoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
T-Butyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,4-Trimethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
S-Butyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
P-Isopropyltoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,3 Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,4-Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
N-Butylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dibromo 3-Chloropropane	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
1,2,4-Trichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Hexachlorobutadiene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Naphthalene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,3-Trichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
	16.0.1					ANALYSIS A	
SURROGATE	METHOD	%REC				DATE	BY
1,2-Dichloroethane-d4	EPA-8260	102				06/24/2013	GAP
Toluene-d8	EPA-8260	95.7				06/24/2013	GAP
4-Bromofluorobenzene	EPA-8260	102				06/24/2013	GAP

U - Analyte analyzed for but not detected at level above reporting limit.



CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S. ALS JOB#: EV13060095

Edmonds, WA 98020 ALS SAMPLE#: -02

CLIENT CONTACT: Piper Roelen DATE RECEIVED: 6/19/2013

DATA RESULTS

	WET IND	DEOUG TO	REPORTING LIMITS	DILUTION	LINUTO	ANALYSIS A	ANALYSIS BY
ANALYTE Dichlorodifluoromethane	METHOD EPA-8260	RESULTS U	2.0	1	UNITS UG/L	06/24/2013	GAP
Chloromethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Vinyl Chloride	EPA-8260	Ü	0.20	1	UG/L	06/24/2013	GAP
Bromomethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Chloroethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Carbon Tetrachloride	EPA-8260	Ü	2.0	9	UG/L	06/24/2013	GAP
Trichlorofluoromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Carbon Disulfide	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Acetone	EPA-8260	Ü	25	1	UG/L	06/24/2013	GAP
1,1-Dichloroethene	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Methylene Chloride	EPA-8260	Ü	5.0	1	UG/L	06/24/2013	GAP
Acrylonitrile	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
Methyl T-Butyl Ether	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Trans-1,2-Dichloroethene	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
1,1-Dichloroethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
2-Butanone	EPA-8260	Ü	10	1	UG/L	06/24/2013	GAP
Cis-1,2-Dichloroethene	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
2,2-Dichloropropane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Bromochloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Chloroform	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,1-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Trichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Dibromomethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromodichloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Trans-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
4-Methyl-2-Pentanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
Toluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Cis-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,2-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2-Hexanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
1,3-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Tetrachloroethylene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Dibromochloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dibromoethane	EPA-8260	U	0.010	1	UG/L	06/24/2013	GAP

Page 4

ADDRESS 8620 Holly Drive, Suite 100, Everett, WA 98208 PHONE 425-356-2600 FAX 425-356-2626





CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S. ALS JOB#: EV13060095

Edmonds, WA 98020 ALS SAMPLE#: -02

CLIENT CONTACT: Piper Roelen DATE RECEIVED: 6/19/2013

		DA	TA RESULTS				
ANALYTE	METHOD	RESULTS	REPORTING LIMITS	DILUTION FACTOR	UNITS	ANALYSIS A	NALYSIS BY
Chlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,1,2-Tetrachloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Ethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
m,p-Xylene	EPA-8260	U	4.0	1	UG/L	06/24/2013	GAP
Styrene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
o-Xylene	EPA-8260	U	2.0	9	UG/L	06/24/2013	GAP
Bromoform	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Isopropylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,2,2-Tetrachloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,3-Trichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
N-Propyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2-Chlorotoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,3,5-Trimethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
4-Chlorotoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
T-Butyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,4-Trimethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
S-Butyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
P-Isopropyltoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,3 Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,4-Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
N-Butylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dibromo 3-Chloropropane	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
1,2,4-Trichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Hexachlorobutadiene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Naphthalene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,3-Trichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
						ANALYSIS A	NALYSIS
SURROGATE	METHOD	%REC				DATE	BY
1,2-Dichloroethane-d4	EPA-8260	102				06/24/2013	GAP
Toluene-d8	EPA-8260	95.5				06/24/2013	GAP
4-Bromofluorobenzene	EPA-8260	102				06/24/2013	GAP

U - Analyte analyzed for but not detected at level above reporting limit.



CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S. ALS JOB#: EV13060095

Edmonds, WA 98020 ALS SAMPLE#: -03

CLIENT CONTACT: Piper Roelen DATE RECEIVED: 6/19/2013

CLIENT PROJECT: Heavens Supply / #583002.050.056 COLLECTION DATE: 6/18/2013 4:00:00 PM

CLIENT SAMPLE ID MW-4:061813 WDOE ACCREDITATION: C601

DA	IA	HE	SU	L	S

		DECUMEN	REPORTING LIMITS	DILUTION	LINUTO	ANALYSIS A	ANALYSIS BY
ANALYTE Dichlorodifluoromethane	METHOD EPA-8260	RESULTS U	2.0	1	UNITS UG/L	06/24/2013	GAP
Chloromethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Vinyl Chloride	EPA-8260	Ü	0.20	1	UG/L	06/24/2013	GAP
Bromomethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Chloroethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Carbon Tetrachloride	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Trichlorofluoromethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Carbon Disulfide	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Acetone	EPA-8260	Ü	25	1	UG/L	06/24/2013	GAP
1,1-Dichloroethene	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Methylene Chloride	EPA-8260	Ü	5.0	1	UG/L	06/24/2013	GAP
Acrylonitrile	EPA-8260	Ü	10	1	UG/L	06/24/2013	GAP
Methyl T-Butyl Ether	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Trans-1,2-Dichloroethene	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
1,1-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2-Butanone	EPA-8260	Ü	10	1	UG/L	06/24/2013	GAP
Cis-1,2-Dichloroethene	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
2,2-Dichloropropane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Bromochloromethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Chloroform	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
1,1,1-Trichloroethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
1,1-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Trichloroethene	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Dibromomethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromodichloromethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP
Trans-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
4-Methyl-2-Pentanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
Toluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Cis-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,2-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2-Hexanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
1,3-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Tetrachloroethylene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Dibromochloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dibromoethane	EPA-8260	U	0.010	1	UG/L	06/24/2013	GAP

Page 6

ADDRESS 8620 Holly Drive, Suite 100, Everett, WA 98208 PHONE 425-356-2600 FAX 425-356-2626





CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S. ALS JOB#: EV13060095

Edmonds, WA 98020 ALS SAMPLE#: -03

DATA RESULTS

CLIENT CONTACT: Piper Roelen DATE RECEIVED: 6/19/2013

REPORTING DILUTION ANALYSIS ANALYSIS LIMITS **FACTOR** DATE BY ANALYTE RESULTS UNITS METHOD 2.0 06/24/2013 GAP Chlorobenzene EPA-8260 U 1 UG/L 1,1,1,2-Tetrachloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Ethylbenzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP m,p-Xylene EPA-8260 U 4.0 1 UG/L 06/24/2013 GAP Styrene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP o-Xylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP U Bromoform EPA-8260 2.0 1 UG/L 06/24/2013 GAP Isopropylbenzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,2,2-Tetrachloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP U 2.0 1 UG/L 06/24/2013 GAP 1,2,3-Trichloropropane EPA-8260 U 2.0 UG/L 06/24/2013 GAP Bromobenzene EPA-8260 1 U UG/L N-Propyl Benzene EPA-8260 2.0 1 06/24/2013 GAP U 2-Chlorotoluene EPA-8260 2.0 1 UG/L 06/24/2013 GAP 1,3,5-Trimethylbenzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 4-Chlorotoluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP U T-Butyl Benzene EPA-8260 2.0 1 UG/L 06/24/2013 GAP EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2,4-Trimethylbenzene S-Butyl Benzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP P-Isopropyltoluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,3 Dichlorobenzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,4-Dichlorobenzene U 2.0 1 UG/L 06/24/2013 GAP EPA-8260 N-Butylbenzene U 2.0 UG/L 06/24/2013 GAP EPA-8260 1 UG/L U 2.0 06/24/2013 1,2-Dichlorobenzene EPA-8260 1 GAP

			ANALYSIS AN	NALYSIS
SURROGATE	METHOD	%REC	DATE	BY
1,2-Dichloroethane-d4	EPA-8260	102	06/24/2013	GAP
Toluene-d8	EPA-8260	95.6	06/24/2013	GAP
4-Bromofluorobenzene	EPA-8260	102	06/24/2013	GAP

10

2.0

2.0

2.0

2.0

1

1

1

1

1

EPA-8260

EPA-8260

EPA-8260

EPA-8260

EPA-8260

U

U

U

U

U

UG/L

UG/L

UG/L

UG/L

UG/L

06/24/2013

06/24/2013

06/24/2013

06/24/2013

06/24/2013

GAP

GAP

GAP

GAP

GAP

1,2-Dibromo 3-Chloropropane

1,2,4-Trichlorobenzene

1,2,3-Trichlorobenzene

Hexachlorobutadiene

Naphthalene

U - Analyte analyzed for but not detected at level above reporting limit.



CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S. ALS JOB#: EV13060095

Edmonds, WA 98020 ALS SAMPLE#: -04

CLIENT CONTACT: Piper Roelen DATE RECEIVED: 6/19/2013

CLIENT PROJECT: Heavens Supply / #583002.050.056 COLLECTION DATE: 6/18/2013 3:43:00 PM

CLIENT SAMPLE ID MW-5:061813 WDOE ACCREDITATION: C601

		DA	TA RESULTS					
ANALYTE	METHOD	RESULTS	REPORTING LIMITS	DILUTION	UNITS	ANALYSIS A	ANALYSIS BY	
Dichlorodifluoromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Chloromethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP	
Vinyl Chloride	EPA-8260	Ü	0.20	a i	UG/L	06/24/2013	GAP	
Bromomethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP	
Chloroethane	EPA-8260	Ü	2.0	a l	UG/L	06/24/2013	GAP	
Carbon Tetrachloride	EPA-8260	U	2.0	i	UG/L	06/24/2013	GAP	
Trichlorofluoromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Carbon Disulfide	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Acetone	EPA-8260	U	25	1	UG/L	06/24/2013	GAP	
1,1-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Methylene Chloride	EPA-8260	U	5.0	1	UG/L	06/24/2013	GAP	
Acrylonitrile	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
Methyl T-Butyl Ether	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Trans-1,2-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
2-Butanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
Cis-1,2-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
2,2-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Bromochloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Chloroform	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1,1-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,2-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Trichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,2-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Dibromomethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Bromodichloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Trans-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
4-Methyl-2-Pentanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
Toluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Cis-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1,2-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
2-Hexanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
1,3-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Tetrachloroethylene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Dibromochloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,2-Dibromoethane	EPA-8260	U	0.010	1	UG/L	06/24/2013	GAP	

Page 8

ADDRESS 8620 Holly Drive, Suite 100, Everett, WA 98208 PHONE 425-356-2600 FAX 425-356-2626





CLIENT: Landau Associates, Inc. DATE:

7/1/2013 130 - 2nd Ave. S. ALS JOB#: EV13060095

Edmonds, WA 98020 ALS SAMPLE#: -04

CLIENT CONTACT: Piper Roelen DATE RECEIVED: 6/19/2013

CLIENT PROJECT: Heavens Supply / #583002.050.056 COLLECTION DATE: 6/18/2013 3:43:00 PM

CLIENT SAMPLE ID MW-5:061813 WDOE ACCREDITATION: C601

		DA	TA RESULTS				
ANALYTE	METHOD	RESULTS	REPORTING LIMITS	DILUTION FACTOR	UNITS	ANALYSIS A	NALYSIS BY
Chlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,1,2-Tetrachloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Ethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
m,p-Xylene	EPA-8260	U	4.0	1	UG/L	06/24/2013	GAP
Styrene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
o-Xylene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromoform	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Isopropylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,2,2-Tetrachloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,3-Trichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
N-Propyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2-Chlorotoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,3,5-Trimethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
4-Chlorotoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
T-Butyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,4-Trimethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
S-Butyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
P-Isopropyltoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,3 Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,4-Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
N-Butylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dibromo 3-Chloropropane	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
1,2,4-Trichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Hexachlorobutadiene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Naphthalene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,3-Trichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
						ANALYSIS A	
SURROGATE	METHOD	%REC				DATE	BY
1,2-Dichloroethane-d4	EPA-8260	102				06/24/2013	GAP
Toluene-d8	EPA-8260	95.4				06/24/2013	GAP
4-Bromofluorobenzene	EPA-8260	101				06/24/2013	GAP

U - Analyte analyzed for but not detected at level above reporting limit.



CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S. ALS JOB#: EV13060095

Edmonds, WA 98020 ALS SAMPLE#: -05

CLIENT CONTACT: Piper Roelen DATE RECEIVED: 6/19/2013

CLIENT SAMPLE ID TRIP BLANK WDOE ACCREDITATION: C601

		DA	TA RESULTS					
ANALYTE	METHOD	RESULTS	REPORTING LIMITS	DILUTION	UNITS	ANALYSIS A	ANALYSIS BY	
Dichlorodifluoromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Chloromethane	EPA-8260	Ü	2.0	41	UG/L	06/24/2013	GAP	
Vinyl Chloride	EPA-8260	Ü	0.20	à	UG/L	06/24/2013	GAP	
Bromomethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP	
Chloroethane	EPA-8260	Ü	2.0	1	UG/L	06/24/2013	GAP	
Carbon Tetrachloride	EPA-8260	U	2.0	i	UG/L	06/24/2013	GAP	
Trichlorofluoromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Carbon Disulfide	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Acetone	EPA-8260	U	25	1	UG/L	06/24/2013	GAP	
1,1-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Methylene Chloride	EPA-8260	U	5.0	1	UG/L	06/24/2013	GAP	
Acrylonitrile	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
Methyl T-Butyl Ether	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Trans-1,2-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
2-Butanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
Cis-1,2-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
2,2-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Bromochloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Chloroform	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1,1-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,2-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Trichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,2-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Dibromomethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Bromodichloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Trans-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
4-Methyl-2-Pentanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
Toluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Cis-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,1,2-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
2-Hexanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP	
1,3-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Tetrachloroethylene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
Dibromochloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP	
1,2-Dibromoethane	EPA-8260	U	0.010	1	UG/L	06/24/2013	GAP	

Page 10

ADDRESS 8620 Holly Drive, Suite 100, Everett, WA 98208 PHONE 425-356-2600 FAX 425-356-2626





CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S. ALS JOB#: EV13060095

Edmonds, WA 98020 ALS SAMPLE#: -05

CLIENT CONTACT: Piper Roelen DATE RECEIVED: 6/19/2013 CLIENT PROJECT: COLLECTION DATE: 6/18/2013 8:00:00 AM

Heavens Supply / #583002.050.056 CLIENT SAMPLE ID TRIP BLANK WDOE ACCREDITATION: C601

		DA	TA RESULTS				
ANALYTE	METHOD	RESULTS	REPORTING LIMITS	DILUTION FACTOR	UNITS	ANALYSIS A	NALYSIS BY
Chlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,1,2-Tetrachloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Ethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
m,p-Xylene	EPA-8260	U	4.0	1	UG/L	06/24/2013	GAP
Styrene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
o-Xylene	EPA-8260	U	2.0	9	UG/L	06/24/2013	GAP
Bromoform	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
sopropylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,2,2-Tetrachloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,3-Trichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
N-Propyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2-Chlorotoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
,3,5-Trimethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1-Chlorotoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Γ-Butyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,4-Trimethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
S-Butyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
P-Isopropyltoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,3 Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
,4-Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
N-Butylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dibromo 3-Chloropropane	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
1,2,4-Trichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Hexachlorobutadiene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Naphthalene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,3-Trichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
						ANALYSIS A	NALYSIS
SURROGATE	METHOD	%REC				DATE	BY
1,2-Dichloroethane-d4	EPA-8260	103				06/24/2013	GAP
Foluene-d8	EPA-8260	94.7				06/24/2013	GAP
4-Bromofluorobenzene	EPA-8260	102				06/24/2013	GAP

U - Analyte analyzed for but not detected at level above reporting limit.



CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S. ALS SDG#: EV13060095

Edmonds, WA 98020 WDOE ACCREDITATION: C601

CLIENT CONTACT: Piper Roelen

CLIENT PROJECT: Heavens Supply / #583002.050.056

LABORATORY BLANK RESULTS

MB-062413W - Batch 3854 - Water by EPA-8260

Dichlorodifluromethane		,		REPORTING	DILUTION		ANALYSIS A	ANALYSIS
Chloromethane	ANALYTE	METHOD	RESULTS	LIMITS	FACTOR	UNITS	DATE	BY
Vinyl Chloride	Dichlorodifluoromethane	EPA-8260		2.0	1	UG/L	06/24/2013	GAP
Bromomethane	Chloromethane	EPA-8260	U		1		06/24/2013	
Chloroethane	Vinyl Chloride	EPA-8260	U	0.20	1	UG/L	06/24/2013	GAP
Carbon Tetrachloride EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trichlorofluoromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Carbon Disulfide EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Acetone EPA-8260 U 2.5 1 UG/L 06/24/2013 GAP Methylene Chloride EPA-8260 U 5.0 1 UG/L 06/24/2013 GAP Acrylonitrile EPA-8260 U 5.0 1 UG/L 06/24/2013 GAP Methyl T-Butyl Ether EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2,2-Dichloroethene EPA-8260 U 2.0 1 UG/L	Bromomethane	EPA-8260	U	2.0	1	UG/L		GAP
Trichlorofluoromethane	Chloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Carbon Disulfide EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Acetone EPA-8260 U 25 1 UG/L 06/24/2013 GAP I.1-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Methylene Chloride EPA-8260 U 5.0 1 UG/L 06/24/2013 GAP Acrylonitrile EPA-8260 U 1.0 1 UG/L 06/24/2013 GAP Methyl T-Butyl Ether EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,2-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2,2-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Clis-1,2-Dichloroethane EPA-8260 U 2.0 1 UG/L	Carbon Tetrachloride	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Acetone	Trichlorofluoromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1-Dichloroethene	Carbon Disulfide	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Methylene Chloride EPA-8260 U 5.0 1 UG/L 06/24/2013 GAP Acrylonitrile EPA-8260 U 10 1 UG/L 06/24/2013 GAP Methyl T-Butyl Ether EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Butanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 2-2-Dichloroptropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Chloroform EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,1-Trichloroethane EPA-8260 U 2.0 1 UG/L <	Acetone	EPA-8260	U	25	1	UG/L	06/24/2013	GAP
Acrylonitrile EPA-8260 U 10 1 UG/L 06/24/2013 GAP Methyl T-Butyl Ether EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,2-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Butanone EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Chioroform EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L	1,1-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Methyl T-Butyl Ether EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,2-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Butanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP Cis-1,2-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,1-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trichloroethane EPA-8260 U 2.0 1	Methylene Chloride	EPA-8260	U	5.0	1	UG/L	06/24/2013	GAP
Trans-1,2-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Butanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 2-Butanone EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Chloroform EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloroptopene EPA-8260 U 2.0 1 UG/L <t< td=""><td>Acrylonitrile</td><td>EPA-8260</td><td>U</td><td>10</td><td>1</td><td>UG/L</td><td>06/24/2013</td><td>GAP</td></t<>	Acrylonitrile	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
1,1-Dichloroethane	Methyl T-Butyl Ether	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2-Butanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP Cis-1,2-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Chloroform EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,1-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Benzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L <td< td=""><td>Trans-1,2-Dichloroethene</td><td>EPA-8260</td><td>U</td><td>2.0</td><td>1</td><td>UG/L</td><td>06/24/2013</td><td>GAP</td></td<>	Trans-1,2-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Cis-1,2-Dichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Chloroform EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,1-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Benzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromomethane EPA-8260 U 2.0 1 UG/L <t< td=""><td>1,1-Dichloroethane</td><td>EPA-8260</td><td>U</td><td>2.0</td><td>1</td><td>UG/L</td><td>06/24/2013</td><td>GAP</td></t<>	1,1-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2,2-Dichloropropane	2-Butanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
Bromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Chloroform EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,1-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloroptopene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Benzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromomethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L <	Cis-1,2-Dichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Chloroform EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,1-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Benzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromodichloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L	2,2-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,1-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Benzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromomethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromodichloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Toluene EPA-8260 U 2.0 1 UG/L	Bromochloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Benzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromomethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromodichloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Toluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L	Chloroform	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichloroethane	1,1,1-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Benzene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromomethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromodichloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromodichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 4-Methyl-2-Pentanone EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Toluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L	1,1-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Trichloroethene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromomethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromodichloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 4-Methyl-2-Pentanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP Toluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,2-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Hexanone EPA-8260 U 10 1 UG/L	1,2-Dichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromomethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromodichloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 4-Methyl-2-Pentanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP Toluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,2-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Hexanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 1,3-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Tetrachloroethylene EPA-8260 U	Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Dibromomethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Bromodichloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 4-Methyl-2-Pentanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP Toluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,2-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Hexanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 1,3-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Tetrachloroethylene EPA-8260 U 2.0 1 UG/L <td>Trichloroethene</td> <td>EPA-8260</td> <td>U</td> <td>2.0</td> <td>1</td> <td>UG/L</td> <td>06/24/2013</td> <td>GAP</td>	Trichloroethene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromodichloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Trans-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 4-Methyl-2-Pentanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP Toluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,2-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Hexanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 1,3-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Tetrachloroethylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromochloromethane EPA-8260 U 2.0 1 U	1,2-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Trans-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 4-Methyl-2-Pentanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP Toluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,2-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Hexanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 1,3-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Tetrachloroethylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP	Dibromomethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
4-Methyl-2-Pentanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP Toluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,2-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Hexanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 1,3-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Tetrachloroethylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP	Bromodichloromethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Toluene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Cis-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,2-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Hexanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 1,3-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Tetrachloroethylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP	Trans-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Cis-1,3-Dichloropropene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 1,1,2-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Hexanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 1,3-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Tetrachloroethylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP	4-Methyl-2-Pentanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
1,1,2-Trichloroethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP 2-Hexanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 1,3-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Tetrachloroethylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP	Toluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2-Hexanone EPA-8260 U 10 1 UG/L 06/24/2013 GAP 1,3-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Tetrachloroethylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP	Cis-1,3-Dichloropropene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,3-Dichloropropane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Tetrachloroethylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP	1,1,2-Trichloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Tetrachloroethylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP	2-Hexanone	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
Tetrachloroethylene EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP Dibromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP	1,3-Dichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Dibromochloromethane EPA-8260 U 2.0 1 UG/L 06/24/2013 GAP		EPA-8260		2.0	1	UG/L	06/24/2013	GAP
	•	EPA-8260	U		1	UG/L	06/24/2013	GAP
1,2 2,3,13,13,13,13	1,2-Dibromoethane	EPA-8260	U	0.010	1	UG/L	06/24/2013	GAP



CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S. ALS SDG#: EV13060095

Edmonds, WA 98020 WDOE ACCREDITATION: C601

CLIENT CONTACT: Piper Roelen

CLIENT PROJECT: Heavens Supply / #583002.050.056

LABORATORY BLANK RESULTS

MB-062413W - Batch 3854 - W	ater by EPA-826	0					
Chlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,1,2-Tetrachloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Ethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
m,p-Xylene	EPA-8260	U	4.0	1	UG/L	06/24/2013	GAP
Styrene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
o-Xylene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromoform	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Isopropylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,1,2,2-Tetrachloroethane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,3-Trichloropropane	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Bromobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
N-Propyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
2-Chlorotoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,3,5-Trimethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
4-Chlorotoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
T-Butyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,4-Trimethylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
S-Butyl Benzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
P-Isopropyltoluene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,3 Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,4-Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
N-Butylbenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2-Dibromo 3-Chloropropane	EPA-8260	U	10	1	UG/L	06/24/2013	GAP
1,2,4-Trichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Hexachlorobutadiene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
Naphthalene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP
1,2,3-Trichlorobenzene	EPA-8260	U	2.0	1	UG/L	06/24/2013	GAP



CLIENT: Landau Associates, Inc. DATE: 7/1/2013

130 - 2nd Ave. S.

ALS SDG#: EV13060095

Edmonds, WA 98020

WDOE ACCREDITATION: C601

CLIENT CONTACT:

Piper Roelen

CLIENT PROJECT: Heavens Supply / #583002.050.056

LABORATORY CONTROL SAMPLE RESULTS

ALS Test Batch ID: 3854 - Water by EPA-8260

SPIKED COMPOUND	METHOD	%REC	RPD	QUAL	ANALYSIS DATE	ANALYSIS BY	
1,1-Dichloroethene - BS	EPA-8260	95.2			06/24/2013	GAP	
1,1-Dichloroethene - BSD	EPA-8260	99.5	4		06/24/2013	GAP	
Benzene - BS	EPA-8260	100			06/24/2013	GAP	
Benzene - BSD	EPA-8260	106	6		06/24/2013	GAP	
Trichloroethene - BS	EPA-8260	100			06/24/2013	GAP	
Trichloroethene - BSD	EPA-8260	106	6		06/24/2013	GAP	
Toluene - BS	EPA-8260	94.0			06/24/2013	GAP	
Toluene - BSD	EPA-8260	99.0	5		06/24/2013	GAP	
Chlorobenzene - BS	EPA-8260	88.8			06/24/2013	GAP	
Chlorobenzene - BSD	EPA-8260	93.9	6		06/24/2013	GAP	



CLIENT: Landau Associates, Inc.

7/1/2013 DATE:

130 - 2nd Ave. S.

ALS SDG#: EV13060095

Edmonds, WA 98020

WDOE ACCREDITATION:

CLIENT CONTACT: **CLIENT PROJECT:**

Piper Roelen

Heavens Supply / #583002.050.056

C601

MATRIX SPIKE RESULTS

ALS Test Batch ID: 3854 - Water Parent Sample: BATCH QC

SPIKED COMPOUND	METHOD	%REC	RPD	QUAL	ANALYSIS DATE	ANALYSIS BY	
1,1-Dichloroethene - MS	EPA-8260	96.7			06/24/2013	GAP	
1,1-Dichloroethene - MSD	EPA-8260	99.7	3		06/24/2013	GAP	
Benzene - MS	EPA-8260	98.0			06/24/2013	GAP	
Benzene - MSD	EPA-8260	101	3		06/24/2013	GAP	
Trichloroethene - MS	EPA-8260	99.8			06/24/2013	GAP	
Trichloroethene - MSD	EPA-8260	102	2		06/24/2013	GAP	
Toluene - MS	EPA-8260	91.5			06/24/2013	GAP	
Toluene - MSD	EPA-8260	94.4	3		06/24/2013	GAP	
Chlorobenzene - MS	EPA-8260	86.4			06/24/2013	GAP	
Chlorobenzene - MSD	EPA-8260	87.8	2		06/24/2013	GAP	

APPROVED BY

Laboratory Director

ALS ENVIRONMENTAL Sample Receiving Checklist

Client: Landau Associates ALS	10b#: EV13061	1095
Project: Heavens Supply / #583002.05	50.056	12
Received Date: 6/19/13 Received Time: // 05		
Type of shipping container: Cooler X Box O	ner	770,
Shipped via: UPS/FedEx US Postal Service Cou	rier Hand Del	ivered X Ruck
Were custody seals on outside of sample? If yes, how many? 1 Where? Outside cooler Custody seal date: 6/18/13 Seal name: Landau	Yes No	<u>N/A</u>
Was Chain of Custody properly filled out (ink, signed, dated, etc.)?	<u>X</u>	
Did all bottles have labels?	<u>X</u>	
Did all bottle labels and tags agree with Chain of Custody?	X	***************************************
Were samples received within hold time?	<u>×</u>	
Did all bottles arrive in good condition (unbroken, etc.)?	<u>×</u>	
Was sufficient amount of sample sent for the tests indicated?	<u>×</u>	
Was correct preservation added to samples?	<u>×</u>	
If no, Sample Control added preservative to the following: Sample Number Reagent Analyte ———————————————————————————————————		
Were VOA vials checked for absence of air bubbles? Bubbles present in sample #:	<u>×</u> _	
Temperature of cooler upon receipt: $\frac{7.8\mathring{c}}{00}$ /ce Cold	Cool Ambient N	7/A
Explain any discrepancies: <u>Received 1 set of True</u>	Blanks not 1	isted on
Was client contacted? Yes Who was called? <u>Brandf</u> By	rhom? <u>Shawn</u> Da	te: <u>6/19/13</u> 11,19a
Outcome of call: Martin Valery Will email a re	vised Coc to	Rick to

300 300 300	ANDAU As sociates
-------------	-----------------------------

Seattle/Edmonds (425) 778-0907
Tacoma (253) 926-2493

Spokane (509) 327-9737

☐ **Portland** (503) 542-1080

Date <u>6-18-13</u>

Chain-of-Custody Record

Project Name Heaven'S Supp	lγ	Prolec	No. 5830	×02.050.(>56		1.		Test	ing Para	ımete	Taracques 1870
Project Location/Event 260416	Z WA							[]	'	[[]	'	Standard Accelerated
Sampler's Name <u>Pevan Bra</u>	7		***************************************	AND THE PROPERTY OF THE PROPER		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	y /	1.	//	$\mathcal{A}\mathcal{A}$	11	
Project Contact Tiper Rock	2.40-					/N		//	//	[1	
Send Results To Tiper Roelen			M.r.L.	illar:	1	tim/			[11.	Π	
				Nto of	8	¥ /		[11		11	Observations/Comments
Sample I.D. MW-Z: 061813	Date 6-19-13	Time V525	Matrix Water	Containers	K	-	f - f		f = f		f - f	erinafianimo o assista e e ntrata manata ma
MW-3: 061813	i i	1915		3	X	***************************************				+		X Allow water samples to settle, collect aliquot from clear portion
MU-4:06 1313		1600	Volter	3	X							X NVTPH-Dx - run acid wash/silica gel cleanup
NU-5:061813	Ą	1543	WOHET	3	X							
TRIP BLANK	*******	- Alexander - Control - Co	WATER.	2.	X							run samples standardized to product
				-								Analyze for EPH if no specific product identified
												VOC/BTEX/VPH (soll); non-preserved preserved w/methanol preserved w/sodium bisulfate Freeze upon receipt
_{regente} lle authorise de la company de la c											+	Dissolved metal water samples field filtered
												Other
nganajajajanajana, jamanajanajana, jamana ana jamana jamana jamana jamana jamana jamana jamana jamana jamana j		·										4 gi.
шинан кі і і іст су также музуу үчдін ді іні құндатуы саған тана саған тана тана іні іні іні іні іні іні іні і	······································		***************************************									
annanan en elektrische en elektrone en e			, same de la compansión de									
Special Shipment/Handling or Storage Requirements					A		h				Metl Ship	hod of Courier Pickup
Belinguished by		Received I	» /)	1			Relinqu	ished	by		···-\$\$-	Received by
Algalia 2/4/	— /	Show	1 Kox	XIXIN		1	Signatur	300 p. 10. 3 11 p. 11.	<u></u>		·····	Signature
Shawn Robush Signature Devan Bran 14 Printed Name Printed Name			Printed Name					Printed Name				
Company Company			Company					Company				
Date 6-18-13 Time 17-25 Date 6/19/13 Time //:05		5 1	DateTime					DateTime				